



1407 W North Temple, Suite 310
Salt Lake City, Utah 84114

December 19, 2017

***VIA ELECTRONIC FILING
AND OVERNIGHT DELIVERY***

Utah Public Service Commission
Heber M. Wells Building, 4th Floor
160 East 300 South
Salt Lake City, UT 84114

Attention: Gary Widerburg
Commission Secretary

RE: Docket No. 17-035-01 – Application of Rocky Mountain Power to Decrease the Deferred EBA Rate through the Energy Balancing Account Mechanism – Response Testimony

Rocky Mountain Power hereby submits its response to the audit report and direct testimony of the Utah Division of Public Utilities filed on November 15, 2017. As requested by the Commission, Rocky Mountain Power is also providing seven (7) printed copies of the filing via overnight delivery.

Rocky Mountain Power respectfully requests that all formal correspondence and requests for additional information regarding this filing be addressed to the following:

By E-mail (preferred): datarequest@pacificorp.com
utahdockets@pacificorp.com
Jana.saba@pacificorp.com
yvonne.hogle@pacificorp.com

By regular mail: Data Request Response Center
PacifiCorp
825 NE Multnomah, Suite 2000
Portland, OR 97232

Informal inquiries may be directed to Jana Saba at (801) 220-2823.

Sincerely,

Joelle Steward
Vice President, Regulation

cc: Service List

REDACTED

Rocky Mountain Power

Docket No. 17-035-01

Witness: Michael G. Wilding

BEFORE THE PUBLIC SERVICE COMMISSION
OF THE STATE OF UTAH

ROCKY MOUNTAIN POWER

REDACTED

Response Testimony of Michael G. Wilding

December 2017

1 **Q. Please state your name, business address and present position with PacifiCorp,**
2 **dba Rocky Mountain Power (“the Company”).**

3 A. My name is Michael G. Wilding. My business address is 825 NE Multnomah Street,
4 Suite 600, Portland, Oregon 97232. My title is Manager, Net Power Costs.

5 **Q. Are you the same Michael G. Wilding who submitted direct testimony on behalf**
6 **of the Company in this proceeding?**

7 A. Yes.

8 **Q. What is the purpose of your response testimony?**

9 A. My testimony responds to certain issues raised by the Utah Division of Public Utilities
10 (“DPU”) in its energy balancing account (“EBA”) Audit Report and by Daymark
11 Energy Advisors (“Daymark”), on behalf of the DPU, in its Audit Report. Specifically,
12 I address the replacement power costs calculated by Daymark for the proposed
13 adjustment related to Gadsby Units 4–6 plant outages. The Company’s position is that
14 no adjustment for plant outages is warranted as the Company was prudent in its
15 operations. However, if the Commission determines that an adjustment is needed, the
16 calculation of replacement power costs for Gadsby Units 4–6 plant outages made by
17 Daymark should be corrected. In addition, I address the DPU’s request related to
18 updating certain language in Tariff Schedule 94.

19 **Q. Do any other Company witnesses also provide testimony in response to issues**
20 **raised by the DPU and Daymark?**

21 A. Yes. Company witness Mr. Dana M. Ralston provides testimony responding to the
22 proposed adjustments related to plant outages and the Joy longwall. Mr. Ralston
23 explains that the Company was prudent in its operations and management of its thermal

24 generation plants and the Joy longwall.

25 **REPLACEMENT POWER COSTS**

26 **Q. Please describe the proposed adjustment for plant outages.**

27 A. Daymark recommends removing replacement power costs from the EBA for seven
28 plant outages at Gadsby Units 4–6, which it claims were imprudent.

29 **Q. Does the Company agree the replacement power for plant outages should be**
30 **disallowed?**

31 A. No. Company witness Mr. Ralston provides detailed testimony explaining the prudence
32 of the identified plant outages.

33 **Q. Does the Company agree with Daymark’s calculation of the replacement power**
34 **cost at the Gadsby Units 4-6?**

35 A. No. To determine the cost of replacement power Daymark compared the hourly
36 California Independent System Operator’s (“CAISO”) day-ahead market (“DAM”)
37 locational marginal prices (“LMP”) to the generation costs. Generation costs are
38 estimated based on average heat rates, natural-gas prices at the Opal index market, and
39 \$2.00/megawatt-hour (“MWh”) for variable operations and maintenance (“VOM”)
40 costs. Any lost MWh was determined by dispatching the unit when generation costs
41 were less than the hourly CAISO DAM LMP. To calculate the replacement power cost,
42 Daymark multiplied lost MWh by the difference between the LMP and the marginal
43 generation cost. While the Company agrees with the calculation methodology of
44 replacement power costs, the Company does not agree with the inputs Daymark used.

45 **Q. Which inputs did Daymark use that the Company disagrees with?**

46 A. First, as Daymark itself noted, PacifiCorp does not participate in the CAISO DAM¹;
47 therefore, lost output should not be valued at a market in which the Company does not
48 participate. It would be more appropriate to replace the CAISO DAM LMP with
49 PowerDex hourly market prices at the 4-Corners market hub because PacifiCorp uses
50 this market hub for the Gadsby plant. Second, the actual VOM costs should be used
51 rather than the *estimated* VOM included by Daymark. The actual VOM costs for
52 Gadsby Units 4–6 are \$[REDACTED]/MWh, compared to Daymark’s estimated VOM costs of
53 \$[REDACTED]/MWh. Lastly, Daymark should have used actual average heat rates rather than
54 the estimated heat rate.

55 **Q. Why is the CAISO DAM LMP not the appropriate price to determine plant**
56 **dispatch?**

57 A. Again, the Company does not participate in the CAISO DAM. In other words, the
58 Company does not provide the CAISO with an accurate day-ahead schedule or day-
59 ahead resource bids; therefore, the CAISO DAM cannot be relied upon. In addition,
60 Gadsby Units 4–6 are not typically dispatched in the day-ahead but instead are
61 dispatched within the day. Therefore using an hourly price, versus a day-ahead price,
62 to determine replacement power costs is more appropriate. Table 1 below shows the
63 percentage of hours each month in which the Gadsby Units 4–6 were dispatched in the
64 day-ahead, and why it is inappropriate to use the CAISO DAM. The percentage of
65 hours in the six months the Company used the CAISO DAM is less than one percent
66 in each of those six months.

¹ Daymark Exhibit 2.3, EBA Audit Report, Page 26.

Table 1

Month (2016)	Gadsby 4	Gadsby 5	Gadsby 6
Jan	0.03%	0.03%	0.03%
Feb			
Mar			
Apr	0.03%	0.03%	0.03%
May	0.01%	0.01%	0.01%
Jun	0.02%	0.02%	0.02%
Jul			
Aug	0.15%	0.11%	0.13%
Sep			
Oct			
Nov		0.08%	
Dec	0.55%	0.55%	0.55%

68 **Q. Has the Company provided a corrected calculation of the replacement power**
69 **costs?**

70 A. Yes, workpapers containing the corrected calculation are provided with my testimony.
71 Making the corrections noted above to the replacement power costs reduces the impact
72 of the proposed adjustments to Utah-allocated net power costs from approximately
73 \$43,000 to approximately \$9,400 before application of the sharing band, where
74 applicable. However, as stated in Mr. Ralston's response testimony, the Company's
75 position is that no adjustment should be made.

76 **Q. Does the Company agree with the computation of other replacement power costs?**

77 A. The methodology Daymark used to compute non-peaker replacement power costs is
78 reasonable. However, the Company did note two instances where the first-day or last-
79 day peak and off-peak outage hours were incorrectly calculated for Hermiston Unit 1
80 and Dave Johnston Unit 4. In addition, the outage hours related to Colstrip Unit 3 were
81 not calculated correctly. The outage to repair the economizer tube leak lasted no more

82 than 84 hours and the remainder of the 209 hours of this outage related to a boiler water
 83 pump issue. These were separate instances and the computation of replacement power
 84 should have only covered the period related to the economizer tube leak, which was
 85 84 hours. Table 2 below shows the corrected replacement power costs for all contested
 86 outages on a total Company basis.

87 **Table 2**

Outage	Start Date	Proposed Replacement Power Costs	Corrected Replacement Power Costs	Difference
Colstrip 3	5/3/2016	\$ 2,923	\$ 1,274	\$ (1,649)
Colstrip 4	10/27/2016	27,193	27,193	-
Dave Johnston 4	3/25/2016	117,482	117,201	(280)
Gadsby 4	3/30/2016	3,571	142	(3,429)
Gadsby 4	4/8/2016	2,525	2,316	(208)
Gadsby 5	3/30/2016	5,703	880	(4,823)
Gadsby 5	4/8/2016	2,145	2,077	(67)
Gadsby 6	3/30/2016	8,459	41	(8,418)
Gadsby 6	4/8/2016	1,573	18	(1,555)
Gadsby 6	7/19/2016	75,090	16,244	(58,846)
Hermiston 1	8/2/2016	79,387	80,835	1,448
Hermiston 1	9/18/2016	7,113	7,113	-
Naughton 2	5/28/2016	47,949	47,949	-
Naughton 2	6/6/2016	136,570	136,570	-
Total		\$ 517,681	\$ 439,854	\$ (77,827)

88 Notably, the replacement energy from an outage is not necessarily only covered
 89 in full or part by market transactions. The Company's actual system operates
 90 dynamically, and therefore a unit's outage would change a number of system
 91 operational events, such as (but not limited to) ramping up / ramping down of other
 92 online generation units, utilizing contract rights, and market transactions.

TARIFF SCHEDULE 94

93

94 **Q. Please explain the DPU’s proposed language change in Tariff Schedule 94.**

95 A. The DPU proposes revising Tariff Schedule 94 to reflect more precise language from
96 the Commission’s order in Docket No. 09-035-15 issued February 16, 2017,² which
97 revised the EBA filing schedule (“Order”). Tariff Schedule No. 94 was included in this
98 filing as Exhibit RMP___(RMM-3) with Mr. Robert M. Meredith’s testimony on
99 March 15, 2017. In accordance with the DPU’s request, attached in Exhibit
100 RMP___(MGW-1R) is a first revision of Tariff Schedule No. 94.3 – 94.10, updating
101 the language consistent with the Order. This first revision includes the original
102 modifications made by Mr. Meredith in his filed testimony as well as the DPU’s request
103 to use Commission language.

104 **Q. Does this conclude your response testimony?**

105 A. Yes.

² Utah Division of Public Utilities Exhibit 1.2, EBA Audit Report, Page 36.

Rocky Mountain Power
Exhibit RMP__(MGW-1R)
Docket No. 17-035-01
Witness: Michael G. Wilding

BEFORE THE PUBLIC SERVICE COMMISSION
OF THE STATE OF UTAH

ROCKY MOUNTAIN POWER

Exhibit Accompanying Response Testimony of Michael G. Wilding
Proposed Revisions to Schedule 94

December 2017

ELECTRIC SERVICE SCHEDULE NO. 94 – Continued

Net Power Costs (NPC): the sum of costs incurred to acquire power to serve customers less revenues collected from sales for resale. NPC components are those included in the Company's production cost model and recorded in the FERC Accounts described in this electric service schedule.

Wheeling Revenue: Revenues from Transmission of Electricity of Others recorded in the FERC Account described in this electric service schedule.

EBA PROCEDURAL SCHEDULE (Beginning with the 2013 Annual EBA Filing)

1. Rocky Mountain Power will file its EBA application on or about March 15.
2. The Division of Public Utilities (DPU) will conduct a preliminary review of Rocky Mountain Power's application and provide a preliminary conclusion if the EBA filing appears to not depart from prior years' filings.
3. On or before May 1, the Public Service Commission of Utah (PSC) will approve interim rates with an amortization period through April of the following year, effective May 1.
4. The DPU will then file its audit report by November 15, following which the PSC will set a schedule in the docket.
5. The PSC will hold a hearing on or about February 1, after which a true-up of rates could be ordered.
6. The PSC will issue an order by March 1 of the following year before the next EBA filing is made.
7. Any true-up to interim rates will go into effect March 1, and be amortized through April 30 of the year following the year the application is filed.

EBA CALCULATIONS AND APPLICATION

APPLICABLE FERC ACCOUNTS: The EBA rate will be calculated using all components of EBAC as defined in the Company's most recent general rate case, major plant addition case, or other case where Base EBAC are approved. EBAC are typically booked to the following FERC accounts, as defined in Code of Federal Regulations, Subchapter C, Part 101, with the noted clarifications and exclusions:

FERC 501- Fuel

FERC Sub 5011000

SAP 515100 – Coal Consumed-Generation (Include)

SAP (all other) – Legal, maintenance, utilities, labor related, miscel O&M (Exclude)

FERC Sub 5013500 - Natural Gas Consumed (Non Gadsby) Natural Gas Swaps (Non Gadsby) (Include)

FERC Sub (All Other) – Property tax, office supplies, Labor, Fuel Handling, Supplies, Maintenance, Start-up Fuel, Start-up Fuel Diesel, Diesel Fuel Hedge, miscellaneous O&M, Flyash Sales (Exclude)

(continued)

ELECTRIC SERVICE SCHEDULE NO. 94 – Continued

EBA FERC 501 Adjustments

FERC Sub 5013500

SAP 515200 – Natural Gas Consumed

Gadsby Related Portion of 515200 is transferred to FERC 547(Fuel-Other Generation)

SAP 515220 – Natural Gas Swaps

Gadsby Related portion of 515220 is transferred to FERC 547(Fuel-Other Generation)

SAP 505917– I/C Nat Gas Cons Ker. This SAP account is transferred to FERC 547(Fuel-Other Generation)

FERC 447 – Sales For Resale

FERC Sub 4471400

SAP 301406 – Short-term Firm Wholesale

Non Transalta Sales (Include)

SAP 301409 – Trading Sales Netted-Estimate (Exclude)

SAP 301410 – Trade Sales Netted (Include)

SAP 301411 – Bookout Sales Netted (Include)

SAP 301412 – Bookout Sales Netted-Estimate (Exclude)

SAP 302751 – I/C ST Firm Whls-Sie (Include)

SAP 302752 – I/C S-T Firm Wholesale Sales-Nevada Pwr (Include)

SAP 302771 – I/C Line Loss Trading Revenue-Sierra Pac (Include)

SAP 302772 – I/C Line Loss-Nevada (Include)

SAP 303028 – Line Loss W/S Trading (Include)

SAP 303100 – Transmission Loss Charge Pass-Through (Exclude)

SAP 303109 – Transmission Line Loss Rev – Subject to Refund (Include)

SAP 301409 – Trading Sales Netted – Estimates (Exclude)

FERC Sub 4471300

SAP 301405 – FIRM Sales (Include)

FERC Sub 4476100

SAP 304101 – Bookouts Netted – Gain (Include)

SAP 304102 – Bookouts Netted – Estimates (Exclude)

FERC Sub 4476200

SAP 304201 – Trading Net- Gains (Include)

FERC Sub 4472000 – Sales for Resale Estimates (Exclude)

FERC Sub 4475000

SAP 301408 – Off-System Non Firm (Include)

FERC Sub 4479000 – Transmission Services - Utah FERC Customers, Wyo-Pacific Cheyenne (Exclude)

FERC Sub 4471000 – Onsystem Firm - Utah FERC Customers, Wyo-Pacific Cheyenne, Brigham City, Portland General Electric (Exclude)

(continued)

ELECTRIC SERVICE SCHEDULE NO. 94 – Continued

EBA FERC 447 Adjustments

- 1) SAP 301406 - Short-term Firm Wholesale – Transalta Sales are removed from 447 and transferred into 555 (Purchased Power).
- 2) SAP 505214 – SMUD Purchases from 555 (Purchased Power) are transferred to 447.

FERC 555 – Purchased Power

FERC Sub 5552600

SAP 505351 – Electric Swaps G/L (Include)

SAP 505352 – Electric Swaps G/L Estimate (Exclude)

FERC Sub 5551100,1200,1330 - BPA Residential Exchange (Exclude)

FERC 555 – Purchased Power (continued)

FERC Sub 5552200,2300,2400 – REC Purchases, RPS Compliance Purchases (Exclude)

FERC Sub 5552500

SAP 505190 – OR Solar Incentive Purchases (Include)

SAP 505206 – Other Energy Purchases, Int (Include)

SAP (All Other) – Exchange Value Purchase, Exchange Value Purchase – Estimate, Purchase Power Expense – Estimate, I/C Purchased Power Esp Est-Sierra Pac, I/C Purchased Power Exp Est-Nevada Pwr, Renewable Energy Credit Purchase (Exclude)

FERC Sub 5555500

SAP 505207 – IPP Energy Purchase (Include)

FERC Sub 5556200

SAP 304211 – Trading Netted – Loss (Include)

SAP 304213 – Trading Netted – Estimates (Exclude)

FERC Sub 5556300

SAP 505214 – Firm Energy Purchases (Include)

FERC Sub 5556400

SAP 505218 – Firm Demand Purchases (Include)

FERC Sub 5555700, 5556700

SAP 505215 – Post Merger Imb Charge (Include)

SAP 505220 – Trading Purchases Netted (Include)

SAP 505221 – Bookout Purchases Netted (Include)

SAP 505969 – Transmission Imbalance – Subject to Refund (Include)

SAP 546516 – CA GHG Wholesale Obligation (Include)

SAP 546520 – Operating Reserves Expense (Include)

SAP (All Other) – Bookout Purchases Net – Estimates, Trading Purchases Netted – Estimates, Transmission Imbalance Pass-Through Expense, NPC Deferral Accounting Entries, Excess Net Power Cost Amortization Renewable Energy Credit Sales Deferral CA GHG Allowance Amortization Expense (Exclude)

FERC Sub 5556710

SAP 508001 - EIM Exp - FMM IIE: CAISO to Pac (Include)

SAP 508003 - EIM Exp - FMM Assess: Pac Trans to C&T (Include)

SAP 508011 - EIM Exp - RTD IIE: CAISO to Pac (Include)

SAP 508013 - EIM Exp - RTD Assess: Pac Trans to C&T (Include)

(continued)

ELECTRIC SERVICE SCHEDULE NO. 94 – Continued

FERC 555 – Purchased Power (continued)

FERC Sub 5556710 (continued)

- SAP 508015 - EIM Exp - GHG Em Cost Rev: CAISO to Pac (Include)
- SAP 508021 - EIM Exp - UIE (Load): CAISO to Pac (Include)
- SAP 508023 - EIM Exp - UIE (Load): Pac Trans to C&T (Include)
- SAP 508031 - EIM Exp - UIE (Gen): CAISO to Pac (Include)
- SAP 508033 - EIM Exp - UIE (Gen): Pac Trans to C&T (Include)
- SAP 508041 - EIM Exp - Daily Rounding Adj: w/CAISO (Include)
- SAP 508051 - EIM Exp - O/U Sched Charge: w/CAISO (Include)
- SAP 508052 - EIM Exp – EIM Exp - O/U Sched Alloc: w/CAISO (Include)
- SAP 508053 - EIM Exp - O/U Sched Alloc: w/CAISO (Include)
- SAP 508054 - EIM Exp - O/U Sched Alloc: PAC to TC (Include)
- SAP 508061 - EIM Exp-Ancil Svc Upw Neutral: w/CAISO (Include)
- SAP 508062 - EIM Exp-Spinning Reserve Oblig: w/CAISO (Include)
- SAP 508063 - EIM Exp-Spin Reserve Neutral: w/CAISO (Include)
- SAP 508064 - EIM Exp-Non-Spin Reserve Oblig: w/CAISO (Include)
- SAP 508065 - EIM Exp-Non-Spin Reserve Neut: w/CAISO (Include)
- SAP 508066 - EIM Exp - Excess Cost Neutral: w/CAISO (Include)
- SAP 508071 - EIM Exp - RT Bid Cost Recovery: w/CAISO (Include)
- SAP 508081 - EIM Exp-IFM Loss Surplus Credit w/CAISO (Include)
- SAP 508091 - EIM Exp - Flexible Ramp Cost: w/CAISO (Include)
- SAP 508092 - EIM Exp - Flexible Ramp Cost (Include)
- SAP 508095 - EIM Exp-Flex RampUp Cap Pay: w/CAISO (Include)
- SAP 508096 - EIM Exp-Flex RampUp Cap No Pay: w/CAISO (Include)
- SAP 508101 - EIM Exp-RT Unaccounted Energy: w/CAISO (Include)
- SAP 508111 - EIM Exp-RT Imb Energy Offset: w/CAISO (Include)
- SAP 508112 - EIM Exp-RT Imb Energy Offset (Include)
- SAP 508121 - EIM Exp-RT BCR EIM Alloc: CAISO to Pac (Include)
- SAP 508122 - EIM Exp-RT BCR EIM (Include)
- SAP 508125 - EIM Exp-RTM BCR EIM Set: CAISO to Pac (Include)
- SAP 508131 - EIM Exp-RT Congestion OS: CAISO to Pac (Include)
- SAP 508132 - EIM Exp-RT Congestion (Include)
- SAP 508141 - EIM Exp-RT Marginal Loss: CAISO to Pac (Include)
- SAP 508142 - EIM Exp-Neutrality Adjust CAISO to Pac (Include)
- SAP 508151 - EIM Exp-7070 FRP Forecast Mvmt
- SAP 508152 - EIM Exp-7076 FRP Forecast Mvmt Alloc
- SAP 508153 - EIM Exp-7071 FRP Daily Up Uncert
- SAP 508154 - EIM Exp-7081 FRP Daily Down Uncert
- SAP 508155 - EIM Exp-7077 FRP Daily Up Uncert Alloc
- SAP 508156 - EIM Exp-7078 FRP Month Up Uncert Alloc
- SAP 508157 - EIM Exp-7087 FRP Daily Down Uncert Allo
- SAP 508158 - EIM Exp-7088 FRP Month Down Uncert Allo

(continued)

ELECTRIC SERVICE SCHEDULE NO. 94 – Continued

FERC 555 – Purchased Power (continued)

FERC Sub 5558000

SAP 505227 – Purchased Power Expense – Under Capital Lease (Include)

FERC Sub 5556100

SAP 304111 – Bookouts Netted – Loss (Include)

FERC Sub 5555900

SAP 505224 – Short-Term Firm Wholesale Purchases (Include)

SAP 505931 – I/C ST Firm Pur-Sier (Include)

SAP 505932 – I/C ST Firm Pur-Nev (Include)

EBA FERC 555 Adjustments

1) FERC Sub 5552500

SAP 505206 - Other Energy Purchases: Remove exchange dollars

2) SAP 301406 - Short-term Firm Wholesale – Transalta Sales are removed from 447 and transferred into 555 (Purchased Power).

3) SAP 505214 - SMUD Purchases are removed from 555 (Purchased Power) and transferred to 447.

FERC 565 – Wheeling Expense

FERC Sub 5650000

SAP 546530 - ISO/PX Charges (Include)

FERC Sub 5650010

SAP 506801 - EIM Wheeling Exp-GMC (Include)

SAP 506802 - EIM Wheeling Exp-GMC (Include)

FERC Sub 5651000

SAP 506010 - Short Term Firm Wheeling (Include)

SAP 506059 - Wheeling Expense Estimate (Exclude)

SAP 506911 - I/C S-T Firm Wheeling Exp-Nevada Pwr (Include)

SAP 506912 - I/C S-T Firm Wheeling Exp-Nevada Pwr (Include)

SAP 506952 - I/C Wheeling Exp Estimate-Nevada Pwr (Exclude)

FERC Sub 5652500, 5654600

SAP 506921 - I/C Non-Firm Wheeling Exp-Sierra Pac (Include)

SAP 506922 – I/C Non-Firm Wheeling Exp-Nevada Pwr (Include)

FERC 503 Steam From Other Sources

FERC Sub 5030000

SAP 515900 – Geothermal Steam (Include)

SAP (All Other) – Labor, materials and supplies, other miscellaneous O&M (Exclude)

(continued)

Issued by authority of Report and Order of the Public Service Commission of Utah in Docket No. 17-035-01

FILED: December 19, 2017

EFFECTIVE: May 1, 2017

ELECTRIC SERVICE SCHEDULE NO. 94 – Continued

FERC 547 Fuel – Other Generation

FERC Sub 5471000 - I/C Nat Gas Cons Ker, Natural Gas Consumed, Nat Gas Exp – Under Capital Lease, Natural Gas Swaps (Include)

EBA FERC 547 Adjustments

FERC Sub 5013500

SAP 515200 – Natural Gas Consumed

Gadsby Related Portion of 515200 (From FERC 501) is transferred to this FERC account (547).

SAP 515220 – Natural Gas Swaps

Gadsby Related portion of 515220 (From FERC 501) is transferred to this FERC account (547).

SAP 505917 - I/C Nat Gas Cons Ker. Some of this SAP account was booked originally to FERC 501. This adjustment transfers the amount in 501 to this FERC account (547).

FERC 456.1 Revenues from Transmission of Electricity by Others

FERC Sub 4561100

SAP 505961 – Transmission Imbalance Penalty Revenue – Load (Exclude)

SAP 505963 – Transmission Imbalance Penalty Revenue –Pt to Pt (Exclude)

SAP (All Other) – Primary Delivery and Distribution Sub Charges, Ancillary Revenue, Use of Facility – Revenue, Transmission Resales to Other Parties, Transmission Revenue Unreserved Use Charges Transmission Revenue – Deferral Fees (Include)

SAP 302081 - I/C Anc Rev Sch 1-Scheduling-Sierra Pac (Include)

SAP 302082 - I/C Anc Rev Sch 1-Scheduling-Nevada Pwr (Include)

SAP 302091 - I/C Anc Rev Sch 2-Reactive-Sierra Pac (Include)

SAP 302092 - I/C Anc Rev Sch 2-Reactive-Nevada Pwr (Include)

SAP 302821 - I/C Anc Rev Sch 1-Scheduling-Sierra Pac (Include)

SAP 302822 - I/C Anc Rev Sch 1-Scheduling-Nevada Pwr (Include)

SAP 302831 – I/C Other Wheeling Revenue-Sierra Pac (Include)

FERC Sub 4561600

SAP 301912 – Post-Merger Firm Wheeling Revenue (Include)

FERC Sub 4561910

SAP 301926 – Short-Term Firm Wheeling (Include)

SAP 302812 - I/C ST Firm Wheeling Revenue-Nevada Pwr (Include)

FERC Sub 4561920 – Firm Wheeling Revenue, Pre-Merger Firm Wheeling Revenue, Transmission Capacity Re-assignment revenue and contra revenue, Transmission Point-to-Point Revenue (Include)

FERC Sub 4561930

SAP 301922 – Non-Firm Wheeling Revenue (Include)

FERC Sub 4561990

SAP 301913 – Transmission Tariff True-up (Include)

SAP 302990 – L-T Transmission Revenue – Subject to Refund (Include)

SAP 302991 – S-T Transmission Revenue – Subject to Refund (Include)

(continued)

ELECTRIC SERVICE SCHEDULE NO. 94 – Continued

FERC 456.1 Revenues from Transmission of Electricity by Others (continued)

FERC Sub 4561990 (continued)

- SAP 305910 – Ancillary Revenue Sch 1 – Subject to Refund (Include)
- SAP 305920 – Ancillary Revenue Sch 2 – Subject to Refund (Include)
- SAP 305930 – Ancillary Revenue Sch 3 – Subject to Refund (Include)
- SAP 305931 – Ancillary Revenue Sch 3a – Subject to Refund (Include)

Accruals or estimates in accounts 447, 555, and 565 will be excluded; rather, expenses and revenue will be accounted for in the months that they are incurred. Adjustments shall be made to Actual EBAC that are consistent with Commission accepted or ordered adjustments, or adjustments called out in a stipulation or settlement agreement, as ordered in the most recent general rate case, major plant addition case, or other case where Base EBAC are approved.

EBA DEFERRAL: The monthly EBA Accrual (positive or negative) is determined by calculating the difference between Base NPC and Actual NPC as is described below.

Through May 31, 2016:

$$EBA\ Deferral_{Utah, month} = [(Actual\ EBAC_{month/MWh} - Base\ EBAC_{month/MWh}) \times Actual\ MWh_{Utah, month}] \times 70\%$$

Starting June 1, 2016 through December 31, 2019:

$$EBA\ Deferral_{Utah, month} = [(Actual\ EBAC_{month/MWh} - Base\ EBAC_{month/MWh}) \times Actual\ MWh_{Utah, month}] \times 100\%$$

Where:

$$Actual\ EBAC_{month/MWh} = (NPC_{Utah, month, actual} / Actual\ MWh_{Utah, month}) + (WR_{Utah, month, actual} / Actual\ MWh_{Utah, month})$$

$$Base\ EBAC_{month/MWh} = (NPC_{Utah, month, base} / Base\ MWh_{Utah, month}) + (WR_{Utah, month, base} / Base\ MWh_{Utah, month})$$

$NPC_{Utah, month}$ = Total Company NPC for the month multiplied by the appropriate allocation factors from the most recent general rate case, major plant additions case, or other case where Base EBAC are approved.

$WR_{Utah, month}$ = Total Company Wheeling Revenue for the month multiplied by the appropriate allocation factors from the most recent general rate case, major plant additions case, or other case where Base EBAC are approved.

(continued)

ELECTRIC SERVICE SCHEDULE NO. 94 – Continued

EBA Deferral Account Balance: the monthly EBA Account Balance will be calculated as follows:

$$\text{EBA Deferral Account Balance}_{\text{current month}} = \text{Ending Balance}_{\text{previous month}} + \text{Deferral}_{\text{current month}} \\ - \text{EBA Revenue}_{\text{current month}} + \text{EBA Carrying charge}_{\text{month}}$$

EBA CARRYING CHARGE: the EBA Carrying Charge will be calculated and applied to the monthly balance in the EBA Deferral Account as follows:

$$\text{EBA Carrying Charge}_{\text{month}} = [\text{Ending Balance}_{\text{previous month}} + (\text{Deferral}_{\text{current month}} \times 0.5) \\ - (\text{EBA Revenue}_{\text{current month}} \times 0.5)] \times 0.5\%$$

EBA RATE DETERMINATION: Annually, on the EBA Filing Date, Rocky Mountain Power shall file with the Commission an application for establishment of an EBA rate to become effective on the EBA Rate Effective Date of that year. The EBA Deferral Account Balance as of December 31 shall be allocated to all retail tariff rate schedules and applicable special contracts based on the rate spread approved by the Commission. The new EBA rate will be determined by dividing the EBA Deferral Account Balance allocated to each rate schedule and applicable contract by the schedule or contract forecasted Power Charge and Energy Charge revenues. The EBA rate will be a percentage increase or decrease applied to the monthly Power Charges and Energy Charges of the Customer's applicable schedule or contract as set forth in the schedule.

AUDIT PROCEDURES: All items recorded in the EBA Balancing Account are subject to regulatory audit and prudence review. The Division of Public Utilities will complete its audit according to the EBA Procedural Schedule.

(continued)

Issued by authority of Report and Order of the Public Service Commission of Utah in Docket No. 17-035-01

FILED: December 19, 2017

EFFECTIVE: May 1, 2017

P.S.C.U. No. 50

First Revision of Sheet No. 94.3
Canceling Original Sheet No. 94.3

ELECTRIC SERVICE SCHEDULE NO. 94 – eContinued

Net Power Costs (NPC): the sum of costs incurred to acquire power to serve customers less revenues collected from sales for resale. NPC components are those included in the Company's production cost model and recorded in the FERC Accounts described in this electric service schedule.

Wheeling Revenue: Revenues from Transmission of Electricity of Others recorded in the FERC Account described in this electric service schedule.

EBA PROCEDURAL SCHEDULE (Beginning with the 2013 Annual EBA Filing)

1. Rocky Mountain Power will file its EBA application on or about March 15.
2. The Division of Public Utilities (DPU) will conduct a preliminary review of Rocky Mountain Power's application and provide a preliminary conclusion if the EBA filing appears to not depart from prior years' filings.
- ~~4.3. On or before May 1, the Public Service Commission of Utah (PSC) will approve interim rates with an amortization period through April of the following year, effective May 1.~~
- ~~2.4. The Division of Public Utilities DPU will then file complete its audit report and supporting testimony by July-November 15, following which the PSC will set a schedule in the docket.~~
- ~~3.5. The PSC will hold a hearing on or about February 1, after which a true-up of rates could be ordered. Intervenor may conduct discovery, with a 14 day turn around, beginning March 15.~~
- ~~4.6. The PSC will issue an order by March 1 of the following year before the next EBA filing is made. Hearings on the application will be completed by September 15.~~
- ~~5.7. Any true-up to interim rates change necessary to recover or refund an EBA balance will take go into effect March 1, and be amortized through April 30 on or before November 1 of the year following the year the application is filed.~~

EBA CALCULATIONS AND APPLICATION

APPLICABLE FERC ACCOUNTS: The EBA rate will be calculated using all components of EBAC as defined in the Company's most recent general rate case, major plant addition case, or other case where Base EBAC are approved. EBAC are typically booked to the following FERC accounts, as defined in Code of Federal Regulations, Subchapter C, Part 101, with the noted clarifications and exclusions:

FERC 501- Fuel

- FERC Sub 5011000
 - SAP 515100 – Coal Consumed-Generation (Include)
 - SAP (all other) – -Legal, maintenance, utilities, labor related, miscel O&M (Exclude)
- FERC Sub 5013500 - Natural Gas Consumed (Non Gadsby) -Natural Gas Swaps (Non Gadsby) (Include)

(continued)

Issued by authority of Report and Order of the Public Service Commission of Utah in Docket No. ~~13-035-18417-035-01~~

FILED: ~~September 5, 2014~~ December 19, 2017
EFFECTIVE: ~~September 1, 2014~~ May 1, 2017

P.S.C.U. No. 50

First Revision of Sheet No. 94.3
Canceling Original Sheet No. 94.3

FERC Sub (All Other)- – Property tax, office supplies, Labor, Fuel Handling, Supplies,
Maintenance, Start-up Fuel,
Start-up Fuel Diesel, Diesel Fuel Hedge, miscellaneous O&M, Flyash Sales (Exclude)

(continued)

Issued by authority of Report and Order of the Public Service Commission of Utah in Docket No. ~~13-035-~~
~~18417-035-01~~

FILED: ~~September 5, 2014~~December 19, 2017

EFFECTIVE: ~~September 1, 2014~~May 1, 2017

P.S.C.U. No. 50

Second-Third Revision of Sheet No. 94.4
Canceling **First-Second** Revision of Sheet No. 94.4

ELECTRIC SERVICE SCHEDULE NO. 94 – eContinued

EBA FERC 501 Adjustments

FERC Sub 5013500

SAP 515200 – Natural Gas Consumed

Gadsby Related Portion of 515200 is transferred to FERC 547(Fuel-Other Generation)

SAP 515220 – Natural Gas Swaps

Gadsby Related portion of 515220 is transferred to FERC 547(Fuel-Other Generation)

SAP 505917– I/C Nat Gas Cons Ker. This SAP account is transferred to FERC 547(Fuel-Other Generation)

FERC 447 – Sales For Resale

FERC Sub 4471400

SAP 301406 – Short-term Firm Wholesale

Non Transalta Sales (Include)

SAP 301409 – Trading Sales Netted-Estimate (Exclude)

SAP 301410 – Trade Sales Netted (Include)

SAP 301411 – Bookout Sales Netted (Include)

SAP 301412 – Bookout Sales Netted-Estimate (Exclude)

SAP 302751 – I/C ST Firm Whls-Sie (Include)

SAP 302752 – I/C S-T Firm Wholesale Sales-Nevada Pwr (Include)

SAP 302771 – I/C Line Loss Trading Revenue-Sierra Pac (Include)

SAP 302772 – I/C Line Loss-Nevada (Include)

SAP 303028 – Line Loss W/S Trading (Include)

SAP 303100 – Transmission Loss Charge Pass-Through (Exclude)

SAP 303109 – Transmission Line Loss Rev – Subject to Refund (Include)

SAP 301409 – Trading Sales Netted – Estimates (Exclude)

FERC Sub 4471300

SAP 301405 – FIRM Sales (Include)

FERC Sub 4476100

SAP 304101 – Bookouts Netted – Gain (Include)

SAP 304102 – Bookouts Netted – Estimates (Exclude)

FERC Sub 4476200

SAP 304201 – Trading Net- Gains (Include)

FERC Sub 4472000 – Sales for Resale Estimates (Exclude)

FERC Sub 4475000

SAP 301408 – Off-System Non Firm (Include)

FERC Sub 4479000 – Transmission Services - Utah FERC Customers, Wyo-Pacific Cheyenne (Exclude)

FERC Sub 4471000 – Onsystem Firm - Utah FERC Customers, Wyo-Pacific Cheyenne, Brigham City, Portland General Electric (Exclude)

(continued)

Issued by authority of Report and Order of the Public Service Commission of Utah in Docket No. ~~15-035-0317-035-01~~

FILED: ~~October 20, 2015~~ December 8, 2017
EFFECTIVE: ~~November 1, 2015~~ May 1, 2017

P.S.C.U. No. 50

Second-Third Revision of Sheet No. 94.5
Canceling ~~First-Second~~ Revision of Sheet No. 94.5

ELECTRIC SERVICE SCHEDULE NO. 94 – eContinued

EBA FERC 447 Adjustments

- 1) SAP 301406 - Short-term Firm Wholesale – Transalta Sales are removed from 447 and transferred into 555 (Purchased Power).
- 2) SAP 505214 – SMUD Purchases from 555 (Purchased Power) are transferred to 447.

FERC 555 – Purchased Power

FERC Sub 5552600

SAP 505351 – Electric Swaps G/L (Include)

SAP 505352 – Electric Swaps G/L Estimate (Exclude)

FERC Sub 5551100,1200,1330 - BPA Residential Exchange (Exclude)

FERC 555 – Purchased Power (continued)

FERC Sub 5552200,2300,2400 – REC Purchases, RPS Compliance Purchases (Exclude)

FERC Sub 5552500

SAP 505190 – OR Solar Incentive Purchases (Include)

SAP 505206 – Other Energy Purchases, Int (Include)

SAP (All Other) – Exchange Value Purchase, Exchange Value Purchase – Estimate, Purchase Power Expense – Estimate, I/C Purchased Power Esp Est-Sierra Pac,I/C Purchased Power Exp Est-Nevada Pwr, Renewable Energy Credit Purchase (Exclude)

FERC Sub 5555500

SAP 505207 – -IPP Energy Purchase (Include)

FERC Sub 5556200

SAP 304211 – -Trading Netted – Loss (Include)

SAP 304213 – -Trading Netted – Estimates (Exclude)

FERC Sub 5556300

SAP 505214 – -Firm Energy Purchases (Include)

FERC Sub 5556400

SAP 505218 – -Firm Demand Purchases (Include)

FERC Sub 5555700, 5556700

SAP 505215 – Post Merger Imb Charge (Include)

SAP 505220 – Trading Purchases Netted (Include)

SAP 505221 – Bookout Purchases Netted (Include)

SAP 505969 – Transmission Imbalance – Subject to Refund (Include)

SAP 546516 – CA GHG Wholesale Obligation (Include)

SAP 546520 – Operating Reserves Expense (Include)

~~SAP 505969 – Transmission Imbalance – Subject to Refund (Include)~~

————— SAP (All Other) – Bookout Purchases Net – Estimates, Trading Purchases Netted – Estimates, Transmission Imbalance Pass-Through Expense, NPC Deferral Accounting Entries, Excess Net Power Cost Amortization Renewable Energy Credit Sales Deferral CA GHG Allowance Amortization Expense (Exclude)

FERC Sub 5556710

SAP 508001 - EIM Exp - FMM IIE: CAISO to Pac (Include)

(continued)

Issued by authority of Report and Order of the Public Service Commission of Utah in Docket No. 175-035-013

FILED: ~~October 20, 2015~~ December 19, 2017

EFFECTIVE: ~~November 1, 2015~~ May 1, 2017

P.S.C.U. No. 50

**~~Second~~ Third Revision of Sheet No. 94.5
Canceling ~~First~~ Second Revision of Sheet No. 94.5**

SAP 508003 - EIM Exp - FMM Assess: Pac Trans to C&T (Include)

SAP 508011 - EIM Exp - RTD IIE: CAISO to Pac (Include)

~~_____~~ SAP 508013 - EIM Exp - RTD Assess: Pac Trans to C&T (Include)

(continued)

Issued by authority of Report and Order of the Public Service Commission of Utah in Docket No. ~~175-035-013~~

FILED: ~~October 20, 2015~~ December 19, 2017

EFFECTIVE: ~~November 1, 2015~~ May 1, 2017

P.S.C.U. No. 50

Second-Third Revision of Sheet No. 94.6
Canceling **First-Second** Revision of Sheet No. 94.6

ELECTRIC SERVICE SCHEDULE NO. 94 – eContinued

FERC 555 – Purchased Power (continued)

FERC Sub 5556710 (continued)

SAP 508015 - EIM Exp - GHG Em Cost Rev: CAISO to Pac (Include)
SAP 508021 - EIM Exp - UIE (Load): CAISO to Pac (Include)
SAP 508023 - EIM Exp - UIE (Load): Pac Trans to C&T (Include)
SAP 508031 - EIM Exp - UIE (Gen): CAISO to Pac (Include)
SAP 508033 - EIM Exp - UIE (Gen): Pac Trans to C&T (Include)
SAP 508041 - EIM Exp - Daily Rounding Adj: w/CAISO (Include)
SAP 508051 - EIM Exp - O/U Sched Charge: w/CAISO (Include)
SAP 508052 - EIM Exp - EIM Exp - O/U Sched Alloc: w/CAISO (Include)
SAP 508053 - EIM Exp - O/U Sched Alloc: w/CAISO (Include)
SAP 508054 - EIM Exp - O/U Sched Alloc: PAC to TC (Include)
SAP 508061 - EIM Exp-Ancil Svc Upw Neutral: w/CAISO (Include)
SAP 508062 - EIM Exp-Spinning Reserve Oblig: w/CAISO (Include)
SAP 508063 - EIM Exp-Spin Reserve Neutral: w/CAISO (Include)
SAP 508064 - EIM Exp-Non-Spin Reserve Oblig: w/CAISO (Include)
SAP 508065 - EIM Exp-Non-Spin Reserve Neut: w/CAISO (Include)
SAP 508066 - EIM Exp - Excess Cost Neutral: w/CAISO (Include)
SAP 508071 - EIM Exp - RT Bid Cost Recovery: w/CAISO (Include)
SAP 508081 - EIM Exp-IFM Loss Surplus Credit w/CAISO (Include)
SAP 508091 - EIM Exp - Flexible Ramp Cost: w/CAISO (Include)
SAP 508092 - EIM Exp - Flexible Ramp Cost (Include)
SAP 508095 - EIM Exp-Flex RampUp Cap Pay: w/CAISO (Include)
SAP 508096 - EIM Exp-Flex RampUp Cap No Pay: w/CAISO (Include)
SAP 508101 - EIM Exp-RT Unaccounted Energy: w/CAISO (Include)
SAP 508111 - EIM Exp-RT Imb Energy Offset: w/CAISO (Include)
SAP 508112 - EIM Exp-RT Imb Energy Offset (Include)
SAP 508121 - EIM Exp-RT BCR EIM Alloc: CAISO to Pac (Include)
SAP 508122 - EIM Exp-RT BCR EIM (Include)
SAP 508125 - EIM Exp-RTM BCR EIM Set: CAISO to Pac (Include)
SAP 508131 - EIM Exp-RT Congestion OS: CAISO to Pac (Include)
SAP 508132 - EIM Exp-RT Congestion (Include)
SAP 508141 - EIM Exp-RT Marginal Loss: CAISO to Pac (Include)
SAP 508142 - EIM Exp-Neutrality Adjust CAISO to Pac (Include)
SAP 508151 - EIM Exp-7070 FRP Forecast Mvmt
SAP 508152 - EIM Exp-7076 FRP Forecast Mvmt Alloc
SAP 508153 - EIM Exp-7071 FRP Daily Up Uncert
SAP 508154 - EIM Exp-7081 FRP Daily Down Uncert
SAP 508155 - EIM Exp-7077 FRP Daily Up Uncert Alloc
SAP 508156 - EIM Exp-7078 FRP Month Up Uncert Alloc
SAP 508157 - EIM Exp-7087 FRP Daily Down Uncert Allo
SAP 508158 - EIM Exp-7088 FRP Month Down Uncert Allo

(continued)

Issued by authority of Report and Order of the Public Service Commission of Utah in Docket No. 175-035-013

FILED: ~~October 20, 2015~~ December 19, 2017

EFFECTIVE: ~~November 1, 2015~~ May 1, 2017

P.S.C.U. No. 50

Third Fourth Revision of Sheet No. 94.7
Canceling ~~Second Third~~ Revision of Sheet No. 94.7

ELECTRIC SERVICE SCHEDULE NO. 94 – eContinued

FERC 555 – Purchased Power (continued)

FERC Sub 5558000

SAP 505227 – Purchased Power Expense – Under Capital Lease (~~Exclude~~Include)

FERC Sub 5556100

SAP 304111 – Bookouts Netted – Loss (Include)

FERC Sub 5555900

SAP 505224 – Short-Term Firm Wholesale Purchases (Include)

SAP 505931 – I/C ST Firm Pur-Sier (Include)

SAP 505932 – I/C ST Firm Pur-Nev (Include)

EBA FERC 555 Adjustments

1) FERC Sub 5552500

SAP 505206 - Other Energy Purchases: Remove exchange dollars

2) SAP 301406 - Short-term Firm Wholesale – Transalta Sales are removed from 447 and transferred into 555 (Purchased Power).

3) SAP 505214 - SMUD Purchases are removed from 555 (Purchased Power) and transferred to 447.

FERC 565 – Wheeling Expense (~~continued~~)

FERC Sub 5650000

SAP 546530 - ISO/PX Charges (Include)

FERC Sub 5650010

SAP 506801 - EIM Wheeling Exp-GMC (Include)

SAP 506802 - EIM Wheeling Exp-GMC (Include)

FERC Sub 5651000

SAP 506010 - Short Term Firm Wheeling (Include)

SAP 506059 - Wheeling Expense Estimate (Exclude)

SAP 506911 - I/C S-T Firm Wheeling Exp-Nevada Pwr (Include)

SAP 506912 - I/C S-T Firm Wheeling Exp-Nevada Pwr (Include)

SAP 506952 - I/C Wheeling Exp Estimate-Nevada Pwr (Exclude)

FERC Sub 5652500, ~~2700, 5654600~~ — ~~Non-Firm Wheeling Expense, Pre Merger Firm Wheeling, Firm Wheeling Expense~~

~~Firm Wheeling Expense (Trm) (Include)~~

SAP 506921 - I/C Non-Firm Wheeling Exp-Sierra Pac (Include)

SAP 506922 – I/C Non-Firm Wheeling Exp-Nevada Pwr (Include)

FERC 503 Steam From Other Sources

FERC Sub 5030000

SAP 515900 – Geothermal Steam (Include)

SAP (All Other) – Labor, materials and supplies, other miscellaneous O&M (Exclude)

(continued)

Issued by authority of Report and Order of the Public Service Commission of Utah in Docket No. 176-035-01

FILED: ~~October 11, 2016~~ December 19, 2017

EFFECTIVE: ~~November 1, 2016~~ May 1, 2017

P.S.C.U. No. 50

~~Second~~ Third Revision of Sheet No. 94.8
Canceling ~~First~~ Second Revision of Sheet No. 94.8

ELECTRIC SERVICE SCHEDULE NO. 94 – eCContinued

FERC 547 Fuel – Other Generation

FERC Sub 5471000 - I/C Nat Gas Cons Ker, Natural Gas Consumed, Nat Gas Exp – Under Capital Lease, Natural Gas Swaps (Include)

EBA FERC 547 Adjustments

FERC Sub 5013500

SAP 515200 – Natural Gas Consumed

Gadsby Related Portion of 515200 (From FERC 501) is transferred to this FERC account (547).

SAP 515220 – Natural Gas Swaps

Gadsby Related portion of 515220 (From FERC 501) is transferred to this FERC account (547).

SAP 505917 - I/C Nat Gas Cons Ker. Some of this SAP account was booked originally to FERC 501. This adjustment transfers the amount in 501 to this FERC account (547).

FERC 456.1 Revenues from Transmission of Electricity by Others ~~(continued)~~

FERC Sub 4561100

SAP 505961 – Transmission Imbalance Penalty Revenue – Load (Exclude)

SAP 505963 – Transmission Imbalance Penalty Revenue –Pt to Pt (Exclude)

SAP (All Other) – Primary Delivery and Distribution Sub Charges, Ancillary Revenue, Use of Facility – Revenue, Transmission Resales to Other Parties, Transmission Revenue Unreserved Use Charges Transmission Revenue – Deferral Fees (Include)

SAP 302081 - I/C Anc Rev Sch 1-Scheduling-Sierra Pac (Include)

SAP 302082 - I/C Anc Rev Sch 1-Scheduling-Nevada Pwr (Include)

SAP 302091 - I/C Anc Rev Sch 2-Reactive-Sierra Pac (Include)

SAP 302092 - I/C Anc Rev Sch 2-Reactive-Nevada Pwr (Include)

SAP 302821 - I/C Anc Rev Sch 1-Scheduling-Sierra Pac (Include)

SAP 302822 - I/C Anc Rev Sch 1-Scheduling-Nevada Pwr (Include)

SAP 302831 – I/C Other Wheeling Revenue-Sierra Pac (Include)

FERC Sub 4561600

SAP 301912 – Post-Merger Firm Wheeling Revenue (Include)

FERC Sub 4561910

SAP 301926 – Short-Term Firm Wheeling (Include)

SAP 302812 - I/C ST Firm Wheeling Revenue-Nevada Pwr (Include)

FERC Sub 4561920 – Firm Wheeling Revenue, Pre-Merger Firm Wheeling Revenue, Transmission Capacity Re-assignment revenue and contra revenue, Transmission Point-to-Point Revenue (Include)

FERC Sub 4561930

SAP 301922 – Non-Firm Wheeling Revenue (Include)

FERC Sub 4561990

SAP 301913 – Transmission Tariff True-up (Include)

(continued)

Issued by authority of Report and Order of the Public Service Commission of Utah in ~~Advice Docket~~ No. ~~16-0417-035-01~~

FILED: ~~May 23, 2016~~ December 19, 2017
2017

EFFECTIVE: ~~June 1, 2016~~ May 1,

P.S.C.U. No. 50

**~~Second~~ Third Revision of Sheet No. 94.8
Canceling ~~First~~ Second Revision of Sheet No. 94.8**

SAP 302990 – L-T Transmission Revenue – Subject to Refund (Include)
SAP 302991 – S-T Transmission Revenue – Subject to Refund (Include)

(continued)

Issued by authority of Report and Order of the Public Service Commission of Utah in ~~Advice~~ Docket No. ~~16-0417-035-01~~

FILED: ~~May 23, 2016~~ December 19, 2017
2017

EFFECTIVE: ~~June 1, 2016~~ May 1,

P.S.C.U. No. 50
Third ~~Fourth~~ Revision of Sheet No. 94.9
Canceling ~~Second-Third~~ Revision of Sheet No. 94.9
ELECTRIC SERVICE SCHEDULE NO. 94 – eContinued
FERC 456.1 Revenues from Transmission of Electricity by Others (continued)

FERC Sub 4561990 (continued)

- SAP 305910 – Ancillary Revenue Sch 1 – Subject to Refund (Include)
- SAP 305920 – Ancillary Revenue Sch 2 – Subject to Refund (Include)
- SAP 305930 – Ancillary Revenue Sch 3 – Subject to Refund (Include)
- SAP 305931 – Ancillary Revenue Sch 3a – Subject to Refund (Include)

Accruals or estimates in accounts 447, 555, and 565 will be excluded; rather, expenses and revenue will be accounted for in the months that they are incurred. Adjustments shall be made to Actual EBAC that are consistent with Commission accepted or ordered adjustments, or adjustments called out in a stipulation or settlement agreement, as ordered in the most recent general rate case, major plant addition case, or other case where Base EBAC are approved.

EBA DEFERRAL: The monthly EBA Accrual (positive or negative) is determined by calculating the difference between Base NPC and Actual NPC as is described below.

Through May 31, 2016:

$$EBA\ Deferral_{Utah, month} = [(Actual\ EBAC_{month/MWh} - Base\ EBAC_{month/MWh}) \times Actual\ MWH_{Utah, month}] \times 70\%$$

Starting June 1, 2016 through December 31, 2019:

$$EBA\ Deferral_{Utah, month} = [(Actual\ EBAC_{month/MWh} - Base\ EBAC_{month/MWh}) \times Actual\ MWH_{Utah, month}] \times 100\%$$

Where:

$$Actual\ EBAC_{month/MWh} = (NPC_{Utah, month, actual} / Actual\ MWh_{Utah, month}) + (WR_{Utah, month, actual} / Actual\ MWh_{Utah, month})$$

$$Base\ EBAC_{month/MWh} = (NPC_{Utah, month, base} / Base\ MWh_{Utah, month}) + (WR_{Utah, month, base} / Base\ MWh_{Utah, month})$$

$NPC_{Utah, month}$ = Total Company NPC for the month multiplied by the appropriate allocation factors from the most recent general rate case, major plant additions case, or other case where Base EBAC are approved.

$WR_{Utah, month}$ = Total Company Wheeling Revenue for the month multiplied by the appropriate allocation factors from the most recent general rate case, major plant additions case, or other case where Base EBAC are approved.

(continued)

Issued by authority of Report and Order of the Public Service Commission of Utah in Docket No. 175-035-013

FILED: ~~October 20, 2015~~ December 19, 2017

EFFECTIVE: ~~November 1, 2015~~ May 1, 2017

P.S.C.U. No. 50

First-Second Revision of Sheet No. 94.10
Canceling ~~Original-First Revision of~~ Sheet No. 94.10

ELECTRIC SERVICE SCHEDULE NO. 94 – eContinued

EBA Deferral Account Balance: the monthly EBA Account Balance will be calculated as follows:

$$\text{EBA Deferral Account Balance}_{\text{current month}} = \text{Ending Balance}_{\text{previous month}} + \text{Deferral}_{\text{current month}} \\ - \text{EBA Revenue}_{\text{current month}} + \text{EBA Carrying charge}_{\text{month}}$$

EBA CARRYING CHARGE: the EBA Carrying Charge will be calculated and applied to the monthly balance in the EBA Deferral Account as follows:

$$\text{EBA Carrying Charge}_{\text{month}} = [\text{Ending Balance}_{\text{previous month}} + (\text{Deferral}_{\text{current month}} \times 0.5) \\ - (\text{EBA Revenue}_{\text{current month}} \times 0.5)] \times 0.5\%$$

EBA RATE DETERMINATION: Annually, on the EBA Filing Date, Rocky Mountain Power shall file with the Commission an application for establishment of an EBA rate to become effective on the EBA Rate Effective Date of that year. The EBA Deferral Account Balance as of December 31 shall be allocated to all retail tariff rate schedules and applicable special contracts based on the rate spread approved by the Commission. The new EBA rate will be determined by dividing the EBA Deferral Account Balance allocated to each rate schedule and applicable contract by the schedule or contract forecasted Power Charge and Energy Charge revenues. The EBA rate will be a percentage increase or decrease applied to the monthly Power Charges and Energy Charges of the Customer's applicable schedule or contract as set forth in the schedule.

AUDIT PROCEDURES: All items recorded in the EBA Balancing Account are subject to regulatory audit and prudence review. The Division of Public Utilities will complete its audit according to the EBA Procedural Schedule.

(continued)

Issued by authority of Report and Order of the Public Service Commission of Utah in Docket No. ~~16~~17-035-01

FILED: ~~October 11, 2016~~ December 19, 2017

EFFECTIVE: ~~November 1, 2016~~ May 1, 2017

REDACTED

Rocky Mountain Power

Docket No. 17-035-01

Witness: Dana M. Ralston

BEFORE THE PUBLIC SERVICE COMMISSION
OF THE STATE OF UTAH

ROCKY MOUNTAIN POWER

REDACTED

Response Testimony of Dana M. Ralston

December 2017

1 **Q. Please state your name, business address, and present position with PacifiCorp**
2 **d/b/a Rocky Mountain Power (“the Company”).**

3 A. My name is Dana M. Ralston. My business address is 1407 West North Temple, Suite
4 210, Salt Lake City, Utah 84116. My title is Senior Vice President of Thermal
5 Generation and Mining.

6 **Q. Mr. Ralston, have you previously submitted direct testimony on behalf of Rocky**
7 **Mountain Power in this proceeding?**

8 A. No.

9 **Q. What is the purpose of your response testimony in this proceeding?**

10 A. I respond to the direct testimony of Mr. Philip DiDomenico and Mr. Dan F. Koehler of
11 Daymark Energy Advisors, Inc. (“Daymark”) and the Technical Report on the Energy
12 Balancing Account (“EBA”) Audit for Rocky Mountain Power for Calendar Year 2016,
13 filed on behalf of the Division of Public Utilities of the State of Utah (“DPU”).
14 Specifically, I explain why the purchase of the Joy longwall by Bridger Coal Company
15 (“BCC”) was prudent and how acquisition of the longwall was expected to benefit BCC
16 operations and ultimately customers. I discuss the unexpected and complex geologic
17 conditions encountered in the 14th Right longwall panel and subsequent recovery
18 efforts. I demonstrate why Daymark’s allegations stating the Company and BCC were
19 imprudent in the management of the mine are unfounded. I also explain and support
20 the actions taken by the Company that demonstrate its prudence with respect to the
21 proposed generation plant outage adjustments identified in the audit report.

22 **QUALIFICATIONS**

23 **Q. Briefly describe your education and professional experience.**

24 A. I have a Bachelor of Science Degree in Electrical Engineering from South Dakota State
25 University. I am currently PacifiCorp’s Senior Vice President of Thermal Generation
26 and Mining. Prior to November 2017, I was the Vice President of Coal Generation and
27 Mining since March 2015, and Vice President of Generation from January 2010 to
28 March 2015. For 29 years before that, I held a number of positions of increasing
29 responsibility within Berkshire Hathaway Energy’s Generation organization, including
30 the plant manager position at the Neal Energy Center, a 1,600 megawatt generating
31 complex. In my current role, I am responsible for operating and maintaining
32 PacifiCorp’s coal- and gas-fired generation fleet, coal fuel supply, and mining.

33 **Q. Have you testified in previous regulatory proceedings?**

34 A. Yes. I have testified in proceedings before the utility commissions in Utah, Oregon,
35 Washington, and Wyoming.

36 **SUMMARY OF TESTIMONY**

37 **Q. Please summarize your testimony.**

38 A. My testimony:

- 39 • Explains why the Joy longwall was purchased by BCC;
- 40 • Provides information demonstrating the strategic evaluation, purchase, and
41 implementation of the Joy longwall at BCC was prudent and occurred only after
42 technological and geological assessments were complete;
- 43 • Highlights actions taken by BCC to inform operators of challenging geologic
44 conditions in the 14th Right longwall panel, providing Joy longwall on-site set up

- 45 and operating direction with JoyGlobal representatives prior to commencing
46 operations, and classroom and hands-on Joy longwall training with JoyGlobal;
- 47 • Provides background information showing that the Joy longwall performance was
48 exceeding expectations before approaching cross-cut 18 in the 14th Right longwall
49 panel;
 - 50 • Discusses unexpected geologic conditions encountered near cross-cut 17, the
51 complexity and severity of those conditions and actions taken by BCC in an attempt
52 to resume coal production activities;
 - 53 • Describes longwall recovery efforts and demonstrates that all recovery efforts
54 deemed safe and reasonable were exhausted prior to the abandonment of the
55 longwall;
 - 56 • Discusses observations detailed in the root cause analysis investigative report
57 prepared by BCC;
 - 58 • Demonstrates that Daymark’s allegations the Company was imprudent in the
59 management of the mine are unfounded.
 - 60 • Demonstrates the Company was prudent in managing the plant resources, and the
61 outage adjustments identified in the audit report are unwarranted.

62 **BRIDGER COAL COMPANY**

63 **Q. Please describe BCC.**

64 A. BCC is a joint venture that mines coal at the Jim Bridger coal mine for delivery to the
65 adjacent Jim Bridger power plant. PacifiCorp (through its wholly-owned subsidiary
66 Pacific Minerals, Inc.) owns a two-thirds interest in BCC, and Idaho Power Company
67 (through its wholly-owned subsidiary Idaho Energy Resources Co.) owns a one-third

68 interest. PacifiCorp and Idaho Power Company have the same ownership percentages
69 in the Jim Bridger plant as in BCC. BCC began supplying coal extracted from surface
70 mining operations to the Jim Bridger plant in 1974.

71 **Q. When did BCC begin development of the underground mine?**

72 A. In 2004, BCC began developing the underground mine infrastructure using continuous
73 miner equipment.

74 **Q. Did the Company's original underground mine plan incorporate longwall mining
75 techniques?**

76 A. Yes. Longwall mining is highly productive and provides a cost benefit relative to
77 continuous mining operations. In longwall mining operations, continuous miner section
78 equipment develops entries that provide access to large blocks of coal referred to as
79 panels that can be efficiently extracted with longwall mining equipment. A contract was
80 signed with DBT Group¹ in 2005 to construct the longwall that would be used at the
81 mine. Longwall operations using the DBT longwall began in March 2007.

82 **THE JOY LONGWALL ACQUISITION**

83 **Q. If BCC had the DBT longwall, why did BCC purchase the Joy longwall?**

84 A. As mining at BCC's underground mine continued, extensive surface coal exploration
85 programs along with detailed in-mine geologic mapping confirmed that coal seam
86 thickness and coal seam structural geology variability increased. The Joy longwall,
87 manufactured by JoyGlobal,² had been in operation at the Company's Deer Creek Mine
88 in Central Utah which was shuttered in early 2015. The Joy longwall would therefore

¹ DBT Group was a German based underground mining equipment manufacturer that was acquired by Bucyrus International Inc. in 2007 which was subsequently purchased by Caterpillar Inc. in 2010.

² JoyGlobal Inc. is a Wisconsin based mining equipment manufacturer that was acquired by Komatsu Ltd. in 2017.

89 be available at BCC provided that technical analyses concluded the longwall could
90 operate effectively there. The primary advantage the Joy longwall had over the DBT
91 longwall was that the Joy longwall could operate more effectively at thinner coal seam
92 thicknesses than the DBT. The effective operating range of the DBT longwall extends
93 from 10.5 to 12 feet while the effective operating range of the Joy longwall extended
94 from seven to 10 feet. The lower operating height specification of the Joy longwall
95 would increase the flexibility of the longwall to overcome challenges of changes in
96 coal seam thickness and variations in the structural geology. The flexibility provided
97 by the Joy longwall would also decrease the run-of-mine ash content of coal produced.

98 **Q. Prior to selling the Joy longwall to BCC, did the Company complete an evaluation**
99 **to determine whether the Joy longwall could successfully operate in the known**
100 **geologic conditions at BCC?**

101 A. Yes. The Company and BCC's technical groups (engineering and geology) with the
102 assistance of Malecki Technologies Inc. ("MTI"), a geotechnical engineering
103 consultant, and JoyGlobal evaluated the potential benefits of using the Joy longwall at
104 BCC beginning in early 2014 and concluded in the summer of 2015 that the Joy
105 longwall would provide operating and costs benefits to BCC. This evaluation directly
106 compared specifications of each longwall system (the DBT and the Joy) and determined
107 the potential viability of the Joy longwall system related to BCC's coal reserve. Key
108 specification factors (shield capacity, shield canopy tip-to-face and floor pressure) were
109 compared between the DBT longwall and the Joy longwall. The group concluded the
110 Joy longwall would provide operational benefits with regard to tip-to-face, floor
111 pressure, and range of operating cutting height. In addition, the Company evaluated the

112 effective remaining life of the Joy system (number of cycles), and concluded that the
113 Joy longwall could be used by BCC through the expected life of the underground mine.

114 **THE JOY LONGWALL - 14TH RIGHT**

115 **Q. Did the Company develop a specific geologic longwall report for the 14th Right**
116 **longwall panel?**

117 A. Yes. Consistent with established geologic procedures, BCC develops a comprehensive
118 geologic report for each longwall panel. The report, included as Confidential Exhibit
119 RMP___(DMR-1R), documents geologic, hydrologic, geotechnical, and coal quality
120 projections of each longwall panel. To develop the report, Company and BCC geologic
121 staff conduct detailed geologic in-mine mapping of each gateroad and the setup entries.
122 Data mapping includes; coal thickness, coal quality—channel samples, roof and floor
123 geology, hydrologic characteristics, general mining conditions, and geotechnical
124 information. In addition, extensive surface exploration data is used to detail mid-panel
125 geologic trends and longwall extraction conditions.

126 **Q. Was the report based on comprehensive data that was analyzed and presented by**
127 **professional experts?**

128 A. Yes. The longwall panel reports are prepared by licensed professional geologists
129 experienced in underground coal mining geology. Reports are distributed to
130 management and discussed with longwall supervisors.

131 **Q. Were the contents of the 14th Right longwall report discussed with mine**
132 **management and longwall section supervisors?**

133 A. Yes. The report was provided to and discussed with mine personnel in advance of
134 mining the longwall panel. In addition, the BCC mine geologist visited the longwall

135 face 22 times from September 3, 2015 to December 17, 2015 to conduct surveys. The
136 surveys document coal thickness, coal quality, roof and floor geology, hydrologic
137 characteristics, and general mining conditions. During these surveys, the geologist
138 discusses the results of the surveys with the shearer operator, longwall coordinator and
139 the foreman. Survey results are communicated to mine management.

140 **Q. Did known gaps or voids exist in the data used to develop the detailed longwall**
141 **mining report for the 14th Right panel?**

142 A. No. BCC conducted extensive geologic investigations prior to the 14th Right
143 extraction, including extensive surface exploration drilling to define regional and in-
144 panel thickness trends and lithologic characteristics of the roof and floor and in-mine
145 detailed geologic mapping of all entries to enhance the regional trends data. All of the
146 data from exploration and in-mine mapping was incorporated into the overall geologic
147 model to predict general mining conditions.

148 **Q. You state there were no known gaps or voids in the data for developing the report.**
149 **Does the Company have the ability to determine with 100 percent certainty all**
150 **existing localized geologic conditions?**

151 A. No. While the Company conducts extensive drilling and core sampling in the coal
152 reserve, it is impractical and unreasonable to drill to determine with 100 percent
153 certainty all existing geologic conditions. The industry standard consists of drilling
154 holes every quarter of a mile. The drill holes at BCC are approximately every eighth of
155 one mile in the location in question, which is significantly above the industry standard.

156 **Q. Based on the information available to BCC relative to specific geologic conditions**
157 **in the area and the favorable operational evaluation developed by JoyGlobal, did**
158 **BCC have confidence the 14th Right longwall panel could be successfully mined**
159 **using the Joy longwall?**

160 A. Yes. BCC personnel with assistance of MTI, geotechnical engineering consultant, and
161 JoyGlobal concluded the Joy longwall would provide operating benefits at BCC,
162 especially with the longwall's ability to operate in lower coal seam heights than the
163 DBT longwall. A detailed 14th Right longwall report using the data previously
164 mentioned was developed and discussed with mine personnel. Based on the 14th Right
165 report, BCC determined that the Joy longwall could safely and effectively mine this
166 panel.

167 **Q. What steps did the Company take to ensure the mining crews were adequately**
168 **trained on the Joy longwall operation?**

169 A. Although several individuals at BCC had extensive operational experience with the Joy
170 longwall at the Deer Creek mine, JoyGlobal was on site starting August 25, 2015 to
171 assist with the longwall set up and provide technical direction to the crews on the
172 operation of the longwall prior to the longwall commencing operations on
173 August 31, 2015. In addition, JoyGlobal conducted classroom and hands on Joy
174 longwall training while the longwall was in actual operation for mine personnel during
175 September 12, 2015 through October 9, 2015 to ensure longwall section employees
176 could confidently operate the Joy longwall. Finally, operational manuals for major
177 longwall section components were available as a reference for employees.

178 **Q. Please describe the unexpected localized geologic features that impeded the Joy**
179 **longwall's ability to move or retreat after BCC prudently evaluated geological and**
180 **geo-technical conditions in the area and Joy longwall operating parameters.**

181 A. As the mine approached cross-cut 18 in the 14th Right longwall panel in early to mid-
182 December 2015, the Joy longwall intercepted two unexpected geologic features
183 simultaneously, a mid-panel coal seam thinning trend and severe geologic structural
184 rolls in the floor. The detailed mine map included as Exhibit RMP___(DMR-2R)
185 projected a coal seam thickness of approximately nine feet in this area, which is well
186 within the operating limits of the Joy longwall. However, the coal seam unexpectedly
187 thinned to approximately six and a half feet thick at mid-face. The combination of the
188 rapidly thinning coal seam and severity of the multi-dimensional structural rolls (shown
189 in Exhibits RMP___(DMR-3R) and RMP___(DMR-4R)) in the floor forced equipment
190 operators to alter the mining horizon to limit contact with the hard sandstone floor. The
191 severity of the structural rolls increased as the longwall retreated towards cross-cut 17.
192 The structural rolls were both parallel and perpendicular to the face. In addition, the
193 hard sandstone floor, normally approximately two feet thick, thinned at the crowns of
194 the structural rolls to less than one foot thick. The combination of the thinning coal
195 seam, thinning sandstone floor, and severity of the structural rolls exceeded the
196 capacity of the shearer to maneuver through the coal face without trimming into the
197 hard sandstone floor and the roof. As the crews struggled to navigate through these
198 difficult conditions, the hard sandstone crown was cut, which exposed the incompetent
199 paleosol or claystone under the hard sandstone floor.

200 **Q. Please explain what corrective actions BCC took to navigate through the complex**
201 **and rapidly changing geologic conditions.**

202 A. Crews attempted to alter the longwall mining horizon by changing the cutting angle of
203 the shearer to overcome the structural rolls. Longwall crews continuously evaluate
204 mining conditions encountered (coal seam thickness trends and structural features)
205 along the face and attempt corrective measures to mitigate the changing mining
206 environment. At times during mid-December, longwall crews were able to alter the
207 mining horizon to effectively stay within the coal seam and limit incidental contact
208 with the hard sandstone floor.

209 **Q. Briefly describe operating limitations that longwall section equipment has relative**
210 **to rapidly changing geological conditions.**

211 A. The longwall is a large, highly mechanized piece of equipment with some flexibility to
212 navigate various geologic features including changes in seam thickness and structural
213 changes. However, in the case of the 14th Right longwall panel, the severity of the rolls
214 in conjunction with the thinning seam exceeded the capacity of the shearer to navigate
215 through without trimming both the hard sandstone floor and the roof. When the rolls
216 are extremely severe, as in the case of 14th Right, as the shearer traverses along the face
217 of the coal seam, the roof and floor must sometimes be removed for clearance
218 especially at the transition zones of the structural rolls.

219 **Q. Please describe the operational and production performance of the Joy longwall**
220 **prior to December 2015.**

221 A. The Joy longwall exceeded expectations in terms of productivity and was consistent
222 with projected coal quality. For the period from startup on August 31, 2015 to the end

223 of November 2015, productivity of the Joy longwall exceeded each of the measured
224 metrics (budgeted tonnage by ■ percent, budgeted feet advanced by ■ percent,
225 budgeted tons/shift by ■ percent and budgeted feet/work shift by ■ percent). Quality
226 of coal produced from September through November from the Joy longwall (14th Right
227 panel) averaged 12 percent ash which was below the Jim Bridger plant target delivery
228 specification of ■ percent ash.

229 **Q. Did the Company and BCC investigate the circumstances surrounding the**
230 **abandonment of the Joy longwall?**

231 A. Yes. The Company and BCC completed an in-depth root cause analysis and prepared
232 the report titled “FINAL Report of Investigation – Joy Longwall 14th Right
233 Investigation” dated October 13, 2016 shortly after the decision was made to stop the
234 longwall recovery efforts.

235 **Q. Please highlight the findings in the root cause analysis report.**

236 A. Notably, the report was compiled after individual interviews with longwall section and
237 mine management employees occurred. Several combined root cause analysis meetings
238 were held with BCC, Idaho Power, and PacifiCorp representatives. Information
239 gathered during this process is contained in the report. The report identified the
240 following seven items as reasons contributing to the unexpected Joy longwall event:

- 241 1. The coal seam thickness thinned and a mid-face structural roll was encountered
242 simultaneously.
- 243 2. Although crews were trained extensively and several had previously operated
244 this longwall at the Deer Creek mine, operating the Joy longwall in the unique
245 geological conditions at BCC was new to all employees.

- 246 3. Shearer operators cut into the hard sandstone floor to control roof caving and
247 minimize ash contamination and did not adequately communicate issues to
248 management employees.
- 249 4. The thinning coal seam forced the shearer operator to cut the crown that was
250 caused by a pronounced roll to maintain the cutting height required to allow the
251 shearer to pass the shields. This resulted in the shearer exposing the incompetent
252 claystone.
- 253 5. Longwall crews did not follow consistent operating practices (spotting shields
254 and climbing out of the claystone).
- 255 6. The crews had to manually remove material that had fallen from the roof on the
256 face conveyor (pan) resulting in excessive downtime.
- 257 7. While equipment was maintained properly, significant unplanned mechanical
258 downtime occurred.

259 The report also discusses challenges associated with geology, hydrology, scheduling
260 adjustments and a reduced available workforce driven by the holiday period, significant
261 unexpected mechanical downtime, inconsistent operating practices and
262 communication, and the absence of written procedures for cutting the hard sandstone
263 floor and catching top rock.

264 **Q. Daymark noted, among other concerns, that the lack of a steady retreat rate at the**
265 **Bridger mine was a factor that contributed to the Joy longwall failure. Please**
266 **explain why the longwall could not move at a steady rate.**

267 A. During the timeframe of December 23, 2015 to December 29, 2015, the underground
268 mine experienced significant operational issues such as roof flushing, frozen stacking

269 tubes and mechanical problems that prevented the longwall from moving. Most
270 notably, longwall crews were faced with rocks flushing or falling from the roof at the
271 longwall mine face due to the poor roof conditions. The flushing caused downtime and
272 slowing of the mining process in order to manually move rocks off of the panline to
273 restart the chain conveyor. The rocks were then moved back into the pan and conveyed
274 out of the mine. The flushing of the roof was also pushing the shearer into the floor.
275 Additionally, the stacking tubes at the surface of the underground mine were frozen
276 solid with coal for a time due to extremely cold weather. The frozen stacking tubes
277 prevented the conveyor system from operating effectively.

278 **Q. Do Daymark advisors and consultants have expertise or experience in coal mining**
279 **operations or consulting?**

280 A. No. As stated in their testimony and report, while Daymark has extensive expertise in
281 utility operations they do “not have specific expertise in coal mining operations.”³
282 Additionally, although “sound operations are equally applicable across a multitude of
283 industries”⁴, the communication and documentation procedures for electric
284 transmission, distribution, and generation are significantly different than those faced in
285 the underground mining environment.

286 **Q. Please give further details about the eight items listed in the “Methods to Prevent**
287 **a Reoccurrence” section of the root cause analysis report.**

288 A. As described below, the majority of the items discussed in the “Methods to Prevent a
289 Reoccurrence” section emphasize a need to improve existing practices and/or
290 procedures as opposed to an absence of procedures that may or may not be standard in

³ Daymark Energy Advisors EBA Audit Report, page 4.

⁴ Ibid., page 4.

291 the industry.

- 292 1. Written longwall standards. Formal written longwall procedures have been in-
293 place since longwall operations began at the underground mine in March 2007.
294 Additionally, written standards were formalized in August 2017 and continue
295 to be refined.
- 296 2. Additional geologic training. Historically, geologic longwall reports were
297 developed and provided to management employees. Maps identifying coal
298 seam thickness contours, roof lithology, drilling data, etc. were provided to all
299 longwall section employees and verbal discussions occurred on an as needed
300 basis. However, a written Longwall Standards document was developed after
301 the Joy longwall event that requires all longwall section employees meet with
302 Company geologists for training prior to coal extraction from a new longwall
303 panel and as changing geologic conditions dictate.
- 304 3. Expanded geologic operating plans. Historically, operating plans were
305 developed and discussed with all longwall section employees and mine
306 management personnel based on discussions and input from Company
307 geologists. However, the Longwall Standards document formalizes the
308 communication process (both verbal and written) between operators, longwall
309 section staff (management and union), and geologists.
- 310 4. Shearer operator communication. Historically, shearer operators have verbally
311 communicated with each other, foreman and geologists regarding operational
312 issues. However, the Longwall Standards document formalized the
313 communication process to be both verbal and written.

- 314 5. Shift change communication. Historically, operators verbally communicated
315 operational and geological conditions to the on-coming shift and prepared
316 written production reports. The written production reports were not always
317 reviewed by on-coming shift supervisors. The Longwall Standards document
318 requires operators and supervisors to provide written reports to on-coming
319 crews to ensure complete and accurate information is provided to shift
320 supervisors.
- 321 6. Supervisor documentation. Historically, supervisors have evaluated changing
322 face conditions, made operating adjustments and verbally communicated
323 changes to other longwall employees. The Longwall Standards document
324 requires supervisors to document changing conditions in production reports.
- 325 7. Mechanical availability. The referenced report states that “while equipment was
326 being maintained properly, unplanned mechanical downtime resulted in the
327 inability to run the longwall during the initial timing of the event”. The
328 Company recognized that not having a spare part contributed to several hours
329 of downtime during the longwall event. The Company has reviewed and
330 updated the critical spare longwall parts list to mitigate mechanical delays and
331 the Longwall Standards document requires all longwall employees to report
332 mechanical problems to maintenance personnel immediately to ensure timely
333 repairs occur.
- 334 8. Adequate staffing levels. Historically, operating shifts at the mine were reduced
335 from two to one shift per operating day during extended holiday periods. This
336 practice did not create operational issues prior to the 14th Right longwall event.

337 In December 2015, the Company followed call-out procedures contained in the
338 collective bargaining agreement, but represented employees declined to work
339 unscheduled shifts. Therefore, the Company is now scheduling more employees
340 to work during holiday periods when conditions warrant, and attempts to
341 manage coal production activities to avoid longwall moves over extended
342 holiday periods. In addition, the Company signed a Memorandum of Agreement
343 with the union to provide enhanced workforce coverage during longwall move
344 periods.

345 **Q. Why did the Company perform an investigation?**

346 A. The Company considered it important to understand the events and issues that resulted
347 in the abandonment of the Joy longwall and to develop actions to prevent a future
348 occurrence. While the Company's actions were prudent with respect to the purchase,
349 use, and recovery attempts of the longwall the root cause analysis was done with a
350 critical view in an effort to continuously improve our operations.

351 **JOY LONGWALL RECOVERY EFFORTS**

352 **Q. Please summarize Joy longwall recovery efforts.**

353 A. The longwall recovery efforts were conducted over a nine month period using
354 traditional and state-of-the art technologies. Not all the methods discussed and
355 evaluated were attempted due to safety and operational concerns. Longwall recovery
356 efforts were discussed with experienced mine personnel, industry experts, vendors and
357 the Mine Safety and Health Administration ("MSHA"). Recovery methods used
358 included:

- 359
- Pumped grout from the surface to an area above the shields to consolidate roof

- 360 material.
- 361 • Pumped a chemical into the floor to fill voids and increase compressive
- 362 strength.
- 363 • Pumped various types of foams, chemicals, and grouts above and below the
- 364 shields from the longwall face to fill voids and consolidate roof material.
- 365 • Installed wooden crib blocks underneath the shields to stabilize floor
- 366 conditions.
- 367 • Pumped various types of glue into the face to consolidate and stabilize face
- 368 conditions.
- 369 • Installed one inch by ten foot long re-bar at an angle near the top of the shields
- 370 to provide additional structural face support.
- 371 • Horizontally drilled holes under the shields and face conveyor and then
- 372 circulated a refrigerant to freeze and stabilize the floor.
- 373 • Took taper cuts with the shearer in the headgate area to reduce abutment
- 374 pressures on the face.
- 375 • Constructed plywood beams to form bridges to distribute shield floor loading.

376 **Q. Did BCC solicit input from industry experts to ensure all reasonable recovery**
377 **techniques were considered?**

378 A. Yes. BCC solicited input and services from industry experts, contractors, mine
379 operators and MSHA in an effort to safely and effectively recover the Joy longwall and
380 resume production activities. Please refer to Confidential Exhibit RMP___(DMR-5R)
381 for the timeline of recovery efforts and industry experts consulted.

382 **Q. At what point and why did the Company determine the Joy longwall was to be**
383 **abandoned in place?**

384 A. On October 7, 2016 the Company made the decision to stop further efforts to recover
385 the longwall due to severe roof failure around several shields. The roof failure resulted
386 in an unsafe condition that was too dangerous for people to continue recovery efforts.

387 **Q. In your opinion, was the Company prudent in its actions taken for the Joy**
388 **longwall issue either in its operation or in the recovery efforts?**

389 A. Yes. The Company was diligent in its evaluation of the use of the Joy longwall, it's
390 evaluation of the predicted mining conditions, the training of Company employees, and
391 the prudent efforts to recover the longwall using several techniques and outside
392 resources. Daymark's review focuses on the Company's root cause analysis and takes
393 parts of that critical review to make their determination. Daymark does not have mining
394 expertise and did not appear to look at the incident with the Joy Longwall in its entirety.
395 When all the information is taken into account the Company's actions were prudent
396 and recovery of the Joy longwall expenses should be recovered.

397 **GENERATION PLANT OUTAGE ADJUSTMENTS**

398 **Overview of plant outages**

399 **Q. Have you reviewed the Daymark report on plant outages and do you agree?**

400 A. Yes. I have reviewed the report, and I do not agree with Daymark's generalization that
401 the Company's involvement with third-party contractors and vendors as "casual". The
402 Company takes its responsibilities very seriously and manages contractors diligently.
403 Daymark assumes that if a contractor makes a mistake it means the Company did not
404 manage that contractor prudently. This expectation is unrealistic and unfair. The

405 Company closely monitors its contractors, but cannot be expected to micromanage
406 every task made by a contract employee. Doing so would require the Company to have
407 as many people supervising the contractors as the contractor has employees. The
408 standard Daymark suggests is simply unreasonable. The Company manages its thermal
409 generation fleet very effectively to the benefit of our customers. In 2016, the
410 Company's thermal fleet performed better than the NERC average, with an equivalent
411 availability factor (EAF) of 90.69 percent compared to the NERC average in 2015 of
412 82.24 percent⁵. In the following testimony, I explain the specifics around each outage
413 Daymark recommends disallowing.

414 **Colstrip Unit 3 Outage**

415 **Q. Do you agree with the Daymark review and recommendation related to the**
416 **Colstrip Unit 3 Outage? If not, why not?**

417 A. No. Daymark claims that the Company demonstrated a lack of urgency by waiting six
418 years to fully address a problem. Based on the extent of the damage identified during
419 the 2011 inspections, the operator of the Colstrip plant came up with a plan to address
420 the issues in 2014, during the next scheduled outage, and re-inspect the area with the
421 anticipation that an additional project would need to occur in 2017 due to continued
422 erosion in different areas of the economizer. The tube that failed was inspected in 2014,
423 and the wall thickness of the tube was adequate at that time. The plan was to re-inspect
424 this area in 2017 to ensure the tubes were within acceptable wall thickness and replace
425 any tubes that were not.

426 The Boiler Circulating Water Pump ("BWCP") portion of this outage was due

⁵ 2015 NERC data was used because the 2016 data is not available.

427 to an equipment failure that occurred during the outage, and its failure was not due to
428 imprudent practices by the Company. One of the BWCPs experienced a motor failure
429 during startup of the unit after the tube leak repair was complete. Due to this failure,
430 the outage was extended to repair the BWCP. This event had no connection with the
431 tube leak and should not be included in any lost production calculations.

432 **Q. How is the Company prudent in its participation of the Colstrip plant?**

433 A. Rocky Mountain Power is an active owner of its jointly-owned plants where the
434 Company is a minority partner. The Company dedicates a full-time employee to
435 manage the interaction with all the jointly-owned plants. This person, along with others,
436 has daily contact with the plants and raises issues with the plants on matters of
437 operations, budget, and planning. With this involvement the Company represents the
438 best interests of our customers.

439 **Q. What is your recommendation to the Commission with respect to the adjustment
440 proposed by Daymark?**

441 A. The Colstrip Unit 3 outage was a result of material failure and not the lack of prudently
442 established procedures and practices. The Company corrected known deficiencies in as
443 timely and prudently as possible. I respectfully recommend that the Commission reject
444 the adjustment proposed by Daymark.

445 **Colstrip Unit 4 Outage**

446 **Q. Do you agree with the Daymark review and recommendation relating to the
447 Colstrip Unit 4 Outage? If not, why not?**

448 A. No. Daymark testifies that if the #11 bearing leak resulted from failure to remove
449 material after an oil flush, the Company should be held accountable. The bearing leak

450 occurred from a one inch valve that was in place for the oil flush. The leak was located
451 at the valve connection threads to the pipe. The location where the valve was installed
452 originally had a pipe cap and a one-inch valve was installed for the oil flush. After the
453 oil flush was completed the valve was closed and not removed. This is not a failure to
454 remove material because the valve performed the same function as the pipe cap. The
455 leak location could have occurred if there were a valve or a pipe cap at this location.
456 The leak resulted from an equipment malfunction not a procedural failure.

457 **Q. What is your recommendation to the Commission with respect to the adjustment**
458 **proposed by Daymark?**

459 A. The Colstrip Unit 4 outage was a result of a leak due to equipment failure and not
460 procedural failure on the part of the Company or contractors. I respectfully recommend
461 the Commission reject the adjustment proposed by Daymark.

462 **Dave Johnston Unit 4 Outage**

463 **Q. Do you agree with the Daymark review and recommendation relating to the Dave**
464 **Johnston Unit 4 Outage? If not, why not?**

465 A. No. The condenser tube sheet RTV repair was entirely effective from 1988 until June
466 2009, with only minor RTV repairs throughout that time period. In June 2009, the first
467 significant leak associated with the RTV occurred. In 2009, the Company began the
468 process to permanently repair the condenser damage by replacing the tubes during a
469 major outage scheduled to occur in 2020. In March 2010, a second significant leak
470 occurred followed by a third significant leak in May 2014. It was determined that a
471 protective tube sheet coating, which was installed in 1987, had significantly
472 deteriorated. The deteriorated protective coating prevented proper adhesion of RTV to

473 the tube sheet making further RTV repairs of the tube sheet difficult. The repair was
474 completed after the unit had been online for eight days. Prior to the end of 2014,
475 engineering had reviewed potential solutions, received quotations, and determined that
476 epoxy cladding the tube sheet was the most economical solution. The epoxy cladding
477 was scheduled for installation during the 2017 planned unit overhaul due to the eight
478 day installation time. In March 2016, another leak occurred and the epoxy cladding was
479 installed in one side (half) of the condenser during derated operation. The other side
480 (half) was completed as planned during the scheduled overhaul which began March
481 2017.

482 **Q. Do you believe an appropriate standard of prudence was exercised by the**
483 **Company in its operation of Dave Johnston Unit 4?**

484 A. Yes. The decision by the Company to replace the 26 year old RTV with an epoxy
485 coating during a planned unit overhaul was prudent and in the best interests of
486 customers.

487 **Q. What is your recommendation to the Commission with respect to the adjustment**
488 **proposed by Daymark?**

489 A. The lost generation was a result of a leak due to equipment failure and not procedural
490 failure on the part of the Company or contractors. I respectfully recommend that the
491 Commission reject the adjustment proposed by Daymark.

492 **Gadsby Units 4, 5 and 6**

493 **Q. Do you agree with the Daymark review and recommendation relating to the**
494 **Gadsby gas pipe line outage? If not, why not?**

495 A. No. Daymark asserts that the Company demonstrated lack of a focus on proper planned

496 maintenance for this line. The Company tested the cathodic protection in 2014 and
497 2015, prior to the failure, with no indication of a system problem. The leak in question
498 was discovered during a weekly gas leak check which prompted shutdown of the
499 system due to safety concerns. The pipe was exposed and found in very good condition
500 along the majority of the pipe including where the cathodic protection was connected.
501 However corrosion and pitting was found at elbows and joints where the pipe was
502 coated or wrapped in the field after installation. The pipe was pressure tested with
503 nitrogen after being exposed and no leak was found. Questar Gas also assisted in
504 ground monitoring to help find the leak. The leak was assumed to be a very small pin
505 hole in the vicinity of the highest ground level gas concentration between Unit 4 and 5
506 stacks. After approximately 50 percent of the pipe was exposed and no definitive leak
507 had been found it was determined the most prudent course of action was to replace the
508 pipe with above ground piping due to the uncertainty of the location of the leak and
509 premature pitting found in isolated areas of the pipe. This avoided additional excavation
510 of the remaining pipe and any future incidents due to the pitting discovered.

511 **Q. Do you believe that the duration of the outage was excessive?**

512 A. No. The Company initiated a plan immediately to install temporary piping above
513 ground to allow for a well-designed and cost-effective plan to replace the underground
514 piping. The temporary piping was fabricated in sections away from the site while
515 underground gas monitoring was taking place. The Company was very effective in
516 installing the temporary piping in a safe, expeditious and cost effective manner.

517 **Q. What is your recommendation to the Commission with respect to the adjustment**
518 **proposed by Daymark?**

519 A. The Company's response to the Gadsby gas pipe line outage was prudent. I respectfully
520 recommend that the Commission reject the adjustment proposed by Daymark.

521 **Gadsby Unit 6 Outage**

522 **Q. Do you agree with the Daymark review and recommendation relating to the**
523 **Gadsby Unit 6 outage? If not, why not?**

524 A. No. Daymark testified that this was a Company failure to follow industry practices,
525 recommending a disallowance. The Company witnessed the manufacture and testing
526 of the exciter at the National Electric Coil ("NEC") shop. This work was completed by
527 NEC not General Electric ("GE"). The shop testing in 2015 met industry standards.
528 The exciter was transported and installed by NEC at the Gadsby site and witnessed by
529 a professionally licensed electrical engineer. The installation met industry standards.
530 The unit operated successfully for several months. Once stationary coils began failing,
531 tests were completed to determine the root cause. GE was brought in to complete
532 extensive testing. Initially, GE thought that the insulation on the coils had deteriorated.
533 However, when a new coil failed, the focus was turned to other areas such as stray
534 currents and the excitation system. Basler Electric Company ("Basler") was later
535 brought in to investigate the voltage regulating equipment. Individual components were
536 tested and eliminated as sources of the failures. NEC was also notified of the issues and
537 they believed it was not the exciter. GE performed an extensive investigation of the
538 failures. Eventually, GE removed the Basler voltage regulator equipment from the
539 circuit and determined the new rotating exciter was imposing an imbalance in the three

540 phase resistance causing the stationary coil to fail. When NEC was notified they
541 initially disagreed based on their shop tests but later agreed once they were on site and
542 confirmed the same tests that GE had completed. As previously stated, the unit met
543 standards in the shop and operated successfully for several months prior to failure. The
544 Company took prudent and reasonable steps to ensure that the equipment was built and
545 installed to industry standards.

546 **Q. Do you believe that the duration of the outage was excessive?**

547 A. No. The Company initiated a plan immediately with NEC to repair the faulty exciter
548 and replace the coils.

549 **Q. Do you believe the Company met its standard of prudence in the management of
550 the Gadsby Unit 6 outage?**

551 A. Yes. The Company prudently prepared and responded to the coil failures by
552 methodically testing components to determine the root cause. Once the root cause was
553 determined to be the exciter, NEC was immediately involved to expeditiously repair
554 the exciter.

555 **Q. What is your recommendation to the Commission with respect to the adjustment
556 proposed by Daymark?**

557 A. The Company's response to the Gadsby Unit 6 outage was prudent. I respectfully
558 recommend that the Commission reject the adjustment proposed by Daymark.

559 **Hermiston Unit 1 Outage**

560 **Q. Do you agree with the Daymark review and recommendation relating to the
561 Hermiston Unit 1 Outage? If not, why not?**

562 A. No. The plant is operated by Hermiston Generating Company ("HGC"). When

563 Hermiston Unit 1 tripped offline on August 2, 2016, it was due to a #11 failed
564 combustion can. At the time, GE determined that the can failure was due to a lack of
565 purge air; further investigation found that the purge air valve was shut. Due to a recent
566 outage, the plant thought that the valve had been inadvertently shut by a contractor
567 since the valve is normally left open. When Hermiston Unit 1 tripped offline on
568 September 18, 2016 with the same issue, GE, the subject matter expert, and HGC
569 performed troubleshooting and noted that the purge air valve was closed again. Based
570 on no contractors being on site and interviews conducted amongst plant personnel, it
571 was determined that the purge air valve shut based on high vibration from the
572 combustion turbine. After the September 18, 2016 incident, GE conducted additional
573 research and confirmed that there have been other instances of valves inadvertently
574 closing as a result of high vibrations causing wear in the actuator and valve, developing
575 excess play to allow it to close easily. Excess play in the purge air valve was not
576 suspected as the cause on August 2 due to contractors recently being on site, since there
577 was no history of issues with the purge air valve, and it was not identified as a possible
578 cause in detailed discussions with the subject matter expert.

579 Daymark states that they believe it is unlikely that normal amounts of vibration,
580 even over many years, would lead to the closing of this valve. This statement is made
581 without basis. GE has multiple documented cases of this very phenomena occurring.

582 **Q. Do you believe an appropriate standard of prudence was exercised by HGC its**
583 **operation of Hermiston Unit 1?**

584 **A.** Yes. As I have described, HGC utilized industry subject matter experts to assist in the
585 troubleshooting and determining the root cause of the combustion can failure. The

586 course of action executed was prudently planned and checked by industry subject
587 matter experts. The specific incident that occurred was the result of unknown material
588 failure, and not the lack of prudent operations. Since the incident, the plant operator
589 has replaced the purge air valve and conducts routine inspections to verify proper
590 operation.

591 **Q. How is the Company prudent in its participation of the Hermiston plant?**

592 A. The Company is an active owner of its jointly-owned plants. The Company dedicates
593 a full-time employee to manage the interaction with all the jointly-owned plants. This
594 person, along with others, has daily contact with the plants and poses questions and
595 raises issues with the plants on matters of operations, budget, and planning. With this
596 involvement the Company represents the best interests of our customers.

597 **Q. What is your recommendation to the Commission with respect to the adjustment
598 proposed by Daymark?**

599 A. The Hermiston Unit 1 outage on September 18, 2016 was the result of failed equipment
600 and not the lack of prudent operations by the Company. I respectfully recommend that
601 the Commission reject the adjustment proposed by Daymark.

602 **Naughton Unit 2 May 2016 Outage**

603 **Q. Do you agree with the Daymark review and recommendation relating to the
604 Naughton Unit 2 outage on May 28, 2016? If not, why not?**

605 A. No. Daymark testified that they believe the Company is responsible for the
606 inappropriate actions of the third parties it hires on behalf of its customers. In this case,
607 the project manager had discussed bearing clearances with the contractor specifically
608 to avoid the type of problem that occurred. The Company uses competitive bidding

609 procedures and selected a qualified vendor based on these policies. In this case, the
610 vendor was the original equipment manufacturer of the equipment. The Company was
611 aware of the critical need for correct bearing clearances and discussed this with the
612 vendor prior to the work. Contracts do not typically cover replacement power costs as
613 stated since they involve a broad range of circumstances and damages that is difficult
614 to identify and quantify. It is anticipated that if contracts were sought that covered these
615 types of damages, the cost of such contracts would increase dramatically and result in
616 increased costs to the Company and customers. The actions the Company takes when
617 procuring services is prudent, within industry practices and in the best interests of the
618 customer.

619 **Naughton Unit 2 June 2016 Outage**

620 **Q. Do you agree with the Daymark review and recommendation relating to the**
621 **Naughton Unit 2 outage on June 6, 2016? If not, why not?**

622 A. No. Daymark claims that a fire should trigger more attention and analysis than what
623 was provided. The response to the fire was appropriate as personnel quickly engaged
624 and extinguished the fire. The fact is that the subsequent investigation by plant and fan
625 company personnel could not identify a definite root cause of the fire. Based on
626 proximity to the coal pile, it is speculated that coal dust could have been the source of
627 this fire but is not conclusive. Daymark also states that despite the company being
628 aware that the area where the fire occurred was prone to coal dust buildup, it waited
629 until a fire occurred to create preventative maintenance work. It was not known prior
630 to the fire that these areas may be prone to coal dust accumulation. The area is not
631 visible during operation. When the similar area on Unit 1 was checked, there was minor

632 buildup of coal dust. The follow-up actions were initiated to help prevent any future
633 issues, but the implication that this was a known and neglected area is not true. Coal
634 dust is a recognized hazard and plant personnel work diligently to mitigate this hazard.

635 **Jim Bridger Unit 4 Outage**

636 **Q. Do you agree with the Daymark review and recommendation relating to the Jim**
637 **Bridger Unit 4 Outage? If not, why not?**

638 A. No. The root cause of the failure of the #41 PA Fan Motor Failure was analyzed.
639 Although a specific root cause analysis was not performed, the mechanism and root
640 cause of the failure was diagnosed. It was found that the source was a lack of lubrication
641 being supplied to the bearing and as a result the bearing failed. When the bearing failed,
642 the rotor contacted the stator. The heat that was generated also melted the aluminum
643 rotor bars. Additionally, during the analysis of the root cause, it was found that a
644 thermal couple had been installed in a location that was reading lower than normal
645 operating temperatures on the bearings. With all the factors analyzed, the Company
646 worked with the motor shop to evaluate the repairs needed to return the motor to a
647 usable state. It was determined that the Company would need to replace the rotor,
648 restack the rotor, rewind the motor, and replace the bearings. It was at this point that
649 the cost of the rebuild and time required for the repairs against the option of replacing
650 the motor. It was decided that the cost to repair the motor and time required was the
651 more costly option and extended loss of generation. After careful consideration, the
652 decision was made to install a new motor and modify the sole plate to allow for the
653 alignment to hold closer tolerances. This option allowed the opportunity to return the
654 unit to full generating capacity much sooner. In addition, the thermal couples were

655 placed in an area that would show accurate temperatures and display to the control
656 room for monitoring. The site glasses were also modified to ensure operators could
657 verify levels to add lubrication as needed. The modifications to the site glass and
658 thermal probes have been expanded to all the PA Fans. With this analysis and
659 determination of the root cause premature failures will be prevented moving forward.

660 **Q. What is your recommendation with respect to the Daymark generation plant**
661 **outage adjustments?**

662 A. As stated above, the Company took prudent actions in all of the outages listed.
663 Daymark did not fully examine the details around these outages and, in some cases,
664 uses their own opinion without any supporting evidence. Managing these resources
665 requires a balanced approach for the best overall interests of our customers and includes
666 risks. As shown above, the Company evaluates the costs and risks when managing the
667 assets.

668 **Q. Do you agree that the Company prudently managed the Joy longwall and the**
669 **generation plant outages?**

670 A. Yes. As stated earlier, the Company demonstrated that it diligently evaluated and
671 managed the installation and the operation of the Joy longwall. The Company also
672 demonstrated that the events that led up to the issue with the longwall were a result of
673 two unknown geological features that occurred simultaneously and exceeded the
674 capacity of the longwall to maneuver through this area. The Company has also showed
675 the efforts to recover the longwall were prudent by using several techniques and
676 resources. Finally, with respect to the plant outages, the Company has shown that it
677 diligently manages these resources and the actions taken were prudent and in the best

678 interests of the customer.

679 **Q. Does this conclude your response testimony?**

680 A. Yes.

REDACTED

Rocky Mountain Power
Exhibit RMP____(DMR-1R)
Docket No. 17-035-01
Witness: Dana M. Ralston

BEFORE THE PUBLIC SERVICE COMMISSION
OF THE STATE OF UTAH

ROCKY MOUNTAIN POWER

REDACTED

Exhibit Accompanying Response Testimony of Dana M. Ralston
14th Right Longwall Panel Report

December 2017

**THIS EXHIBIT IS CONFIDENTIAL IN
ITS ENTIRETY AND IS PROVIDED
UNDER SEPARATE COVER**


Rocky Mountain Power
Exhibit RMP__(DMR-2R)
Docket No. 17-035-01
Witness: Dana M. Ralston

BEFORE THE PUBLIC SERVICE COMMISSION
OF THE STATE OF UTAH

ROCKY MOUNTAIN POWER

Exhibit Accompanying Response Testimony of Dana M. Ralston
Bridger Coal D41 Thickness

December 2017



**Bridger Coal
13th - 16th Right
D41 Coal Seam Thickness
Updated September 2017**

Rocky Mountain Power
Exhibit RMP__(DMR-3R)
Docket No. 17-035-01
Witness: Dana M. Ralston





BEFORE THE PUBLIC SERVICE COMMISSION
OF THE STATE OF UTAH

ROCKY MOUNTAIN POWER

Exhibit Accompanying Response Testimony of Dana M. Ralston
14th Right Structural Rolls

December 2017

14th Right Longwall Structural Rolls



P.O. BOX 88
 POINT OF ROCKS, WYO. 82942
 MINE I.D. NO. 48-01646

BRIDGER
 COAL COMPANY

14TH RIGHT LONGWALL
STRUCTURAL ROLLS

Actual Conditions Encountered

Structural Roll Perpendicular to the Face (Actual Conditions Encountered)

Projected Seam Structure

Rocky Mountain Power
Exhibit RMP__(DMR-4R)
Docket No. 17-035-01
Witness: Dana M. Ralston

BEFORE THE PUBLIC SERVICE COMMISSION
OF THE STATE OF UTAH

ROCKY MOUNTAIN POWER

Exhibit Accompanying Response Testimony of Dana M. Ralston
Example of A Structural Roll in the Floor

December 2017

**Example of a Structural Roll in the Floor –
Near Bridger Coal Co., Point of Rocks, Wyoming**



Example of a Structural Roll in the Floor



P.O. BOX 68
POINT OF ROCKS, WYO. 82942
MINE I.D. NO. 48-01646

**EXAMPLE OF A
STRUCTURAL ROLL
IN THE FLOOR**

REDACTED

Rocky Mountain Power
Exhibit RMP____(DMR-5R)
Docket No. 17-035-01
Witness: Dana M. Ralston

BEFORE THE PUBLIC SERVICE COMMISSION
OF THE STATE OF UTAH

ROCKY MOUNTAIN POWER

REDACTED

Exhibit Accompanying Response Testimony of Dana M. Ralston
Joy Longwall Recovery Chronology

December 2017

**THIS EXHIBIT IS CONFIDENTIAL IN
ITS ENTIRETY AND IS PROVIDED
UNDER SEPARATE COVER**

CERTIFICATE OF SERVICE

Docket No. 17-035-01

I hereby certify that on this 19th day of December 2017, a true and correct copy of the foregoing was served by electronic mail and overnight delivery to the following:

Utah Office of Consumer Services	
Cheryl Murray Utah Office of Consumer Services 160 East 300 South, 2 nd Floor Salt Lake City, UT 84111 cmurray@utah.gov	Robert Moore Assistant Attorney General 500 Heber M. Wells Building 160 East 300 South Salt Lake City, Utah 84111 rmoore@utah.gov
Michele Beck Utah Office of Consumer Services 160 East 300 South, 2 nd Floor Salt Lake City, UT 84111 mbeck@utah.gov	Steven Snarr Assistant Attorney General 500 Heber M. Wells Building 160 East 300 South Salt Lake City, Utah 84111 stevensnarr@agutah.gov
Division of Public Utilities	
Chris Parker Division of Public Utilities 160 East 300 South, 4 th Floor Salt Lake City, UT 84111 chrisparker@utah.gov	Patricia Schmid Assistant Attorney General 500 Heber M. Wells Building 160 East 300 South Salt Lake City, Utah 84111 pschmid@agutah.gov
William Powell Division of Public Utilities 160 East 300 South, 4 th Floor Salt Lake City, UT 84111 wpowell@utah.gov	Justin Jetter Assistant Attorney General 500 Heber M. Wells Building 160 East 300 South Salt Lake City, Utah 84111 jjetter@agutah.gov
Erika Tedder Division of Public Utilities 160 East 300 South, 4 th Floor Salt Lake City, UT 84111 etedder@utah.gov	

Utah Association of Energy Users	
Gary A. Dodge (C) HATCH, JAMES & DODGE 10 West Broadway, Suite 400 Salt Lake City, Utah 84101 gdodge@hjdllaw.com	Kevin Higgins (C) ENERGY STRATEGIES 215 S. State Street, #200 Salt Lake City, UT 84111 khiggins@energystrat.com
Neal Townsend (C) ENERGY STRATEGIES 215 S. State Street, #200 Salt Lake City, UT 84111 ntownsend@energystrat.com	
Utah Industrial Energy Consumers	
William J. Evans Parsons Behle & Latimer 201 South Main Street, Suite 1800 Salt Lake City, Utah 84111 bevans@parsonsbehle.com	Vicki M. Baldwin Parsons Behle & Latimer 201 South Main Street, Suite 1800 Salt Lake City, Utah 84111 vbaldwin@parsonsbehle.com
Chad C. Baker Parsons Behle & Latimer 201 South Main Street, Suite 1800 Salt Lake City, Utah 84111 cbaker@parsonsbehle.com	
Rocky Mountain Power	
Jana Saba 1407 W North Temple, Suite 330 Salt Lake City, UT 84114 jana.saba@pacificorp.com utahdockets@pacificorp.com	Yvonne Hogle 1407 W North Temple, Suite 320 Salt Lake City, UT 84114 yvonne.hogle@pacificorp.com



Katie Savarin
Coordinator, Regulatory Operations