

# Pipeline Failure Investigation Report (Non-Confidential Version)

Saratoga Springs

February 6, 2007

# Pipeline Failure Investigation Report

**Pipeline System:** Distribution **Operator:** Questar Gas Company  
**Location:** 682 North Badger Lane, Saratoga Springs, UT 84045 **Date of Occurrence:** February 6, 2007  
**Medium Released:** Natural Gas **Quantity:** 4,571 MCF

**PHMSA Arrival Time & Date:** N/A **Total Damages \$** 500,000.00 +

**Investigation Responsibility:**  State  PHMSA  NTSB  Other \_\_\_\_\_

**Company Reported Apparent Cause:**  Corrosion  Excavation  
 Natural Forces  Incorrect Operation  Other Outside Force Damage  
 Material and/or Welds  Equipment and Operations  Other Third Party Damage

Rupture  Yes  No

Leak  Yes  No

Fire  Yes  No

Explosion  Yes  No

Evacuation  Yes  No

Number of Persons 2 Area Adjacent Homes(2 total)

## Narrative Summary

Short summary of the Incident/Accident which will give interested persons sufficient information to make them aware of the basic scenario and facts.

Mr. Manuel Robles of S&E Cable, Inc. was boring to bury a Qwest communication line to Roper's house, when he damaged a natural gas main at approximately 12:30 PM on February 6, 2007.

The Roper's house was located on Lot 806 of Sunrise Meadows Subdivision Plat "H" in Saratoga Springs, Utah. Lot 806 is a corner lot at the southeast corner of Badger Lane and Prairie Dog Way (see Appendix #1, site plans and Appendix 12, Aerial photos#53 to 62).

The 2" plastic (PE) main belonged to Questar Gas Company (QGC) and was installed along the south side of the Prairie Dog Way between the concrete walkway and the homes along the south side of this street (See Appendix #1, site plans).

QGC was notified; QGC crew arrived at the site at approximately 2:11 PM. The bar hole test of the area indicated gas in the ground and two homes in the vicinity of the damaged main were evacuated. Nobody was in the house at 953 West Prairie Dog ways (Lot 805); Mrs. April Roper and her daughter Olivia were evacuated from their home at 682 North Badger Lane (Lot 806).

QGC's crew proceeded to isolate the damaged section by squeezing off the two ends of the damaged section. They encountered frost in the ground from 6 inches down to couple of feet in the process of digging potholes. At 2:40 PM potholes were complete and the two ends of the damaged section were squeezed off. S&E Cable was asked to reverse and remove the boring machine. QGC's crew then replaced the damaged section, and electro fusion of the two ends was completed around 3:45 PM at which time a 30 minute cooling off period started.

Between 4:10 and 4:15 PM, when Mr. Larry Radford (QGC employee) and Mrs. April Roper had entered the Roper house for re-lighting of the water heater, the house exploded and the fire started.

Fire Department and Police were at the site within 5 to 10 minutes. The incident was fatal to Mrs. April Roper and Mr. Larry Radford. Their bodies were discovered after more than 5 hours. (See Appendix 12, photos #45 to #52).

Division of Public Utilities is petitioning the Public Service Commission to take enforcement actions against:

1. S&E Cable for violation of the Utah Code Title 54-8a-5.5, location with hand tools, and operating without a proper license;
2. Questar Gas Company for violation of the Emergency Leak Repair QGC Manual of Standard Practice Volume 3, Section 5.0.8.7.

Region/State Western / Utah

Reviewed by: AG White

Principal Investigator: Al Zadeh

Title: Division Director

# Pipeline Failure Investigation Report

Date: 7/18/07

Date: 7/18/07

<b>Failure Location &amp; Response</b>			
Location (City, Township, Range, County/Parish): Saratoga Springs, T.5.S.,R.1.W., Utah			(Acquire Map)
Address or M.P. on Pipeline: 682 Badger Lane		(1) Type of Area (Rural, City): City	(1)
Date: February 6, 2007		Time of Failure: 12:30 PM	
Time Detected: 12:30 PM		Time Located: 2:15 PM	
How Located: By Manuel Robles of S&E Cable, Inc. Mr. Manuel damaged the main during directional boring to bury a Qwest communication line to the Roper's house.			
NRC Report #: 825728	(Attach Report)	Time Reported to NRC: 4:58 PM	Reported by: Lou Flaim
<b>Type of Pipeline:</b>			
<b>Gas Distribution</b>		<b>Gas Transmission</b>	
<input type="checkbox"/> LP	<input type="checkbox"/> Municipal	<input type="checkbox"/> Interstate Gas	<input type="checkbox"/> Intrastate Gas
<input checked="" type="checkbox"/> Public Utility	<input type="checkbox"/> Master Meter	<input type="checkbox"/> Jurisdictional Gas Gathering	<input type="checkbox"/> Offshore Gas
		<input type="checkbox"/> Offshore Gas - High H <sub>2</sub> S	
		<b>Hazardous Liquid</b>	
		<input type="checkbox"/> Interstate Liquid	<input type="checkbox"/> Intrastate Liquid
		<input type="checkbox"/> Offshore Liquid	<input type="checkbox"/> Jurisdictional Liquid Gathering
		<input type="checkbox"/> CO <sub>2</sub>	
<b>LNG</b>			
<input type="checkbox"/> LNG Facility			
Pipeline Configuration (Regulator Station, Pump Station, Pipeline, etc.): Plastic distribution main and service			

<b>Operator/Owner Information</b>			
Owner: Questar Gas Company		Operator: Same	
Address: P.O.Box 45360 Salt Lake City, Utah 84145		Address: Same	
Company Official: Ron Jibson		Company Official: Same	
Phone No.: 801-324-5424	Fax No.: 801-324-5535	Phone No. Same	Fax No. Same
Drug and Alcohol Testing Program Contacts			<input type="checkbox"/> N/A
Drug Program Contact & Phone: Brenda Bain 801-324-3742			
Alcohol Program Contact & Phone: Same as above			

<b>Damages</b>			
Product/Gas Loss or Spill <sup>(2)</sup>	4,571 MCF	Estimated Property Damage \$	250,000.00

Photo documentation  
Initial volume lost or spilled

## Pipeline Failure Investigation Report

<b>Damages</b>			
Amount Recovered	N/A	Associated Damages <sup>(3)</sup> \$	5,990.00
Estimated Amount \$	250,000.00		
Description of Property Damage: The Roper's house was destroyed in the explosion/fire.			
Customers out of Service:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No	Number: <u>N/A</u>
Suppliers out of Service:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No	Number: <u>N/A</u>

<b>Fatalities and Injuries</b>					
Fatalities:	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	Company: <u>1</u>	Contractor: _____	Public: <u>1</u>
Injuries - Hospitalization:	<input type="checkbox"/> Yes	<input type="checkbox"/> No	Company: _____	Contractor: _____	Public: _____
Injuries - Non-Hospitalization:	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	Company: _____	Contractor: _____	Public: <u>1</u>
Total Injuries (including Non-Hospitalization):			Company: <u>1</u>	Contractor: _____	Public: <u>2</u>
Name	Job Function	Yrs w/ Comp.	Yrs. Exp.	Type of Injury	
Larry Radford	Operations Rep.	24	21	Fatality	
April Roper	N/A	NA	NA	Fatality	
Olivia Roper	N/A	NA	NA	Cut to mouth	

<b>Drug/Alcohol Testing</b>					<input type="checkbox"/> N/A
Were all employees that could have contributed to the incident, post-accident tested within the 2 hour time frame for alcohol or the 32 hour time frame for all other drugs?					
<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No					
Job Function	Test Date & Time	Location	Results		Type of Drug
			Pos	Neg	
Crew Foreman	2/6/2007 9:15 PM	Top Stop (Convenience Store) Redwood Rd. & Hwy. 73	<input type="checkbox"/>	<input checked="" type="checkbox"/>	See Appendix # 2
Operations Rep.	2/6/2007 9:15 PM	Top Stop (Convenience Store) Redwood Rd. & Hwy. 73	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
Operations Rep.	2/6/2007 9:15 PM	Top Stop (Convenience Store) Redwood Rd. & Hwy. 73	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
			<input type="checkbox"/>	<input type="checkbox"/>	

<sup>3</sup> Including cleanup cost

# Pipeline Failure Investigation Report

<b>Drug/Alcohol Testing</b>				<input type="checkbox"/> N/A
			<input type="checkbox"/>	<input type="checkbox"/>

<b>System Description</b>	
Describe the Operator's System: Distribution with plastic main and service lines	

<b>Pipe Failure Description</b>		<input checked="" type="checkbox"/> N/A
Length of Failure (inches, feet, miles):		(1)
Position (Top, Bottom, include position on pipe, 6 O'clock):	Description of Failure (Corrosion Gouge, Seam Split):	
Laboratory Analysis: <input type="checkbox"/> Yes <input type="checkbox"/> No		
Performed by:		
Preservation of Failed Section or Component: <input type="checkbox"/> Yes <input type="checkbox"/> No		
If Yes - Method:		
In Custody of:		
Develop a sketch of the area including distances from roads, houses, stress inducing factors, pipe configurations, etc. Bar Hole Test Survey Plot should be outlined with concentrations at test points. Direction of Flow.		

<b>Component Failure Description</b>		<input checked="" type="checkbox"/> N/A
Component Failed:	(1)	
Manufacturer:	Model:	
Pressure Rating:	Size:	
Other (Breakout Tank, Underground Storage):		

<b>Pipe Data</b>		<input type="checkbox"/> N/A
Material: Polyethylene Plastic	Wall Thickness/SDR: 11	
Diameter (O.D.): 2 inches	Installation Date: 11/04/2005	
SMYS: N/A	Manufacturer: Polypipe	
Longitudinal Seam: N/A	Type of Coating: N/A	
Pipe Specifications (API 5L, ASTM A53, etc.): ASTM D2513		

<b>Joining</b>		<input checked="" type="checkbox"/> N/A
Type:	Procedure:	
NDT Method:	Inspected: <input type="checkbox"/> Yes <input type="checkbox"/> No	

# Pipeline Failure Investigation Report

<b>Pressure @ Time of Failure @ Failure Site</b>					<input type="checkbox"/> N/A
Pressure @ Failure Site: 45 psig			Elevation @ Failure Site: 4,510 feet		
Pressure Readings @ Various Locations:			Direction from Failure Site		
Location/M.P./Station #	Pressure (psig)	Elevation (ft msl)	Upstream	Downstream	
TG0001(regulator station)	45	4,603	1.5 miles		

<b>Upstream Pump Station Data</b>		<input checked="" type="checkbox"/> N/A
Type of Product:	API Gravity:	
Specific Gravity:	Flow Rate:	
Pressure @ Time of Failure <sup>(4)</sup>	Distance to Failure Site:	
High Pressure Set Point:	Low Pressure Set Point:	

<b>Upstream Compressor Station Data</b>		<input checked="" type="checkbox"/> N/A
Specific Gravity:	Flow Rate:	
Pressure @ Time of Failure <sup>(4)</sup>	Distance to Failure Site:	
High Pressure Set Point:	Low Pressure Set Point:	

<b>Operating Pressure</b>		<input type="checkbox"/> N/A
Max. Allowable Operating Pressure: 60 psig	Determination of MAOP: pressure test (100 psig)	
Actual Operating Pressure: 45 psig, See Appendix # 3		
Method of Over Pressure Protection: Worker/Monitor Regulator Station		
Relief Valve Set Point: 52 psig(token): 55psig(monitor)	Capacity Adequate?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No

<b>Integrity Test After Failure</b>		<input checked="" type="checkbox"/> N/A
Pressure Test Conducted in place? (Conducted on Failed Components or Associated Piping):	<input type="checkbox"/> Yes	<input type="checkbox"/> No
If NO, Tested after removal?	<input type="checkbox"/> Yes	<input type="checkbox"/> No
Method:		

<sup>4</sup> Obtain event logs and pressure recording charts

# Pipeline Failure Investigation Report

<b>Integrity Test After Failure</b>		<input checked="" type="checkbox"/> N/A
Describe any failures during the test.		

<b>Soil/water Conditions @ Failure Site</b>		<input type="checkbox"/> N/A
Condition of and Type of Soil around Failure Site (Color, Wet, Dry, Frost Depth): <b>Sandy clay with gravel, frost at varying depths down to the pipe</b>		
Type of Backfill (Size and Description): <b>sand</b>		
Type of Water (Salt, Brackish): N/A	Water Analysis <sup>(5)</sup> <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	

<b>External Pipe or Component Examination</b>		<input checked="" type="checkbox"/> N/A
External Corrosion? <input type="checkbox"/> Yes <input type="checkbox"/> No <sup>(1)</sup>	Coating Condition (Disbonded, Non-existent): <sup>(1)</sup>	
Description of Corrosion:		
Description of Failure Surface (Gouges, Arc Burns, Wrinkle Bends, Cracks, Stress Cracks, Chevrons, Fracture Mode, Point of Origin):		
Above Ground: <input type="checkbox"/> Yes <input type="checkbox"/> No <sup>(1)</sup>	Buried: <input type="checkbox"/> Yes <input type="checkbox"/> No <sup>(1)</sup>	
Stress Inducing Factors: <sup>(1)</sup>	Depth of Cover: <sup>(1)</sup>	

<b>Cathodic Protection</b>		<input checked="" type="checkbox"/> N/A
P/S (Surface):	P/S (Interface):	
Soil Resistivity:                          pH:	Date of Installation:	
Method of Protection:		
Did the Operator have knowledge of Corrosion before the Incident? <input type="checkbox"/> Yes <input type="checkbox"/> No		
How Discovered? (Close Interval Survey, Instrumented Pig, Annual Survey, Rectifier Readings, ECDA, etc):		

<b>Internal Pipe or Component Examination</b>		<input checked="" type="checkbox"/> N/A
Internal Corrosion: <input type="checkbox"/> Yes <input type="checkbox"/> No <sup>(1)</sup>	Injected Inhibitors: <input type="checkbox"/> Yes <input type="checkbox"/> No	
Type of Inhibitors:	Testing: <input type="checkbox"/> Yes <input type="checkbox"/> No	

5 Attach copy of water analysis report

## Pipeline Failure Investigation Report

<b>Internal Pipe or Component Examination</b>		<input checked="" type="checkbox"/> N/A
Results (Coupon Test, Corrosion Resistance Probe):		
Description of Failure Surface (MIC, Pitting, Wall Thinning, Chevrons, Fracture Mode, Point of Origin):		
Cleaning Pig Program: <input type="checkbox"/> Yes <input type="checkbox"/> No	Gas and/or Liquid Analysis: <input type="checkbox"/> Yes <input type="checkbox"/> No	
Results of Gas and/or Liquid Analysis <sup>(6)</sup>		
Internal Inspection Survey: <input type="checkbox"/> Yes <input type="checkbox"/> No	Results <sup>(7)</sup>	
Did the Operator have knowledge of Corrosion before the Incident? <input type="checkbox"/> Yes <input type="checkbox"/> No		
How Discovered? (Instrumented Pig, Coupon Testing, ICDA, etc.):		

<b>Outside Force Damage</b>		<input type="checkbox"/> N/A
Responsible Party: S&E Cable, Inc.	Telephone No.: 801-688-6145	
Address: 5153 W. 5400 S., Kearns, UT 84118		
Work Being Performed: <b>Directional boring</b>		
Equipment Involved: Vermeer Hammer Head Mobile (boring missile) <sup>(1)</sup>	Called One Call System? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	
One Call Name: Blue Stakes of Utah	One Call Report # <sup>(8)</sup> A70260070	
Notice Date: 1/26/2007	Time: 9:03 AM	
Response Date: 1/29/2007	Time: 2:15 PM	
Details of Response: See Appendix #4, Blue Stake ticket and locate records		
Was Location Marked According to Procedures? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No		
Pipeline Marking Type: <sup>(1)</sup>	Location: <sup>(1)</sup>	

6 Attach copy of gas and/or liquid analysis report

7 Attach copy of internal inspection survey report

8 Attach copy of one-call report



## Pipeline Failure Investigation Report

<b>Outside Force Damage</b>		<input type="checkbox"/> N/A
Paint and Flags	South side of Prairie Dog Way	
State Law Damage Prevention Program Followed? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> No State Law		
Notice Required: <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No		Response Required: <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No
Was Operator Member of State One Call? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No		Was Operator on Site? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No
Did a deficiency in the Public Awareness Program contribute to the accident? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No		
Is OSHA Notification Required? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No		

<b>Natural Forces</b>	<input checked="" type="checkbox"/> N/A
Description (Earthquake, Tornado, Flooding, Erosion):	

<b>Failure Isolation</b>		<input type="checkbox"/> N/A
Squeeze Off/Stopple Location and Method: See Appendix #1 Site Plan		(1)
Valve Closed - Upstream: N/A Time: N/A	I.D.: N/A M.P.: N/A	
Valve Closed - Downstream: N/A Time: N/A	I.D.: N/A M.P.: N/A	
Pipeline Shutdown Method: <input checked="" type="checkbox"/> Manual <input type="checkbox"/> Automatic <input type="checkbox"/> SCADA <input type="checkbox"/> Controller <input type="checkbox"/> ESD		
Failed Section Bypassed or Isolated: Isolated		
Performed By: QGC Crew, Brian Southwick, Crew Foreman		Valve Spacing: N/A

<b>Odorization</b>		<input type="checkbox"/> N/A
Gas Odorized: <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Concentration of Odorant (Post Incident at Failure Site):	
Method of Determination: <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	% LEL: <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	% Gas In Air: <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No
Odorometer Test	Time Taken: <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	
Was Odorizer Working Prior to the Incident? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Type of Odorizer (Wick, By-Pass): Pump 11:44 AM., 2/07/2007	

## Pipeline Failure Investigation Report

<i>Odorization</i>		<input type="checkbox"/> N/A
Odorant Manufacturer: Natural Gas Odorization Model: YZ Industries, NJEX 7202	Type of Odorant: 50% Tetrahydrothiophene(THT), 50% Tert-butylmercaptan(TBM)	
Amount Injected: 0.75 lbs/mcfh	Monitoring Interval (Weekly): Monthly	
Odorization History (Leaks Complaints, Low Odorant Levels, Monitoring Locations, Distances from Failure Site): No complaints; Odorant level normal; Monthly baseline test locations located 4.8 miles to the east and 9.4 miles to the west of failure site; See Appendix #5 Odorant Records		

<i>Weather Conditions</i>		<input type="checkbox"/> N/A
Temperature: mid to high 30s	Wind (Direction & Speed): minimal	
Climate (Snow, Rain): No.	Humidity: minimal	
Was Incident preceded by a rapid weather change? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No		
Weather Conditions Prior to Incident (Cloud Cover, Ceiling Heights, Snow, Rain, Fog): <b>Cold, frost on the ground</b>		

<i>Gas Migration Survey</i>		<input type="checkbox"/> N/A
Bar Hole Test of Area: <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Equipment Used: Bascom-Turner Gas Ranger	
Method of Survey (Foundations, Curbs, Manholes, Driveways, Mains, Services) <sup>(9)</sup> Foundation and adjacent grounds within 20 feet of the building, (See Appendix #7, QGC Standard Practice), For the CGI (See Appendix #8, calibration records, and Appendix #12, photos #35 to 40)		

<i>Environment Sensitivity Impact</i>		<input checked="" type="checkbox"/> N/A
Location (Nearest Rivers, Body of Water, Marshlands, Wildlife Refuge, City Water Supplies that could be or were affected by the medium loss): <sup>(1)</sup>		
OPA Contingency Plan Available? <input type="checkbox"/> Yes <input type="checkbox"/> No		Followed? <input type="checkbox"/> Yes <input type="checkbox"/> No

<i>Class Location/High Consequence Area</i>		<input checked="" type="checkbox"/> N/A
Class Location: 1 <input type="checkbox"/> 2 <input type="checkbox"/> 3 <input type="checkbox"/> 4 <input type="checkbox"/> Determination: _____	HCA Area? <input type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> N/A Determination: _____	

9 Plot on site description page

# Pipeline Failure Investigation Report

<b>Class Location/High Consequence Area</b>	<input checked="" type="checkbox"/> N/A
Odorization Required? <input type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> N/A	

<b>Pressure Test History</b> <span style="float: right;"><input checked="" type="checkbox"/> N/A</span>						
<i>(Expand List as Necessary)</i>						
	Req'd <sup>(10)</sup> Assessment Deadline Date	Test Date	Test Medium	Pressure (psig)	Duration (hrs)	% SMYS
Installation	N/A					
Next						
Next						
Most Recent						
Describe any problems experienced during the pressure tests.						

<b>Internal Line Inspection/Other Assessment History</b> <span style="float: right;"><input checked="" type="checkbox"/> N/A</span>					
<i>(Expand List as Necessary)</i>					
	Req'd <sup>(10)</sup> Assessment Deadline Date	Assessment Date	Type of ILI Tool <sup>(11)</sup>	Other Assessment Method <sup>(12)</sup>	Indicated Anomaly If yes, describe below
Initial					<input type="checkbox"/> Yes <input type="checkbox"/> No
Next					<input type="checkbox"/> Yes <input type="checkbox"/> No
Next					<input type="checkbox"/> Yes <input type="checkbox"/> No
Most Recent					<input type="checkbox"/> Yes <input type="checkbox"/> No
Describe any previously indicated anomalies at the failed pipe, and any subsequent pipe inspections (anomaly digs) and remedial actions.					

<b>Pre-Failure Conditions and Actions</b> <span style="float: right;"><input checked="" type="checkbox"/> N/A</span>	
Was there a known pre-failure condition requiring <sup>(10)</sup> the operator to schedule evaluation and remediation? <input type="checkbox"/> Yes (describe below or on attachment) <input type="checkbox"/> No	
If there was such a known pre-failure condition, had the operator established and adhered to a required <sup>(10)</sup> evaluation and remediation schedule? Describe below or on attachment. <input type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> N/A	
Prior to the failure, had the operator performed the required <sup>(10)</sup> actions to address the threats that are now known to be related to the cause of this failure? <input type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> N/A	
List below or on an attachment such operator-identified threats, and operator actions taken prior to the accident.	

10 As required of Pipeline Integrity Management regulations in 49CFR Parts 192 and 195

11 MFL, geometry, crack, etc.

12 ECDA, ICDA, SCCDA, "other technology," etc.

# Pipeline Failure Investigation Report

<b>Pre-Failure Conditions and Actions</b>	<input checked="" type="checkbox"/> N/A
Describe any previously indicated anomalies at the failed pipe, and any subsequent pipe inspections (anomaly digs) and remedial actions.	

<b>Maps &amp; Records</b>	<input type="checkbox"/> N/A
Are Maps and Records Current? <sup>(13)</sup> <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	
Comments: See Appendix #1	

<b>Leak Survey History</b>	<input type="checkbox"/> N/A
Leak Survey History (Trend Analysis, Leak Plots): No prior leaks, except for a few 3 <sup>rd</sup> party leaks in the general area (new subdivision).	

<b>Pipeline Operation History</b>	<input type="checkbox"/> N/A
Description (Repair or Leak Reports, Exposed Pipe Reports): LRO# 69311 (3 <sup>rd</sup> party leak on Badger Lane, in 2006)	
Did a Safety Related Condition Exist Prior to Failure? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No    Reported? <input type="checkbox"/> Yes <input type="checkbox"/> No	
Unaccounted For Gas: N/A	
Over & Short/Line Balance (24 hr., Weekly, Monthly/Trend): N/A	

<b>Operator/Contractor Error</b>		<input type="checkbox"/> N/A
Name: 1. S&E Cable, Inc. (contractor) [Note: S&E Cable was in violation of Utah Code Title 54.8a.5.5 Location with hand tools, and was operating without a proper license. Utah Pipeline Safety Section does not have jurisdiction over contractors] 2. Questar Gas Company (operator)	Job Function: Repair of 3 <sup>rd</sup> party damage	
Title: Response Crew to 3 <sup>rd</sup> party damage (Crew Foreman: Brian Southwick)	Years of Experience: 6 to 27 yrs	
Training (Type of Training, Background): See Appendix #6 (Operator Qualification records)		
Was the person "Operator Qualified" as applicable to a precursor abnormal operating condition? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> N/A		
Was qualified individual suspended from performing covered task <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> N/A		
Type of Error (Inadvertent Operation of a Valve): Failure to clear the house properly for Natural Gas in violation of QGC Manual of Standard Practice Volume 3, Section 5.0.8.7 (See Appendix #7 QGC Procedure/Checklist).		

13 Obtain copies of maps and records

# Pipeline Failure Investigation Report

<b>Operator/Contractor Error</b>					<input type="checkbox"/> N/A
Procedures that are required: Emergency Leak Repair QGC Manual of Standard Practice Volume 3, Section 5.0.8.7. (See Appendix #7 QGC Procedure/Checklist)					
Actions that were taken: According to Brian Southwick when he had asked Larry Radford about the gas levels in the ground along the north side of the house, Larry responded; "it was clear" (below 2% gas in the air). Larry was using CGI (ID#73, with serial number 0512-055540) for testing gas levels in the ground outside the house (See Appendix #8, Calibration Records and Appendix #12, Photos #35 to 40) . This CGI unit was in Larry's truck after the incident, indicating that Larry did not use this unit for testing gas level inside the house. Larry's TIF (a different kind of instrument which makes a clicking sound when encounters methane gas at 500PPM level and higher) was discovered in the basement of the house after the explosion (Appendix 12, Photo #31). The on-off button of the instrument was at on position. It is not clear at this time, why it did not alert Larry from entering the house. This instrument has been tested non-destructively (See Appendix #8, statement from QGC and maintenance records). There will be additional destructive testing by the manufacturer at some point in the future. The Division will obtain copies of any reports of such testing.					
Pre-Job Meeting (Construction, Maintenance, Blow Down, Purging, Isolation): N/A					
Prevention of Accidental Ignition (Tag & Lock Out, Hot Weld Permit): N/A					
Procedures conducted for Accidental Ignition: N/A					
Was a Company Inspector on the Job? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No					
Was an Inspection conducted on this portion of the job? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No					
Additional Actions (Contributing factors may include number of hours at work prior to failure or time of day work being conducted): The crew had started work at 7:00 AM in the morning of the incident. At the time of the accident it would have been only less than half an hour over 8 hour workday.					
Training Procedures: See Appendix #6					
Operation Procedures: See Appendix #7					
Controller Activities: N/A					
Name	Title	Years Experience	Hours on Duty Prior to Failure	Shift	
Alarm Parameters: N/A					
High/Low Pressure Shutdown: N/A					
Flow Rate: N/A					
Procedures for Clearing Alarms: N/A					
Type of Alarm: N/A					

# Pipeline Failure Investigation Report

<i>Operator/Contractor Error</i>	<input type="checkbox"/> N/A
Company Response Procedures for Abnormal Operations: N/A	
Over/Short Line Balance Procedures: N/A	
Frequency of Over/Short Line Balance: N/A	
Additional Actions: <b>The next day a vacuum truck was used to pull the natural gas that was released from the damaged main out of the ground near adjacent property.</b>	

<i>Additional Actions Taken by the Operator</i>	<input checked="" type="checkbox"/> N/A
Make notes regarding the emergency and Failure Investigation Procedures (Pressure reduction, Reinforced Squeeze Off, Clean Up, Use of Evacuators, Line Purging, closing Additional Valves, Double Block and Bleed, Continue Operating downstream Pumps):	

## Pipeline Failure Investigation Report

### Photo Documentation <sup>(1)</sup>

Overall Area from best possible view. Pictures from the four points of the compass. Failed Component, Operator Action, Damages in Area, Address Markings, etc.

Photo No.	Description	Roll No.	Photo No.	Description	Roll No.
1	Standing W. of the site looking E.		31	Mr. Radford's TIF	
2	Standing W. of the site looking E.		32	LMr. Radford's Tool Box	
3	Standing N.E. of the site looking S.		33	Mr. Radford's Truck	
4	Standing N. looking E.(couch on the neighbor's roof)		34	Mr. Radford's Truck	
5	Standing N. looking S.		35	LMr. Radford's CGI	
6	Standing S. looking N.		36	Mr. Radford's CGI	
7	Standing S.W. looking N.E.		37	Mr. Radford's CGI	
8	Standing N.W. looking S.E.		38	Mr. Radford's CGI	
9	Standing N. E. looking W. 2/06/2007		39	Mr. Radford's CGI	
10	Standing N.E. looking S.W. 2/07/07		40	Mr. Radford's CGI	
11	Standing N.E. looking W.		41	Gas Meter	
12	Standing N.E. looking W. Squeeze off pot-holes are visible, blue tarp covers where main was damaged		42	Inlet and Outlet to gas meter	
13	East squeeze off pothole		43	Safety valve to the furnace	
14	West squeeze off pothole		44	Safety valve to the water heater	
15	Repaired section of main		45	Mr. Radford's body	
16	Service Riser N.W. corner		46	Mr. Radford's body	
17	Standing W. looking E.		47	Mr. Radford's body	
18	Damage to west side of the adjacent home (Lot 805) at 953 West Prairie Dog Way		48	Mr. Radford's body	
19	Standing N.E. looking S.W.		49	Mrs. Roper's body	
20	CGI inside Mr. Radford's truck		50	Mrs. Roper's body	
21	Standing N.W. looking S.E.		51	Mrs. Roper's body	
22	Standing W. looking E. and down		52	Mrs. Roper's body	
23	Standing E. looking W. and down		53	53 to 62 Aerial photos taken by Utah County Sheriff's Office.	
24	Standing S. looking N.		54		
25	Standing S. looking N.		55		
26	Standing N.W. looking E.		56		
27	Standing N.W. looking S.E.		57		
28	Bottom left pothole is where boring started , blue tarp covers where main was damaged, Top center is west squeeze off pothole.		58		
29	Damaged section of main		59		

## Pipeline Failure Investigation Report

<i>Photo Documentation</i> <sup>(1)</sup>			
30	Damaged section of main		60
Type of Camera: Olympus Digital Camera D-450 Zoom, 1.3 Mega pixel was used by Utah Pipeline Safety Staff for Photos #1 to #30, Photos #31 to #52 were submitted by State Fire Marshall's Office, and Photos #53 to #62 were submitted by Utah County Sheriff's Office.			
Film ASA:N/A			
Video Counter Log (Attach Copy): N/A			

<i>Additional Information Sources</i>			
Agency	Name	Title	Phone Number
Police:	Scott Jody	Detective, Utah County Sheriff's Office	801-343-4000
Fire Dept.:	Dennis Barker	Utah County Fire Marshall	801-404-0659
State Fire Marshall:	Troy Mills	Deputy	801-556-4154
State Agency:			
NTSB:			
EPA:			
FBI:			
ATF:			
OSHA:	Jim Johnston	Compliance Officer	801-530-6604
Insurance Co.:			
FRA:			
MMS:			
Television:	Local Channels 2, 4, 5, 13		
Newspaper:	Local newspapers		
Other:	Mike Penovich	Saratoga Springs Fire Marshall	801-830-2462



## **Pipeline Failure Investigation Report**

<i>Persons Interviewed</i>		
Name	Title	Phone Number
<b>Brian Southwick</b>	<b>Crew Foreman, QGC</b>	<b>801-853-6506</b>
<b>Ryan Whittekiend</b>	<b>Operations Rep., QGC</b>	<b>801-853-6542</b>
<b>Jack Bryant</b>	<b>Operations Rep., QGC</b>	<b>801-853-6542</b>
<b>Manuel Robles</b>	<b>Equipment Operator, S&amp;E Cable, Inc.</b>	<b>801-688-6145</b>
<b>Sandy Parra</b>	<b>Owner S&amp;E Cable, Inc.</b>	<b>801-688-6145</b>
<b>Captain Alisa Harper</b>	<b>Saratoga Springs Fire Dept.</b>	<b>801-766-6506</b>

## Pipeline Failure Investigation Report

<i>Event Log</i>	
Sequence of events prior, during, and after the incident by time. (Consider the events of all parties involved in the incident, Fire Department and Police reports, Operator Logs and other government agencies.)	
Time	Event
12:30 PM	Mr. Manuel Robles of S&E Cable damaged a 2" gas main by directional boring, Mr. Robles called Mrs. Sandy Parra, (See Appendix #14, Utah County Sheriff's Report Page 20)
12:59:23 PM	Mrs. Sandy Parra owner of S&E Cable placed a call to QGC, (See Appendix #9, emergency call timeline)
1:32 PM	Brian Southwick of QGC and his crew while on a job at 1100 N. 100 W., Pleasant Grove received the call to respond to this 3 <sup>rd</sup> party damage.
1:35 PM	Mr. Southwick and crew left Pleasant Grove heading to Saratoga Springs
2:11 PM	Mr. Southwick and crew arrived at 682 North Badger Lane, Saratoga Springs, Manuel pointed to the area of the damaged main, gas was bubbling out of ground along the cracks and edges of the concrete walk way.
2:15 PM	Bar hole test revealed gas in the ground, Crew proceeded to evacuate two homes within the damaged area of the main. Nobody was in the house at 953 West Prairie Dog Way: Mrs. April Roper and her daughter Olivia were evacuated from Roper's house at 682 North Badger Lane.
2:40 PM	The damaged section was secured by squeezing off the two ends.
2:45 PM	Mr. Robles was asked to reverse and remove the boring machine, he did so, and QGC's crew proceeded to repair the damaged main.
3:45 PM	The second electro fusion completed, and the 30 minute cooling off period started.
4:12 PM	Mr. Southwick was at his truck getting a tool to raise the squeeze from the two ends of the repaired section of the main. His truck was parked on the south side of the Prairie Dog Way close to where the repair section of main was located (See Appendix #12, Photos #53 to 62). Mrs. April Roper with her daughter in a stroller walking up toward the west on Prairie Dog Way approached Mr. Southwick and asked when she could enter her house (See Appendix #13, statement from Mrs. Kristine Ewert, and Appendix #14, page 15, second paragraph from the bottom of the page). Mr. Southwick responded "it was safe for her to go back to her house". He then walked them over to Mr. Radford and his truck, where it was parked on the east side of Badger Lane close to the corner of Badger Lane with Prairie Dog Way and asked Mr. Radford to clear her house. Mr. Southwick turned around and headed toward his truck. Last time he saw Mr. Radford and Mrs. Roper, they were walking toward the front of the house.
4:12 to 4:15 PM	Mr. Southwick was at the right side of his truck, the truck was facing east, he was getting the tool to raise the squeeze offs, when he heard the explosion.
4:15 to 4:25 PM	Fire and police arrived at the site. Fire department started to put out the fire.
4:58 PM	Reported to NRC (National Response Center) by Mr. Lou Flaim of QGC (See Appendix #10, PHMSA 30 day report).
9:51 PM	Mr. Radford's body was recovered. (See Appendix #12, Photo #45 and Appendix #11, Medical Examiner Report: Case #R200700215).
9:59 PM	Mrs. Roper's body was recovered (Appendix #12, Photo #49, and Appendix 311, Medical Examiner Report: Case #R200700214).

## Pipeline Failure Investigation Report

<b><i>Event Log</i></b>	
Sequence of events prior, during, and after the incident by time. (Consider the events of all parties involved in the incident, Fire Department and Police reports, Operator Logs and other government agencies.)	

<b><i>Investigation Contact Log</i></b>			
Time	Date	Name	Description
AM	2/07/07	Judy Scott	Utah County Sheriff's Office
AM	2/07/07	Ken Leetham	City Manager, Saratoga Springs
AM	2/07/07	Timothy Parker	Mayor, Saratoga Springs
AM	2/07/07	Jimmy Franc	nextdoor neighbor's father
AM	2/07/07	Estuardo Peres	neighbor
AM	2/08/07	Mike Swenson	married to Greg Roper's sister
AM	2/08/07	Gail Roper	Greg Roper's sister
AM	2/07/07	Abbie Magrane	Questar attorney
AM	2/07/07	Ron Jorgensen	General Manager, QGC
AM	2/07/07	Jeff Hansen	QGC
AM	2/07/07	Troy Sorensen	QGC
AM	2/07/07	Ron Jibson	QGC
AM	2/07/07	James E. Johnston	OSHA
AM	2/08/07	Gary Hansen	Blue Stakes of Utah
AM	2/07/07	Sterling Jacobson	Rapid Wave, LLC.
AM	2/08/07	Richard D. Bradford	Attorney for Mr. Roper
AM	2/08/07	Mike Shinkle	Attorney for Mr. Roper
AM	2/09/07	Robert Jacobsen, CFI	Burn Pattern Analysis, INC.
AM	2/26/07	John Sumner	ELM Locating & Utility Services
AM	2/14/07	Ray Fugal	Fugal and Sons
AM	2/26/07	Kay Hansen	Paralegal, Questar
AM	2/26/07	Tim D. Dunn	Dunn & Dunn Attorney for Questar
AM	2/26/07	Ryan Whittekiend	QGC
AM	2/26/07	Jack Bryant	QGC
AM	2/26/07	Brian Southwick	QGC

## Pipeline Failure Investigation Report

<i>Investigation Contact Log</i>			
Time	Date	Name	Description
AM	2/27/07	Dave Bridge	S&E Cable, Inc. Attorney
AM	2/27/07	Sandy Parra	S&E Cable, Inc.
AM	2/27/07	Manuel Robles	S&E Cable, Inc.
AM	3/12/07	Ryan Gallagher	Qwest, Inc.
AM	4/12/07	Mike Penovich	Saratoga Springs Fire Chief.
AM	4/12/07	Troy Mills	Utah State Fire Marshal Office, investigator

<i>Failure Investigation Documentation Log</i>				
Operator: Questar Gas Company		Unit #: Central	CPF #: N/A	Date: 4/11/07
Appendix Number	Documentation Description	Date Received	FOIA	
			Yes	No
1	Site Drawings and maps	3/20/07		X
2	Post accident drug test results.	4/09/07		X
3	Pressure chart, Reg. Station TG0001	3/0/07		X
4	Blue Stakes of Utah Ticket and ELM Locating Records	Feb.2007	X	
5	Odorization and Chromatograph records of odorants	3/02/02		X
6	Operator Qualification Records	3/02/07		X
7	QGC Manual of Standard Practice Volume 3, Section 5-00-8.7 & Checklist	3/23/07		X
8	Calibration records CGI (QGC ID#73), and TIF (QGC Statement and Maintenance record)	3/02/07		X
9	Processing timeline of emergency call by Questar Gas Company	4/09/07		X
10	PHMSA 30 day report.	3/23/07	X	
11	Medical examiner reports: Case #R200700214, and Case #R200700215	3/14/07 3/21/07	X	
12	Pictures	2/06/07 2/07/07	X	
13	Statement from Kristine Ewert Roper's neighbor Statement from Captain Alisa Harper (2/16/07)	2/06/07		X
14	Utah County Sheriff's Report	5/16/07	X	
15	State Fire Marshal Report Case # 132007000013	4/26/07	X	

## **Pipeline Failure Investigation Report**

<b>Failure Investigation Documentation Log</b>				
Operator: Questar Gas Company		Unit #: Central	CPF #: N/A	Date: 4/11/07
Appendix Number	Documentation Description	Date Received	FOIA	
			Yes	No

**Site Description**

Provide a sketch of the area including distances from roads, houses, stress inducing factors, pipe configurations, etc. Bar Hole Test Survey Plot should be outlined with concentrations at test points. Photos should be taken from all angles with each photo documented. Additional areas may be needed in any area of this guideline.

# APPENDIXES

1	Site Plans
2	Post Accident Drug Test
3	Pressure Chart Station: TG 0001
4	Blue Stakes' Ticket, and ELM Locating Records
5	Odorization Records
6	OQ Records
7	QGC Standard Practice
8	CGI Calibration Records, and TIF Maintenance/QGC Statement
9	Emergency Call Processing Timeline
10	PHMSA 30 Day Report
11	Medical Examiner's Report
12	Photo Documentation
13	Statements From: Kristine Ewert, and Captain Alisa Harper
14	Utah County Sheriff's Office Incident Report 07UC01273
15	State Fire Marshal Report Case File No:132007000013