

Witness CCS – 5D RR TN

Exhibit CCS – 5D RR TN

**BEFORE THE PUBLIC SERVICE COMMISSION OF UTAH**

---

**In the Matter of the  
Application of Questar Gas  
Company to Increase  
Distribution Non-Gas Rates  
And Charges and Make  
Tariff Modifications**

) **Docket No. 07-057-13**  
) **Direct**  
) **Testimony of**  
) **Thomas J. Norris P.E.**  
) **For the Committee of**  
) **Consumer Services**

---

April 21, 2008

**INCREASED CAPITAL EXPENDITURE FOR INFRASTRUCTURE**

**DIRECT TESTIMONY**

**OF**

**THOMAS J. NORRIS P.E.**

**ON BEHALF OF**

**THE UTAH COMMITTEE OF CONSUMER SERVICES**

**APRIL 21, 2008**

1 **Q. PLEASE STATE YOUR NAME AND ADDRESS.**

2 **A.** My name is Thomas J Norris and my business address is 35 Lincoln  
3 St. Andover, MA 01810.

4

5 **Q. WHO ARE YOU REPRESENTING AND WHAT IS THE NATURE**  
6 **OF YOUR TESTIMONY?**

7 **A.** I am representing the Committee of Consumer Services and my  
8 testimony will address the proposed inclusion of \$45 million of feeder  
9 line replacement in the Questar Gas Company rate base in this  
10 proceeding, Docket 07-057-13.

11

12 **Q. HOW IS YOUR TESTIMONY ORGANIZED?**

13 **A.** First I'll outline my qualifications as a pipeline expert, next I'll  
14 analyze the Company's rationale for the proposed accelerated feeder  
15 line replacement, then I'll show the results of replacing the feeder lines,  
16 next I'll do a quick comparative analysis, finally I'll discuss my  
17 recommendation and conclusion.

18

19 **I. QUALIFICATIONS**

20

21 **Q. DESCRIBE YOUR QUALIFICATION AND EXPERIENCE.**

22        **A.** Attached as an exhibit is a resume of my education and experience.

23        I will provide a brief description of the portions of my resume which are

24        most relevant to the matters which I will testify about.

25        I have extensive experience in rates and regulatory matters. I was a

26        member of the staff of the New York Public Service Commission,

27        serving as Chief of Gas Rates and Chief of Gas Planning.

28        Following my tenure with the NYPSC, I joined Tenneco's natural gas

29        pipeline division where I was Vice President of Rates. In subsequent

30        assignments with Tenneco's pipeline division I was Vice President

31        Operations, and Vice President Gas Supply. In my last assignment at

32        Tenneco I was Senior Vice President Major Projects, an assignment

33        that included presidency of Kern River Gas Transmission.

34        Since my employment at Tenneco ended in 1996 I have been

35        practicing as an independent consultant.

36        I have testified on numerous occasions in state and federal

37        proceedings involving rates and tariff matters of local distribution

38        companies and interstate pipelines.

39        I am a professional engineer licensed in the state of New York.

40

41

42        **II.        QUESTAR'S NEED TO SIGNIFICANTLY ACCELERATE**

43        **ITS FEEDER LINE REPLACEMENT PROGRAM**

44

45 **Q. DESCRIBE THE FEEDER LINE PROGRAM WHICH QUESTAR**  
46 **GAS COMPANY HAS INSTITUTED.**

47 **A.** Questar began replacement of its feeder lines which were  
48 constructed with reconditioned pipe in 2007 and expects to conclude  
49 the program by 2012. At the beginning of the program it had over  
50 300,000 feet (56.8 miles) of reconditioned pipe in service. In 2007 it  
51 expended \$48.2 million on various feeder line replacements. It is  
52 planning to spend \$45 million in both 2008 and 2009 on replacements  
53 projects. The company indicated that its replacement program is based  
54 on a number of considerations. The primary consideration is public  
55 safety. System reliability is another consideration as is the need to  
56 provide for customer growth. Lastly the program considers the effect  
57 of the construction on the convenience to the general public.

58

59 **Q. DO YOU HAVE ANY COMMENTS ON THESE**  
60 **CONSIDERATIONS THAT WERE USED TO DEVELOP THE**  
61 **COMPANY PROGRAM?**

62 **A.** In general these considerations are appropriate for a program of this  
63 type. However the major underpinning for the program is the notion  
64 that due to the age of the reconditioned pipe it should be replaced on  
65 an accelerated basis. The federal safety regulations do not permit  
66 Questar to continue to operate any pipeline determined to be unsafe.  
67 Those facilities determined to be unsafe must be replaced or

68 maintained to return them to safe operating condition immediately  
69 following such determination (49 CFR part 192). Therefore it must be  
70 assumed that the FL replacement program does not include pipelines  
71 determined to currently be unsafe.

72

73 **Q. IF THE FL PIPELINES ARE NOT CURRENTLY UNSAFE WHAT**  
74 **IS THE COMPANY POSITION FOR REPLACING THEM DUE TO**  
75 **PUBLIC SAFETY CONCERNS?**

76 **A.** In response to CCS data request 19.06 asking for identification of  
77 lines that might be more likely to be problematic than others Questar  
78 responded that "... feeder lines containing reconditioned pipe as  
79 having elevated risk vis-à-vis pipelines constructed using current  
80 engineering and technology. Risk associated with transmission  
81 pipelines can be considered to be the result of two factors, probability  
82 and consequence of failure. The consequence of failure is taken into  
83 consideration under the U.S. Department of Transportation regulations  
84 for transmission pipeline safety through definitions for "high  
85 consequence area". "The probability of failure on all feeder lines  
86 containing reconditioned pipe is higher due to the existence of aging,  
87 reconditioned repairs and steel properties (e.g. lower fracture  
88 toughness)."

89

90 **Q. GIVEN THE POTENTIAL ISSUES WITH RECONDITIONED PIPE**  
91 **IN THE FEEDER LINES HOW HAS THE COMPANY ASSESSED**  
92 **THE SITUATION AND CONCLUDED THAT THE REPLACEMENT**  
93 **PROGRAM INCLUDED IN ITS RATE CASE IS APPROPRIATE?**

94 **A.** One of the key considerations is “reconditioned repairs”. The  
95 company indicated in its response to CCS 19.06 that its historical  
96 records do not “describe the precise location or extent of reconditioned  
97 repairs, thus it is not been possible to discriminate the possibility of  
98 failure of one reconditioned feeder line or location from another.”

99

100 **Q. DO YOU AGREE WITH THE COMPANY’S CONCLUSIONS?**

101 **A.** In part. However, I would note that there are other methods for  
102 determining pipes that may be at greater risk. For example, as part of  
103 the response the company indicated it had a self imposed operating  
104 pressure restriction of 250 psig on FL 18, which would indicate some  
105 level of concern. The 250 psig is in contrast to the 499 psig MAOP of  
106 that line. Nonetheless, FL 18 is not scheduled for replacement until  
107 2010 and that is a commentary on the safety of the feeder line system.  
108 In contrast the lines scheduled for replacement in 2008 have had only  
109 minimal repairs of a routine nature over the last three years.

110

111 **Q. HAS THE COMPANY PROVIDED A HISTORY OF NON-**  
112 **SCHEDULED MAINTENANCE ON ITS FEEDER LINES FOR THE**  
113 **PAST THREE YEARS?**

114 **A.** Yes it has.

115

116 **Q. CAN YOU SUMMARIZE THE NON-SCHEDULED MAINTENANCE**  
117 **HISTORY OF QUESTAR'S FEEDER LINES FOR THE PAST THREE**  
118 **YEARS?**

119 **A.** Yes

120 **a. Feeder Line 4 16" Installed in 1962 Operated at 350 psig**

121 3 separate repairs to the pipeline coating each estimated to

122 cost less than \$1000

123 **b. Feeder Line 5 16" line installed in 1962 operated at 350**

124 **psig** 2 repairs to pipeline coating each estimated to cost less

125 than \$1000

126 **c. Feeder Line 7 6" line installed in 1971 operated at 350**

127 **psig**

128 Replaced section of line at cost of \$345,000

129 **d. Feeder Line 11 12" installed in 1953,1961 and 1966**

130 **operated at 350 psig**

131 3 separate coating repairs each estimated to cost less than

132 \$1000.



- 133 e. **Feeder Line 12 14” line installed in 1954 and 1963**  
134 **operated at 350 psig**  
135 3 separate coating repairs each estimated to cost less than  
136 \$1000.
- 137 f. **Feeder Line 13 12” installed 1952 original pipe operated**  
138 **at 350 psig**  
139 Repaired coating at estimated cost of less than \$1000.
- 140 g. **Feeder Line 18 14” line installed in 1955 operated at 315**  
141 **psig**  
142 Pipeline rupture. Segment replaced at cost of \$108,000.
- 143 h. **Feeder Line 19 14” line installed In 1955,1957and 1964**  
144 **operated at 440 psig**  
145 Numerous repairs Third party damage- sleeve installed  
146 Two coatings repaired at cost of less than \$1000 each  
147 Two field repairs of unknown character each estimated to  
148 cost less than \$1000  
149 Two instances of installation of repair sleeves at estimated  
150 cost of \$5000 each  
151 Two replacements of 9’ of pipe and one of 14’ costing a total  
152 of \$11,350  
153 One segment of unspecified length replaced at a cost of  
154 \$878,000.

155 A total 10 incidents occurred on FL 19, a number of which  
156 arose as a result of an “integrity management dig”.

157 **i. Feeder Line 25 6” line installed 1968 operated at 350**  
158 **psig**

159 Repair of damage caused by third party excavation at total  
160 cost estimated to be less than \$5000.

161 **j. Feeder Line 35 16” line installed 1964 original pipe**  
162 **operated at 350 psig**

163 Two incidents of damage due to third party excavation  
164 repaired at cost of less than \$1000 for each incident

165 Two coating repairs discovered by “integrity management  
166 dig” each costing less than \$1000

167 **k. Feeder Line 41 16” line installed 1965 original pipe**  
168 **operated at 350 psig**

169 Repair of damage caused by third party excavation  
170 estimated to cost less than \$1000

171 During the three year period a total of 31 repairs were made to the  
172 Feeder Lines mostly of a routine nature at minimal cost. Coating  
173 repair was common, probably due to the materials used and field  
174 fabrication techniques used during the times the pipe was installed.

175

176 **Q. HOW WOULD FUTURE MAINTENANCE COSTS BE**  
177 **IMPACTED BY THE REPLACEMENT PROGRAM?**

178           **A.** Apparently very little. In response to CCS 19.08 Questar stated  
179           “Typical operation and maintenance activities include atmospheric  
180           corrosion inspection, pipeline patrol, marking line locations, line  
181           crossing inspection, leak surveys, cathodic surveys and valve  
182           inspections. It is not anticipated that these costs will vary  
183           significantly from past levels as a result of the replacement  
184           program.”

185           However, the response goes on to state that, “Pipeline replacement  
186           will reduce future integrity management costs for Feeder Lines 4, 5,  
187           and 11. Under the current integrity management program, these  
188           pipelines are assessed at seven year intervals. Because the  
189           existing pipelines cannot be assessed by internal inspection tools,  
190           external corrosion direct assessment (ECDA) surveys were  
191           completed on the pipelines from 2005 to 2007. The estimated cost  
192           of these surveys was approximately \$600,000. Future integrity  
193           surveys of the lines can be conducted with internal inspection tools  
194           in conjunction with survey of existing upstream segment of Feeder  
195           Line 4 at nominal incremental cost of approximately \$10,000.”  
196           However since these lines were surveyed during the 2005 to 2007  
197           period, new surveys will not be required until the period beginning  
198           in 2012.

199

200 **Q. BASED ON THE RECENT REPAIR RECORDS, THE FEEDER**  
201 **LINES #18 AND #19 PRESUMABLY HAVE MORE CHANCE OF**  
202 **PROBLEMS, THAN THE LINES THAT THE COMPANY**  
203 **PROPOSES TO REPLACE IN 2008?**

204 **A.** That is correct. Based on this information, the Company has  
205 not provided adequate evidence to demonstrate that public safety,  
206 its stated number one consideration, is primarily driving the  
207 replacement program.

208

209 **Q. PLEASE COMMENT ON THE SECOND CONSIDERATION OF**  
210 **THE REPLACEMENT PROGRAM SYSTEM RELIABILITY.**

211 **A.** System reliability is intended to refer to both the need to have a  
212 core network of transmission lines available to move gas to areas  
213 of the distribution system where it is needed during various times of  
214 the day and various seasons of the year. While system reliability is  
215 described as a second consideration, Questar has provided no  
216 particulars as to how the program addresses this need. Obviously  
217 newer pipe installed using modern technology will reduce the  
218 probability of a system failure but there is no reason to believe that  
219 a failure of the existing pipe is imminent. The maintenance history  
220 of the feeder lines would indicate otherwise.

221

222 **Q. ARE YOU SUGGESTING THAT THE FEEDER LINE**  
223 **REPLACEMENT PROGRAM SHOULD NOT GO FORWARD.**

224 **A.** Not really. What I am saying is that Questar has not provided  
225 adequate evidence or explanation supporting the details of the  
226 replacement program. Where the feeder lines are inadequate due  
227 to growth or gas supply considerations they will of necessity be  
228 replaced in whole or in part. Where the maintenance history  
229 indicates a significant problem replacement probably makes sense.  
230 For example Feeder Line 19 which operates at 350 to 440 psig,  
231 was the subject of numerous non-scheduled maintenance over the  
232 past three years and replacing that line would appear to make  
233 sense. In fact Questar is planning to replace it in 2009 at an  
234 estimated cost of \$45 million. Feeder Line 18 suffered a rupture in  
235 2006 and is being operated at 250 psig despite having a MAOP of  
236 499 psig. Feeder Line 18 is not scheduled for replacement until  
237 2010. On the other hand, Feeder Lines 4, 5 and 11 which are  
238 scheduled for replacement in 2008 only had non-scheduled  
239 maintenance due to need for repairs to external pipe coating  
240 discovered during 'integrity management digs'. Questar hasn't  
241 disclosed its rationale for the specific lines it designated for  
242 replacement in 2008 vs those scheduled to be replaced in later  
243 years. On the surface it would not appear that neither safety nor  
244 reliability considerations are the driver.

245

246

247

**Q. THE THIRD CONSIDERATION GIVEN BY QUESTAR IS TO**

248

**PROVIDE FOR CUSTOMER GROWTH. HOW DOES THAT FIT**

249

**INTO THE PROPOSED SCHEDULE TO REPLACE FEEDER**

250

**LINES?**

251

**A.** Questar has provided no specific information in this docket as to

252

how its schedule for feeder line replacement fits with additional

253

capacity needs to serve customer growth.

254

255

**Q. WHAT ABOUT THE LAST CONSIDERATION?**

256

**A.** Considering the cost of replacing a pipe, the lowest reason on a

257

priority list to replace a section of pipe would be convenience.

258

259

260

### **III. RESULTS OF THE FEEDER LINE REPLACEMENT**

261

262

**Q. WILL THE REPLACEMENT OF FEEDER LINES 4, 5 AND 11**

263

**IN 2008 RESULT IN AN INCREASE IN THE CAPACITY OF**

264

**THOSE LINES?**

265

**A.** Yes. The existing lines being replaced are 12", 16" and 18" pipes

266

that are being replaced by 24" pipes. Both the existing segments

267

and the replacement segments are designed to be operated at 354

268           psig. In a response to CCS 2.02, Questar indicates that the 354  
269           psig pressure limit is based on pressure limitations of its feeder line  
270           system in the area south of North Temple Station. There is no  
271           indication that the 354 psig MAOP is related to the strength of the  
272           pipe being installed. It is quite possible that pipe could be operated  
273           at higher pressures but for the pressure limitations of  
274           interconnected lines in that area of the system. Installing pipe now  
275           which is physically capable of being operated at higher pressures  
276           will provide Questar with the ability to increase the capacity of that  
277           part of its system later at no additional expense. The incremental  
278           cost of higher grade pipe is akin to plant held for future use.

279

280           **Q. WILL THE FEEDER LINE 4, 5, AND 11 REPLACEMENT**  
281           **PIPES INCREASE THE CAPACITY OF THE QUESTAR**  
282           **SYSTEM?**

283           **A.** In its response to CCS 2.02 Questar avoided a response to  
284           increased capacity by stating that “Feeder Lines 4, 5 and 11 are  
285           integral to the Questar Gas high pressure transmission system and  
286           as such do not have defined individual capacities.” This is not  
287           responsive. The carrying capacity of the existing and replacement  
288           lines can be determined using pipeline flow equations regardless of  
289           the integrated nature of the system or the pressure limitation.

290

291 **Q. HOW HAVE YOU EVALUATED THE POTENTIAL BENEFITS**  
292 **OF INCREASED CAPACITY?**

293 **A.** In the first place Questar would not replace smaller diameter  
294 pipe with 24" pipe at considerably more cost unless it provided a  
295 benefit commensurate with the cost increase. Second, the limitation  
296 on the part of the system in which the replacements are being  
297 installed is the 354 psig. Using 354 psig operating pressure a 24"  
298 pipe can carry significantly more gas than a 12", 16" or 18" pipe  
299 operated at the same pressure. The carrying capacity of a pipeline  
300 is proportional to the square of the diameter. So that in a given  
301 segment a 24" pipe could carry 4 times as much gas as a 12" pipe  
302 everything else being equal. As long as the pressure in the 24" pipe  
303 did not exceed 354 psig the operations of the interconnected pipes  
304 would not be adversely affected. Because the system is integrated  
305 the capacity of the whole is increased by the replacement of small  
306 diameter pipe with larger diameter pipeline. Questar acknowledges  
307 this in CCS 2.02 when it states, "System operation will be  
308 enhanced by significantly increasing feeder line pressures under  
309 peak load conditions throughout the Salt Lake valley and west in  
310 the Toole and Grantsville areas. The pressures in the Toole area  
311 increase by almost 30 psig on a peak day." That is another way of  
312 saying that maintaining the same operating pressure of the  
313 integrated feeder line system with larger diameter replacement pipe



314 in FL 4, 5 and 11 would allow additional gas supply to be delivered.  
315 The replacements increase system capacity.

316

317 **Q. IS A DRIVER FOR QUESTAR'S FEEDER LINE**

318 **REPLACEMENT INCREASED SYSTEM CAPACITY?**

319 A. It is certainly a product of the replacement and may well have  
320 been a driver in the replacement schedule adopted by Questar.

321

322

323 **IV. COMPARATIVE REVIEW**

324

325 **Q. HOW DO THE PROJECTED COSTS FOR 2008 PROJECTS**

326 **COMPARE WITH QUESTAR'S HISTORICAL EXPERIENCE?**

327 A. During the period 2002 through 2007 Questar replaced 156,937  
328 feet of Feeder Line 26, a 24" pipe, at a cost of \$40.8 million or  
329 \$1.37 million per mile. In comparison Questar is projecting \$45  
330 million per year for five years, \$225 million, to replace  
331 approximately 56.8 miles of feeder line a unit cost of \$3.96 million  
332 per mile.

333

334 **Q. ARE THERE FACTORS WHICH EXPLAIN THE INCREASE IN**

335 **COSTS FROM THE HISTORICAL PERIOD?**

336           **A.** Yes. There are factors which help explain some of the large  
337 increase in cost per mile. While the 24" diameter of line 26 is the  
338 largest diameter of the feeder line system and therefore the most  
339 expensive to construct, other factors influence cost. For example  
340 steel mill products increased 74% from 2002 to 2007. Pipeline  
341 construction in the Rocky Mountain region has increased  
342 considerably and as a result contractor costs have increased  
343 significantly. In addition, specific location can have a significant  
344 impact on cost. The Phase VI of the FL 26 project constructed in  
345 2007 cost twice as much per mile as Phase V-b also constructed in  
346 2007.

347

348

349                           **V. CONCLUSIONS AND RECOMMENDATIONS**

350

351           **Q. BASED ON YOUR REVIEW OF THE INFORMATION**  
352 **PROVIDED BY QUESTAR IN SUPPORT OF THEIR RATE FILING**  
353 **HOW WOULD YOU PROPOSE TO TREAT THE**  
354 **REPLACEMENTS OF FEEDER LINES 4, 5 AND 11 FOR RATE**  
355 **PURPOSES?**

356           **A.** The rate making process is one of balancing investment and  
357 related operating expenses with revenues. If an investment has the  
358 potential to increase revenues then it should be included in rate

359 base only to the extent that the revenues to be derived from its  
360 utilization are also included. With respect to the feeder line  
361 replacements scheduled for 2008 those lines will be capable of  
362 moving significantly greater quantities of gas than the lines they are  
363 replacing. For example the 24" line that replaces a 12" line is  
364 capable of moving about four times as much gas at the same  
365 pressure drop. The 24" line replacing 16" line is capable of moving  
366 over twice as much gas under the same operating conditions. The  
367 24" line replacing 18" pipe is capable of moving about 1.75 times as  
368 much gas. The actual increase in gas capacity will in actuality be  
369 somewhat greater than the amounts cited above since new pipe will  
370 be less rough internally. The choice of 24" pipe is based on  
371 anticipation of increased gas flow. A recent Questar IRP indicated  
372 that replacement of 2 miles of 16" with 24" between 27<sup>th</sup> E and 33<sup>rd</sup>  
373 S would increase the take away capacity from the Little Mountain  
374 gate by 46,000 dth/d

375

376 **Q. HOW WOULD YOU ADDRESS THE INCLUSION OF THE 2008**  
377 **FEEDER LINE REPLACEMENTS IN RATE BASE GIVEN THE**  
378 **INCREASED CAPACITY RESULTING FROM THE LARGER**  
379 **DIAMETER OF THE REPLACEMENT PIPE?**

380 **A.** Given that Questar has not provided adequate justification that  
381 safety or system reliability are driving the feeder line replacement

382 program, it appears that increased system capacity is one of the  
383 primary benefits and drivers. Therefore, I would allocate the cost of  
384 the replacement pipe between replacement capacity and increased  
385 capacity. The cost associated with increased capacity would be  
386 included in rate base only after the utilization of the increased  
387 capacity was recognized in rates. In other words the increased  
388 capacity must be shown to be used and useful in providing service  
389 to Questar Gas' customers.

390

391 **Q. DOESN'T YOUR APPROACH UNFAIRLY PENALIZE**  
392 **QUESTAR FOR BEING PROACTIVE IN DEVELOPING A PLAN**  
393 **TO REPLACE ITS AGING FEEDER LINES?**

394 **A.** Not in my opinion. Questar has determined to replace its feeder  
395 lines over a five year period at a cost of about \$225 million. Its  
396 primary rationale for doing so is the age of the feeder lines and the  
397 fact that many of them were constructed with reconditioned pipe  
398 from the 1929 era. Pipe materials and construction techniques have  
399 advanced considerably since the time these lines were installed.  
400 Nonetheless, Questar's history with these lines doesn't indicate  
401 excessive maintenance or problems with their integrity. Moreover,  
402 the line with the greatest number of maintenance issues over the  
403 past three years, line 19, is not scheduled for replacement until  
404 2009. Line 19 is operated at over 400 psig in contrast to the 350

405           psig for the lines scheduled for replacement in 2008. As I indicated  
406           earlier FL 18 which had experienced a rupture and is currently  
407           being operated at about 50% of its MAOP is not scheduled for  
408           replacement until 2010. I mention this not because I'm questioning  
409           Questar's judgment but because I believe that the 2008  
410           replacements which increase system capacity were chosen for their  
411           beneficial impact on Questar's operating income. Questar's only  
412           explanation for choosing to replace 12", 16", and 18" pipe with 24"  
413           pipe is that it would reduce future maintenance costs by allowing for  
414           use of internal inspection tools. They could have accomplished that  
415           by use of 18" or perhaps even 16" diameter pipe instead of 24".

416

417           **Q. WHAT ARE YOUR RECOMMENDATIONS FOR RATE**

418           **TREATMENT OF THE FEEDER LINE PROJECT?**

419           **A.** Questar's stated reasons for this accelerated feeder line  
420           replacement do not hold up under scrutiny. The Company has not  
421           provided evidence supporting this level of proposed increased  
422           spending and rate base buildup and absent an evidentiary record  
423           the Company should not receive the requested funding. However, I  
424           am not recommending a financial adjustment at this time,  
425           presuming the Company can provide the necessary evidence. In  
426           the case that this evidence is not forthcoming, I recommend  
427           excluding a portion of the replacement cost of FL4, 5 and 11 (the

428 planned feeder line replacement for the test period) based on the  
429 marginal cost difference associated with the larger capacity of the  
430 new lines relative to replacing the old lines at the same capacity. In  
431 my estimation, this cost differential would be at least twenty  
432 percent.

433

434 **Q. ANY FINAL COMMENTS?**

435 **A.** Yes. It is evident that by replacing these feeder lines the  
436 Company's capacity is increased and therefore, the potential for  
437 increased operating income.

438

439 **Q. DOES THIS CONCLUDE YOUR TESTIMONY?**

440 **A.** Yes