

REDACTED
Change in HP Master List Footage

A	B	C	D	E	F	G	H	I	J	K	L
Line (Segment)											
1 FL04											
2 FL06											
3 FL08 (2013 project, not scheduled after 13)											
4 FL011											
5 FL011-1(a)											
6 FL012											
7 FL012-1											
8 FL012-2											
9 Total FL012											
10 FL013											
11 FL014											
12 FL015											
13 FL015-1											
14 FL015-2											
15 Total FL015											
16 FL016											
17 FL016-10											
18 FL018											
19 FL018-3											
20 FL019											
21 FL020 (2013 project, not scheduled after 13)											
22 FL021											
23 FL021-10											
24 FL021-13											
25 FL021-19											
26 FL021-20											
27 FL021-4											
28 FL021-5											
29 FL021-50(a)											
30 FL021-50(b)											
31 Total FL021											
32 FL022											
33 FL023											
34 FL023-2											
35 FL024											
36 FL026											
37 FL026											
38 Total FL0 26											
39 FL028(a)											
40 FL029											
41 FL029-10											
42 FL032											
43 FL033											
44 FL034											
45 FL035(b)											
46 FL036(b)											
47 FL038											
48 FL041(b)											
49 FL041(c)											
50 Total FL0 41											
51 FL042											
52 FL042-3											
53 FL043											
54 FL043-3											
55 Total FL0 43											
56 FL045											
57 FL046											
58 FL047											
59 FL048											
60 FL050 (2013 project, not scheduled after 13)											
61 FL051											
62 Total FL0 51											
63 FL086-1											
64 FL089											
65 FL097											
66 FL098											
67 FL0 11-2A											
68 FL011-2											
69 Total FL0120 Footage 3/											
70 Total Footage											
71 Total Miles (Line 71 / 5280)											

^{1/} 21,513 feet were excluded from the original master list for the following reasons. First, 15,913 feet were not properly queried on Feeder Line 38 and were
^{2/} The retirement of 24,657 feet on FL022 was not included in the infrastructure tracker program because the project was for retirement only, not replacement under the
^{3/} FL0-11-2 and FL011-2A have been combined and renamed to FL0120