

20-035-01 / Rocky Mountain Power

February 1, 2021

OCS Data Request 5.2

### **OCS Data Request 5.2**

Would the FOVM have been be able to detect winding vibrations that could cause fretting had it been working correctly? Please explain, and also state whether the answer is affirmative or negative.

### **Response to OCS Data Request 5.2**

The Company is not aware whether the Fiber Optic Vibration Monitor (FOVM) could detect winding vibrations that could cause fretting because the system stopped working before the failure. The Company was unaware that the monitor had stopped working until the failure occurred.