

Photo 13
11/25/07

2208 E. Fisher Ln.
3 failed insulator
pins




Photo 14 2945 So.
Connor St.
At least 2 failed
insulator pins




Photo 15 3003 S. Connor St.
At least 2 insulator pins
have failed




Photo 16
corner of
3020 S. 2140 E.
Connor Inters.
2 failed insulator pins




Photo 17 3059 So. Connor St.
2 failed insulator pins




Photo 18 3065 Connor S.
2 failed insulator pins

