

Exhibit RMP___(DMR-4R)

DPU Data Request 59.3

Plant Additions: Huntington U2 Explosion

The Company's response to DPU 57(b) states the "unit returned to service on December 14th, 2011 at 19:50." Was the unit allowed to be ramped to full load at the date it was returned to service? If not, please explain why not and when the unit was allowed to be ramped to full load.

Response to DPU Data Request 59.3

The unit returned to service on December 14th, 2011 at 19:50. The unit was released to be fully dispatched on December 17th at 19:15 after a number of post overhaul tests were completed and post overhaul start up problems resolved. Neither the mill explosion nor the mill steam inerting project impacted the time the unit was released to be fully dispatched.