



201 South Main, Suite 2300
Salt Lake City, Utah 84111

June 4, 2013

***VIA ELECTRONIC FILING
AND OVERNIGHT DELIVERY***

Public Service Commission of Utah
Heber M. Wells Building, 4th Floor
160 East 300 South
Salt Lake City, UT 84111

Attention: Gary Widerburg
Commission Secretary

Re: Docket 08-035-55
Service Quality Standards –December 2012 Service Quality Review Report
Replacement Pages and Supplemental Information

On May 1, 2013, in compliance with the Commission's June 11, 2009 order in the docket referenced above, and pursuant to the requirements of Rule R746-313, Rocky Mountain Power (Company) filed with the Commission its Service Quality Review Report for the period January through December 2012. At the May 22, 2013, discussion of the report it was discovered that the worst performing circuit information for 2012 was missing from section 2.8 of the report. Also during that discussion the Company was asked to provide a table showing the worst performing circuit scores using CPI99 convention, which excludes transmission and major events. As a follow up to the May 22, 2013, meeting, Rocky Mountain Power submits replacement pages for section 2.8 of the 2012 report and the additional requested information.

It is respectfully requested that all formal correspondence and Staff requests regarding this matter be addressed to:

By E-mail (preferred): datarequest@pacificorp.com
dave.taylor@pacificorp.com

By regular mail: Data Request Response Center
PacifiCorp
825 NE Multnomah, Suite 2000
Portland, OR 97232

Utah Public Service Commission

June 4, 2013

Page 2

Informal inquiries may be directed to Dave Taylor at (801) 220-2923.

Sincerely,

Jeffrey K. Larsen

Vice President, Regulation & Government Affairs

Enclosures