

P.S.C.U. No. 50

First Revision of Sheet No. 140.21 Canceling Original Sheet No. 140.21

Table 9 – Farm and Dairy Equipment Incentives			
Equipment Type	Equipment Category	Minimum Efficiency Requirements	Incentive "up to"
Automatic Milker Takeoff (Retrofit Only)		Equipment must be able to sense milk flow and remove milker when flow reaches a pre-set level. The vacuum pump serving the affected milking units must be equipped with a VFD. Incentive is available for adding automatic milker takeoffs to existing milking systems, not for takeoffs on a brand new system where there were none before. Replacement of existing automatic milker takeoffs is not eligible for this listed incentive, but may qualify for a Custom Energy Efficiency incentive.	\$235 each
Agricultural Engine Block Heater Timer		Timer must be a UL-listed device and rated for a minimum of 15 amps continuous duty.	\$10 each
High-efficiency Circulating fan (See Note 2)	12-23" Diameter	Fan must achieve an efficiency level of 11 cfm/w	\$25/fan
	24-35" Diameter	Fan must achieve an efficiency level of 18 cfm/w	\$35/fan
	36-47" Diameter	Fans must achieve an efficiency level of 18 cfm/w	\$50/fan
	≥48" Diameter	Fans must achieve an efficiency level of 25 cfm/w	\$75/fan
Heat Recovery		Heat recovery unit must use heat rejected from milk cooling refrigeration system to heat water. Customer must use electricity for water heating.	\$0.15/kWh annual energy savings
High-efficiency Ventilation Fan (See Note 2)	12-23" Diameter	Fan must achieve an efficiency level of 11 cfm/w	\$45/fan
	24-35" Diameter	Fan must achieve an efficiency level of 13 cfm/w	\$75/fan
	36-47" Diameter	Fan must achieve an efficiency level of 17 cfm/w	\$125/fan
	≥48" Diameter	Fan must achieve an efficiency level of 19.5 cfm/w	\$150/fan
Milk Pre-cooler (Retrofit Only)		The equipment must cool milk with well- water before it reaches the bulk cooling tank. New construction not eligible.	\$0.15/kWh annual energy savings

ELECTRIC SERVICE SCHEDULE NO. 140 - Continued

(Continued)

Issued by authority of Report and Order of the Public Service Commission of Utah in Advice No. 16-03