NOTICE: This report is required by 49 CFR Part 191. Failure to report can result in a civil penalty not to exceed 100,000 for each violation for each day that such violation persists except that the maximum civil penalty shall not exceed \$1,000,000 as provided in 49 USC 60122.		OMB NO: 2137-0522 EXPIRATION DATE: 8/31/2020
	Original Report Date:	09/25/2020
U.S Department of Transportation	No.	20200090- 34308
Pipeline and Hazardous Materials Safety Administration		

INCIDENT REPORT - GAS DISTRIBUTION SYSTEM

(DOT Use Only)

A federal agency may not conduct or sponsor, and a person is not required to respond to, nor shall a person be subject to a penalty for failure to comply with a collection of information subject to the requirements of the Paperwork Reduction Act unless that collection of information displays a current valid OMB Control Number. The OMB Control Number for this information collection is 2137-0522. All responses to this collection of information are mandatory. Send comments regarding the burden or any other aspect of this collection of information, including suggestions for reducing the burden to: Information Collection Clearance Officer, PHMSA, Office of Pipeline Safety (PHP-30) 1200 New Jersey Avenue, SE, Washington, D.C. 20590.

INSTRUCTIONS

Important: Please read the separate instructions for completing this form before you begin. They clarify the information requested and provide specific examples. If you do not have a copy of the instructions, you can obtain one from the PHMSA Pipeline Safety Community Web Page at http://www.phmsa.dot.gov/pipeline/library/forms.

Report Type: (select all that apply)	Original:	Supplemental:	Final:
кероп туре. (select all that арргу)	Yes		
Last Revision Date			
Operator's OPS-issued Operator Identification Number (OPID):	12876		
2. Name of Operator	DOMINION ENERG	BY UTAH/WYOMING/IDAH	0
3. Address of Operator:			
3a. Street Address	333 SOUTH STATE	STREET P.O. BOX 45360)
3b. City	SALT LAKE CITY		
3c. State	Utah		
3d. Zip Code	84111		
4. Local time (24-hr clock) and date of the Incident:	08/26/2020 10:04		
5. Location of Incident:			
5a. Street Address or location description	1375 W 570 N		
5b. City	Provo		
5c. County or Parish	Utah		
5d. State:	Utah		
5e. Zip Code:	84601		
5f. Latitude / Longitude	40.24129289, -111.	68334472	
6. National Response Center Report Number:	1285652		
7. Local time (24-hr clock) and date of initial telephonic report to the National	08/26/2020 10:38		
Response Center:			
8. Incident resulted from:	Unintentional release	se of gas	
9. Gas released:	Natural Gas		
- Other Gas Released Name:			
10. Estimated volume of gas released - Thousand Cubic Feet (MCF):	3.000		
11. Were there fatalities?	No		
- If Yes, specify the number in each category:			
11a. Operator employees			
11b. Contractor employees working for the Operator			
11c. Non-Operator emergency responders			
11d. Workers working on the right-of-way, but NOT			
associated with this Operator			
11e. General public			
11f. Total fatalities (sum of above)			
12. Were there injuries requiring inpatient hospitalization?	No		
- If Yes, specify the number in each category:			
12a. Operator employees			
12b. Contractor employees working for the Operator			
12c. Non-Operator emergency responders			
12d. Workers working on the right-of-way, but NOT		<u> </u>	
associated with this Operator			
12e. General public			
12f. Total injuries (sum of above)			
13. Was the pipeline/facility shut down due to the incident?	Yes		
- If No, Explain:			

Form PHMSA F 7100.1 Page 1 of 9

13a. Local time and date of shutdown:	08/26/2020 14:00
13b. Local time pipeline/facility restarted:	08/26/2020 15:00
- Still shut down? (* Supplemental Report Required)	
14. Did the gas ignite?	Yes
15. Did the gas explode?	No
16. Number of general public evacuated:	0
17. Time a service of (very level time 2.4 hours elevel)	0
17. Time sequence (use local time, 24-hour clock):	T
17a. Local time operator identified Incident - effective 10-2014, "Incident"	08/26/2020 10:04
changed to "failure"	
17b. Local time operator resources arrived on site:	08/26/2020 10:00
PART B - ADDITIONAL LOCATION INFORMATION	
1. Was the Incident on Federal land?	No
Location of Incident	Private property
3. Area of Incident:	Aboveground
Specify:	Typical aboveground facility piping or appurtenance (e.g. value
G P35).	or regulator station, outdoor meter set)
If Other, Describe:	or regulator station, editator motor soty
Depth of Cover:	
	Ne
4. Did Incident occur in a crossing?	No
- If Yes, specify type below:	
- If Bridge crossing –	
Cased/ Uncased:	
- If Railroad crossing –	
Cased/ Uncased/ Bored/drilled	
- If Road crossing –	
Cased/ Uncased/ Bored/drilled	
- If Water crossing –	
Cased/ Uncased	
Name of body of water (If commonly known):	
Approx. water depth (ft):	
Approx. water deptir (it).	
PART C - ADDITIONAL FACILITY INFORMATION	
Indicate the type of pipeline system:	Investor Owned
- If Other, specify:	
2. Part of system involved in Incident:	Outside Meter/Regulator set
- If Other, specify:	<u> </u>
2a. Year "Part of system involved in Incident" was installed:	2014
When "Main" or "Service" is selected as the "Part of system involved in Incide	
	Transfer of Question 2), provide the following.
3a. Nominal diameter of pipe (in):	
3b. Pipe specification (e.g., API 5L, ASTM D2513):	
3c. Pipe manufacturer:	
3d. Year of manufacture:	
4. Material involved in Incident:	Other
- If Other, specify:	Aluminum meter
4a. If Steel, Specify seam type:	7 Marini Militari
, , ,	
None/Unknown?	
4b. If Steel, Specify wall thickness (inches):	
4c. If Plastic, Specify type:	
- If Other, describe:	
4d. If Plastic, Specify Standard Dimension Ratio (SDR):	
Or wall thickness:	
4e. If Polyethylene (PE) is selected as the type of plastic in Part C, Qui	estion 4.c:
- Specify PE Pipe Material Designation Code (i.e. 2406, 3408,	
etc.)	
Unknown?	
5. Type of release involved:	Other
- If Mechanical Puncture - Specify Approx size:	1
Approx. size: in. (axial):	
Approx. size: in. (axial): in. (circumferential):	
Approx. size: in. (axial): in. (circumferential): - If Leak - Select Type:	
Approx. size: in. (axial):	

Form PHMSA F 7100.1 Page 2 of 9

- If Other - Describe:	Damaged during fire
	Damaged during life
PART D - ADDITIONAL CONSEQUENCE INFORMATION	
Class Location of Incident :	Class 3 Location
Estimated Property Damage :	
2a. Estimated cost of public and non-Operator private	\$ 500,000
property damage paid/reimbursed by the Operator – effective 6-2011, "paid/reimbursed by the Operator" removed	
Estimated cost of gas released – effective 6-2011, moved to item 2f	
2b. Estimated cost of Operator's property damage & repairs	\$ 300
2c. Estimated cost of Operator's emergency response	\$ 4,031
2d. Estimated other costs	\$0
- Describe: 2e. Property damage subtotal (sum of above)	\$ 504,331
Cost of Gas Released	
Of Estimated and of was valenced	1.640
2f. Estimated cost of gas released Total of all costs	\$ 12 \$ 504,343
Stimated number of customers out of service:	\$ 504,343
3a. Commercial entities	0
3b. Industrial entities	0
3c. Residences	2
PART E - ADDITIONAL OPERATING INFORMATION	
Estimated pressure at the point and time of the Incident (psig):	45.00
2. Normal operating pressure at the point and time of the Incident (psig):	45.00
Maximum Allowable Operating Pressure (MAOP) at the point and time of the Incident (psig):	60.00
4. Describe the pressure on the system relating to the Incident:	Pressure did not exceed MAOP
5. Was a Supervisory Control and Data Acquisition (SCADA) based system in place on the pipeline or facility involved in the Incident?	No
- If Yes:	
5a. Was it operating at the time of the Incident?	
5b. Was it fully functional at the time of the Incident?	
5c. Did SCADA-based information (such as alarm(s), alert(s), event (s), and/or volume or pack calculations) assist with the detection of the Incident?	
5d. Did SCADA-based information (such as alarm(s), alert(s), event (s), and/or volume calculations) assist with the confirmation of the Incident?	
6. How was the Incident initially identified for the Operator?	Notification from Emergency Responder
- If Other, Specify:	
6a. If "Controller", "Local Operating Personnel, including	
contractors", "Air Patrol", or "Ground Patrol by Operator or its	
contractor" is selected in Question 6, specify. 7. Was an investigation initiated into whether or not the controller(s) or control	No the facility was not manitored by a controller(a) at the time
room issues were the cause of or a contributing factor to the Incident?	No, the facility was not monitored by a controller(s) at the time of the Incident
- If "No, the operator did not find that an investigation of the controller(s)	
actions or control room issues was necessary due to:"	
(provide an explanation for why the operator did not investigate) - If Yes, Specify investigation result(s) (select all that apply):	
- Investigation reviewed work schedule rotations, continuous hours	
of service (while working for the Operator), and other factors	
associated with fatigue - Investigation did NOT review work schedule rotations, continuous	
hours of service (while working for the Operator), and other factors	
associated with fatigue	
- Provide an explanation for why not:	
Investigation identified no control room issues	
- Investigation identified no controller issues	
- Investigation identified incorrect controller action or controller error	
- Investigation identified that fatigue may have affected the controller	
(s) involved or impacted the involved controller(s) response	
 Investigation identified incorrect procedures 	
Investigation identified incorrect control room equipment operation	
- Investigation identified maintenance activities that affected control	
room operations, procedures, and/or controller response	

Form PHMSA F 7100.1 Page 3 of 9

- Investigation identified areas other than those above	
Describe:	
PART F - DRUG & ALCOHOL TESTING INFORMATION	
As a result of this Incident, were any Operator employees tested under the post-accident drug and alcohol testing requirements of DOT's Drug & Alcohol Testing regulations?	No
- If Yes:	
1a. How many were tested: 1b. How many failed:	
-	
As a result of this Incident, were any Operator contractor employees tested under the post-accident drug and alcohol testing requirements of DOT's Drug & Alcohol Testing regulations? Contract Contrac	No
- If Yes:	
2a. How many were tested: 2b. How many failed:	
PART G - CAUSE INFORMATION	
Select only one box from PART G in shaded column on left representing the Appright. Describe secondary, contributing, or root causes of the Incident in the narra	
Apparent Cause:	G8 - Other Incident Cause
G1 - Corrosion Failure - only one sub-cause can be picked from shaded le	ft-hand column
Corrosion Failure Sub-Cause:	
- If External Corrosion:	
Results of visual examination:	
- If Other, Specify:	
2. Type of corrosion:	
- Galvanic	
- Atmospheric	
- Stray Current	
- Microbiological	
- Selective Seam	
- Other	
- If Other, Describe:	
The type(s) of corrosion selected in Question 2 is based on the following: Field examination	
- Determined by metallurgical analysis	
- Other	
- If Other, Describe:	
4. Was the failed item buried under the ground?	
- If Yes:	
4a. Was failed item considered to be under cathodic protection at the time of the incident? - If Yes, Year protection started:	
4b. Was shielding, tenting, or disbonding of coating evident at the point of the incident?	
4c. Has one or more Cathodic Protection Survey been conducted at the point of the incident?	
If "Yes, CP Annual Survey" – Most recent year conducted:	
If "Yes, Close Interval Survey" – Most recent year conducted:	
If "Yes, Other CP Survey" – Most recent year conducted:	
- If No:	
4d. Was the failed item externally coated or painted?	
5. Was there observable damage to the coating or paint in the vicinity of the corrosion?	
Pipeline coating type, if steel pipe is involved:	
- If Other, Describe:	
- If Internal Corrosion:	
7. Results of visual examination:	
- If Other, Describe:	
8. Cause of corrosion (select all that apply):	T
- Corrosive Commodity	

Form PHMSA F 7100.1 Page 4 of 9

- Water drop-out/Acid

- Microbiological	
- Erosion	
- Other	
- If Other, Specify:	
	ologia all that apply
9. The cause(s) of corrosion selected in Question 8 is based on the following: (s	еїестан татарру). Т
- Field examination	
- Determined by metallurgical analysis	
- Other	
- If Other, Describe:	
10. Location of corrosion (select all that apply):	
- Low point in pipe	
- Elbow	
- Drop-out	
- Other	
- If Other, Describe:	
11. Was the gas/fluid treated with corrosion inhibitor or biocides?	
12. Were any liquids found in the distribution system where the Incident	
occurred?	
Complete the following if any Corrosion Failure sub-cause is selected AND the Question 2) is Main, Service, or Service Riser.	ne "Part of system involved in incident" (from PART C,
13. Date of the most recent Leak Survey conducted	
14. Has one or more pressure test been conducted since original construction	
at the point of the Incident?	
- If Yes:	
Most recent year tested:	
Test pressure:	
G2 – Natural Force Damage – only one sub-cause can be picked from sha	ded left-handed column
Natural Force Damage – Sub-Cause:	
- If Earth Movement, NOT due to Heavy Rains/Floods:	
1. Specify:	
- If Other, Specify:	
- If Heavy Rains/Floods:	
2. Specify:	
- If Other, Specify:	
- If Lightning:	T
3. Specify:	
- If Temperature:	
4. Specify:	
- If Other, Specify:	
- If Other Natural Force Damage:	
5. Describe:	
Complete the following if any Natural Force Damage sub-cause is selected.	
, ,	T
6. Were the natural forces causing the Incident generated in conjunction with	
an extreme weather event?	<u> </u>
6.a If Yes, specify (select all that apply):	
- Hurricane	
- Tropical Storm	
- Tornado	
- Other	
- If Other, Specify:	
G3 - Excavation Damage - only one sub-cause can be picked from shaded	d left-hand column
Excavation Damage – Sub-Cause:	
- If Previous Damage due to Excavation Activity: Complete the following O Question 2) is Main, Service, or Service Riser.	NLY IF the "Part of system involved in Incident" (from Part C,
Date of the most recent Leak Survey conducted	
2. Has one or more pressure test been conducted since original construction	
at the point of the Incident?	
- If Yes:	
Most recent year tested:	
Test pressure:	

Form PHMSA F 7100.1 Page 5 of 9

Complete the following if Excavation Damage by Third Party is selected.	
3. Did the operator get prior notification of the excavation activity?	
3a. If Yes, Notification received from: (select all that apply):	
- One-Call System	
- Excavator	
- Contractor	
- Landowner	
Complete the following mandatory CGA-DIRT Program questions if any Exca	vation Damage sub-cause is selected.
Do you want PHMSA to upload the following information to CGA-DIRT (www.cga-dirt.com)?	
5. Right-of-Way where event occurred (select all that apply):	
- Public	
- If Public, Specify:	
- Private	
- If Private, Specify:	
- Pipeline Property/Easement	
- Power/Transmission Line	
- Railroad	
- Dedicated Public Utility Easement	
- Federal Land - Data not collected	
- Data not collected - Unknown/Other	
6. Type of excavator:	
7. Type of excavation equipment:	
Type of excavation equipment: Type of work performed:	
Was the One-Call Center notified?	
9a. If Yes, specify ticket number:	
9b. If this is a State where more than a single One-Call Center exists, list	
the name of the One-Call Center notified:	
10. Type of Locator:	
11. Were facility locate marks visible in the area of excavation?	
12. Were facilities marked correctly?	
13. Did the damage cause an interruption in service?	
13a. If Yes, specify duration of the interruption:	First Level COA DIDT Deed Occurs and the constraint and the coast of t
14. Description of the CGA-DIRT Root Cause (select only the one predominant to	Irst level CGA-DIRT Root Cause and then, where available as a
choice, the one predominant second level CGA-DIRT Root Cause as well):	
Root Cause Description: If One-Call Notification Practices Not Sufficient, specify:	
If Locating Practices Not Sufficient, specify:	
- If Excavation Practices Not Sufficient, specify:	
- If Other/None of the Above, explain:	
in outditation of the reports, explain.	
G4 - Other Outside Force Damage - only one sub-cause can be selected	from the shaded left-hand column
Other Outside Force Damage – Sub-Cause:	
- If Damage by Car, Truck, or Other Motorized Vehicle/Equipment NOT Eng	aged in Excavation:
Vehicle/Equipment operated by:	
- If Damage by Boats, Barges, Drilling Rigs, or Other Maritime Equipment of Mooring:	r Vessels Set Adrift or Which Have Otherwise Lost Their
Select one or more of the following IF an extreme weather event was a factor:	
- Hurricane	
- Tropical Storm	
- Tornado	
- Heavy Rains/Flood	
- Other	
- If Other, Specify:	
- If Previous Mechanical Damage NOT Related to Excavation: Complete the Part C, Question 2) is Main, Service, or Service Riser.	following ONLY IF the "Part of system involved in Incident" (from
Date of the most recent Leak Survey conducted:	
4. Has one or more pressure test been conducted since original construction	
at the point of the Incident?	
- If Yes:	
Most recent year tested:	
Test pressure (psig):	

Form PHMSA F 7100.1 Page 6 of 9

- If Intentional Demons	1
- If Intentional Damage: 5. Specify:	
5. Specify: - If Other, Specify:	
- If Other Outside Force Damage:	
6. Describe:	
G5 - Pipe, Weld, or Joint Failure - only one sub-cause can be selected fro	m the shaded left-hand column
Pipe, Weld or Joint Failure – Sub-Cause:	
- If Body of Pipe:	
1. Specify:	
- If Other, Describe:	
- If Butt Weld: 2. Specify:	
- If Other, Describe:	
- If Fillet Weld:	
3. Specify:	
- If Other, Describe:	
- If Pipe Seam: 4. Specify:	
- If Other, Describe:	
- If Mechanical Fitting:	
Specify the mechanical fitting involved:	
- If Other, Describe: 6. Specify the type of mechanical fitting:	
Specify the type of mechanical fitting. If Other, Describe:	
7. Manufacturer:	
8. Year manufactured:	
9. Year Installed: 10. Other attributes:	
11. Specify the two materials being joined:	
11a. First material being joined:	
- If Other, Specify:	
- If Other Plastic, specify:	
11c. Second material being joined:	
- If Other, Specify:	
- If Other Plastic, Specify:	
12. If used on plastic pipe, did the fitting – as designed by the manufacturer –	
include restraint?	
12a. If Yes, specify:	
- If Compression Fitting: 13. Fitting type:	
14. Manufacturer:	
15. Year manufactured:	
16. Year installed: 17. Other attributes:	
Other attributes. 18. Specify the two materials being joined:	<u>L</u>
18a. First material being joined:	
- If Other, specify:	
18b. If Plastic, specify: - If Other Plastic, specify:	
18c. Second material being joined:	
If Other, specify:	
18d. If Plastic, specify: - Other Plastic, specify:	
- Other Plastic, specify.	<u>L</u>
19. Specify:	
- If Other, Specify:	
20. Year installed: 21. Other attributes:	
21. Other attributes: 22. Specify the two materials being joined:	
== = = = = = = = = = = = = = = = = = =	ı

Form PHMSA F 7100.1 Page 7 of 9

22a. First material being joined:	
- If Other, Specify:	
22b. Second material being joined:	
- If Other, Specify:	
- If Other Pipe, Weld, or Joint Failure:	
23. Describe:	
Complete the following if any Pipe, Weld, or Joint Failure sub-cause is select	ed.
24. Additional Factors (select all that apply):	
- Dent	
- Gouge	
- Pipe Bend	
- Arc Burn	
- Crack	
- Lack of Fusion	
- Lamination	
- Buckle - Wrinkle	
- Willikie - Misalignment	
- Burnt Steel	
- Other	
- If Other, Specify:	
25. Was the Incident a result of:	
- Construction defect	
Specify:	
- Material defect	
Specify:	
- If Other, Specify:	
- Design defect	
- Previous damage	
26. Has one or more pressure test been conducted since original construction	
at the point of the Incident?	
- If Yes:	
Most recent year tested: Test pressure:	
rest pressure.	
G6 - Equipment Failure - only one sub-cause can be selected from the shad	ded left-hand column
Equipment Failure – Sub-Cause:	
- If Malfunction of Control/Relief Equipment:	
Specify:	
- Control Valve	
- Instrumentation	
- SCADA	
- Communications	
- Block Valve	
- Check Valve	
- Relief Valve	
- Power Failure	
- Stopple/Control Fitting	
- Stopple/Control Fitting - Pressure Regulator	
- Stopple/Control Fitting - Pressure Regulator - Other	
- Stopple/Control Fitting - Pressure Regulator - Other - If Other, Specify:	
- Stopple/Control Fitting - Pressure Regulator - Other - If Other, Specify: - If Threaded Connection Failure:	
- Stopple/Control Fitting - Pressure Regulator - Other - If Other, Specify: - If Threaded Connection Failure: 2. Specify:	
- Stopple/Control Fitting - Pressure Regulator - Other - If Other, Specify: - If Threaded Connection Failure: 2. Specify: - If Other, Specify:	
- Stopple/Control Fitting - Pressure Regulator - Other - If Other, Specify: - If Threaded Connection Failure: 2. Specify: - If Other, Specify: - If Other, Specify:	
- Stopple/Control Fitting - Pressure Regulator - Other - If Other, Specify: - If Threaded Connection Failure: 2. Specify: - If Non-threaded Connection Failure: 3. Specify:	
- Stopple/Control Fitting - Pressure Regulator - Other - If Other, Specify: - If Threaded Connection Failure: 2. Specify: - If Other, Specify: - If Other, Specify:	
- Stopple/Control Fitting - Pressure Regulator - Other - Other - If Other, Specify: - If Threaded Connection Failure: 2. Specify: - If Non-threaded Connection Failure: 3. Specify: - If Other, Specify: - If Other, Specify:	
- Stopple/Control Fitting - Pressure Regulator - Other - Other - If Other, Specify: - If Threaded Connection Failure: 2. Specify: - If Other, Specify: - If Other, Specify: - If Other, Specify: - If Other, Specify: - If Valve: 4. Specify:	
- Stopple/Control Fitting - Pressure Regulator - Other - If Other, Specify: - If Threaded Connection Failure: 2. Specify: - If Non-threaded Connection Failure: 3. Specify: - If Other, Specify:	
- Stopple/Control Fitting - Pressure Regulator - Other - If Other, Specify: - If Threaded Connection Failure: 2. Specify: - If Non-threaded Connection Failure: 3. Specify: - If Other, Specify:	
- Stopple/Control Fitting - Pressure Regulator - Other - If Other, Specify: - If Threaded Connection Failure: 2. Specify: - If Non-threaded Connection Failure: 3. Specify: - If Other, Specify:	
- Stopple/Control Fitting - Pressure Regulator - Other - If Other, Specify: - If Threaded Connection Failure: 2. Specify: - If Non-threaded Connection Failure: 3. Specify: - If Other, Specify:	

Form PHMSA F 7100.1 Page 8 of 9

5. Describe:	
G7 - Incorrect Operation - only one sub-cause can be selected from the sha	aded left-hand column
Incorrect Operation Sub-Cause:	
- If Other Incorrect Operation:	
1. Describe:	
Complete the following if any Incorrect Operation sub-cause is selected.	
2. Was this Incident related to: (select all that apply)	
- Inadequate procedure	
- No procedure established	
- Failure to follow procedure	
- Other	
- If Other, Describe:	
What category type was the activity that caused the Incident:	
4. Was the task(s) that led to the Incident identified as a covered task in your	
Operator Qualification Program?	
4a. If Yes, were the individuals performing the task(s) qualified for the task (s)?	
G8 - Other Incident Cause - only one sub-cause can be selected from the s	shaded left-hand column
Other Incident Cause – Sub-Cause:	Unknown
- If Miscellaneous:	
1. Describe:	
- If Unknown:	
2. Specify:	Still under investigation, cause of Incident to be determined* (*Supplemental Report required)
DADT LL MADDATIVE DESCRIPTION OF THE INCIDENT	

PART H - NARRATIVE DESCRIPTION OF THE INCIDENT

On August 26, 2020 Dominion Energy Utah (DEU) was notified of a house fire at 1375 W 570 N, Provo, Utah. DEU sent a technician to the site. Upon arrival the technician noted that the fire department had closed the service valve and that the meter was damaged and melted due to the fire. The fire department had also closed the service valve on the meter set at the neighboring house due to fire damage to the structure. The home was a total loss and total estimated damage valued at \$500,000. DEU made the NRC notification due to the estimated cost of damages. DEU crews leak screened the area and pressure tested the service line with no leaks found. DEU then retired the service line to the residence and the neighboring residence.

At this time, the cause of the fire is unknown and the incident is still under investigation. DEU will update the report accordingly after additional information is provided from the investigation.

PART I - PREPARER AND AUTHORIZED SIGNATURE		
Preparer's Name	Lauren Skufca	
Preparer's Title	Engineer Pipeline Compliance	
Preparer's Telephone Number	2166338865	
Preparer's E-mail Address	lauren.l.skufca@dominionenergy.com	
Preparer's Facsimile Number		
Authorize Signature's Name	Reid Hess	
Authorized Signature's Title	Manager Compliance	
Authorized Signature's Email Address	reid.hess@dominionenergy.com	

Form PHMSA F 7100.1 Page 9 of 9