

P.S.C.U. Docket No. 04-057-04  
Data Request No. 2.2  
Requested by Division of Public Utilities  
Date of QGC Response October 4, 2004

2.2 Provide a list of all Oak Springs Compressor failures since the station went into operation. Include (1) the dates of the failures, (2) cause of the failure, (3) duration (4) the specific compressors that were out, and (5) an the volumes that flowed to Payson Gate and the Indianola gate during the period of the outage.

Answer: See attached.

Prepared by: Jon Wheeler, Supervisor Gas Control, Questar Regulated Services