P.S.C.U. Docket No. 17-057-09 DPU Data Request No. 4.01 Requested by Division of Public Utilities Date of DEU Response September 6, 2017

DPU 4.01: Referring to the rebuttal testimony of Michael Platt at page 3, line 16 to page 4, line 12. For the period covering 1997/98 heating season through the 2016/17 heating season, please provide:

- a. Each and every circumstance in which firm sales customers' gas services were curtailed due to lack of pipeline and/or storage capacity. For each such event, provide a detailed description of the circumstances in which such curtailment occurred.
- b. Each and every circumstance in which firm transportation customers' gas services were curtailed due to lack of pipeline and/or storage capacity. For each such event, provide a detailed description of the circumstances in which such curtailment occurred.
- c. Each and every circumstance with a request for firm sales service was denied due to lack of pipeline and/or storage capacity. For each such denial of customer service request(s), provide a detailed description of the circumstances in which such denial occurred.
- d. Each and every circumstance with a request for firm transportation service was denied due to lack of pipeline and/or storage capacity. For each such denial of customer service request(s), provide a detailed description of the circumstances in which such denial occurred.

Answer:

- a. Firm sales customers' gas service has not been curtailed due to lack of pipeline capacity and/or storage capacity.
- b. Firm transportation customers' gas service has not been curtailed due to lack of pipeline capacity and/or storage capacity. These customers have been curtailed in the past because all or a portion of their supply was not delivered to Dominion Energy's system.
- c. See DPU 4.01 Attachment. If the Division seeks greater detail, Company personnel are available to discuss.
- d. See DPU 4.01 Attachment. If the Division seeks greater detail, Company personnel are available to discuss.

Prepared by: Mike Platt, Manager, Engineer Systems