

NOTICE: This report is required by 49 CFR Part 192.1009. Failure to report can result in a civil penalty not to exceed 100,000 for each violation for each day that such violation persists except that the maximum civil penalty shall not exceed \$1,000,000 as provided in 49 USC 60122.		OMB NO: 2137-0522 EXPIRATION DATE: 8/31/2020
 U.S Department of Transportation Pipeline and Hazardous Materials Safety Administration	Initial Submitted Date:	02/28/2020
	Form Type:	INITIAL
	Submitted Date:	
MECHANICAL FITTING FAILURE REPORT FOR CALENDAR YEAR 2019 FOR DISTRIBUTION OPERATORS		
A federal agency may not conduct or sponsor, and a person is not required to respond to, nor shall a person be subject to a penalty for failure to comply with a collection of information subject to the requirements of the Paperwork Reduction Act unless that collection of information displays a current valid OMB Control Number. The OMB Control Number for this information collection is 2137-0522. Public reporting for this collection of information is estimated to be approximately 1 hour per response, including the time for reviewing instructions, gathering the data needed, and completing and reviewing the collection of information. All responses to this collection of information are mandatory. Send comments regarding this burden estimate or any other aspect of this collection of information, including suggestions for reducing this burden to: Information Collection Clearance Officer, PHMSA, Office of Pipeline Safety (PHP-30) 1200 New Jersey Avenue, SE, Washington, D.C. 20590.		
PART A – OPERATOR INFORMATION		(DOT use only)
		2019102112876116862-116816
1. Name of Operator	DOMINION ENERGY UTAH/WYOMING/IDAHO	
3. OPERATOR'S 5 DIGIT IDENTIFICATION NUMBER	12876	
4. HEADQUARTERS NAME & ADDRESS		
4a. Street Address	333 SOUTH STATE STREET, P.O. BOX 45360	
4b. City and County	SALT LAKE CITY,US	
4c. State	UT	
4d. Zip Code	84111	
PART B – PREPARER AND AUTHORIZED SIGNATURE		
_____ Steve Bursett, Operations Supervisor (Preparer's Name and Title)		_____ (801)324-3697 (Area Code and Telephone Number)
_____ steve.bursett@dominionenergy.com (Preparer's email address)		_____ (Area Code and Facsimile Number)
PREPARER'S ADDRESS:		
Number and Street	1140 W 200 S	
City and County	SALT LAKE CITY, United States	
State	UT	
Zip Code	84111	

PART C – MECHANICAL FITTING FAILURE DATA	
1. STATE IN WHICH FITTING FAILED:	UT
2. DATE OF FAILURE:	10/21/2019
3. SPECIFY THE MECHANICAL FITTING:	Nut Follower
4. SPECIFY THE TYPE OF MECHANICAL FITTING:	Tapping Tee
5. LEAK LOCATION:	a)Belowground b)Outside c)Main-to-Service
6. YEAR INSTALLED:	2003
7. YEAR MANUFACTURED:	
8. IF YEAR MANUFACTURED OR YEAR INSTALLED IS NOT KNOWN THEN, DECADE INSTALLED:	
9. MANUFACTURER:	CONTINENTAL (CONTINENTAL INDUSTRIES)
10. PORT OR MODEL NUMBER:	Unavailable
11. LOT NUMBER:	Unavailable
12. OTHER ATTRIBUTES:	Unavailable
13. FITTING MATERIAL:	Combination Plastic and Steel
14. SPECIFY THE TWO MATERIALS BEING JOINED	
A) FIRST PIPE	
-NORMAL SIZE:	3/4"
-UNIT:	NPS
-MATERIAL:	Plastic
-IF PLASTIC, SPECIFY:	Polyethylene (PE)
B) SECOND PIPE	
-NORMAL SIZE:	2"
-UNIT:	NPS
-MATERIAL:	Steel
-IF PLASTIC, SPECIFY:	
15. APPARENT CAUSE OF LEAK:	Incorrect Operation
Reports submitted during 2011 and 2012 with a cause of "Material or Weld" and leak due to "Construction/Installation Defect" have been changed by PHMSA to a cause of "Incorrect Operation".	
16. HOW DID THE LEAK OCCUR?	Pull Out
17. OPERATOR'S INTERNAL MECHANICAL FITTING FAILURE TRACKING NUMBER (OPTIONAL):	71061