

Photo 7
1/25/07

1 Failed insulator pin
2491 E. Fisher Ln




Photo 8
1 Failed Insulator Pin
2483 E. Fisher Lane




Photo 9
Multiple Outages
3 Failed insulators

2447 Fisher Lane

Photo 10 2447 E. Fisher Lane
Multiple Outages
3 Failed Insulators
Next to Rosecrest School





Photo 11 - North side of
2940 S. 2300 E.
Next to Rosecrest school

(Photo 12) North side of
2940 S. 2300 E.
2 Failed insulator pins

