

Photo 50

Pole with over  
1 foot of ground  
wire missing. thus  
rendering the ground  
impotent — posing  
an unnecessary hazard.

(corner of 23rd E.  
& Fisher Lane - S.E.  
quadrant) by home  
formerly owned by  
Sorenson family.



FRACTURED GROUND WIRE (section  
[Exhibit F] Missing)



No ground wire  
in this gap

