

**ELECTRIC SERVICE SCHEDULE NO. 4 - Continued**

**ANNUAL CHARGE:** For each Company pole on which the attaching entity has placed an attachment, **\$8.10** per foot of space used by the attaching entity. “Space used” is determined under (I) the provisions of Utah Admin. Code § R746-345-5.A.3.

**SCHEDULE OF NON-RECURRING FEES:** For each Company pole on which the (N) attaching entity has placed or requests to place an attachment, the following fees may be applied.

**1. Inspections**

In instances when the Company has sufficient electronic pole attachment data in its records, the Company may elect to perform a Desktop Inspection, which is an inspection performed using only existing electronic data, maps and pictures. There is no fee associated with a Desktop Inspection. In instances when the Company does not have sufficient data to perform a Desktop Inspection or the Desktop Inspection results in findings that require a field visit, additional inspection fees apply as shown.

**a. Pre-Construction Inspection:** One of the following three fees is applicable to each application to attach to the Company’s poles or when a Licensee wishes to modify an existing attachment to verify Licensee-reported field conditions of the poles and to determine the extent of make-ready work necessary.

**i. Level 1 (Visual Inspection)**

Charge: \$31.30 first pole; \$17.65 each pole thereafter in the same application.

Level 1 inspection is defined as a “drive by” that does not require the inspector to exit the vehicle and are intended to identify that clearances and strength of the structure are visibly verifiable. These inspections are typically performed when the Licensee has provided all required information given the type of request on the Application form.

**ii. Level 2 (Measured Inspection)**

Charge: \$41.20 first pole; \$30.40 each pole thereafter in the same application.

Level 2 inspections are most commonly performed when the data submitted for the poles does not appear to provide proper clearance to accommodate the newly proposed attachment or when the Licensee has failed to provide all required information given the type of request on the Application form.

**iii. Level 3 (Pole Analysis Inspection)**

Charge: \$88.55 first pole; \$75.90 each pole thereafter in the same application.

Level 3 inspections are most commonly performed when the poles do not appear to have proper strength to accommodate the newly proposed attachment or when the Licensee has failed to provide all required information given the type of request on the Application form. This level of inspection is highly common on requests for use of transmission poles.

(continued)

(N)