



PublicService Commission <psc@utah.gov>

Fwd: PUC_UT.112316.002_I

1 message

Gary Widerburg <gwiderburg@utah.gov>
To: PublicService Commission <psc@utah.gov>

Wed, Nov 23, 2016 at 8:16 AM

----- Forwarded message -----
From: <Regulatory.NEMC@centurylink.com>
Date: Wed, Nov 23, 2016 at 7:46 AM
Subject: PUC_UT.112316.002_I
To: gwiderburg@utah.gov



PUC Report

Report Number : UT.112316.002
Impacted Company : CenturyLink
Date and Time : 22-NOV-2016 14:00:00
TIMEZONE : MST
For Questions Contact : Jim Farr 801 238-0240
Reason for Outage : 175 pair cable cut. Details under investigation.
Notification :
Cause of Outage :
Location of Outage : SALINA/UT
Exchange Name / Wire : SALNUTMARS1
Center :
Expected Duration : 23-NOV-2016 14:00:00
Duration : 0017:40:34
Number of Customers/
Cable pair impacted : 295
Services Affected : LOCAL LOOP
Agencies Notified :
Significant Update :
Resolution :
Restore Date/Time :

--Disclaimer--

--
Gary Widerburg
Commission Secretary

11/23/2016

State of Utah Mail - Fwd: PUC_UT.112316.002_I

Public Service Commission of Utah
[801-530-6713](tel:801-530-6713)