



PublicService Commission &lt;psc@utah.gov&gt;

**Fwd: PUC\_UT.070217.001\_I**

1 message

**Gary Widerburg** <gwiderburg@utah.gov>  
 To: PublicService Commission <psc@utah.gov>

Mon, Jul 3, 2017 at 8:01 AM

----- Forwarded message -----  
 From: <Regulatory.NEMC@centurylink.com>  
 Date: Sun, Jul 2, 2017 at 5:03 PM  
 Subject: PUC\_UT.070217.001\_I  
 To: gwiderburg@utah.gov



## PUC Report

**Report Number** : UT.070217.001  
**Impacted Company** : CenturyLink  
**Date and Time** : 02-JUL-2017 14:56:41  
**TIMEZONE** : MDT  
**For Questions Contact** : Jim Farr 801 238-0240  
**Reason for Outage** : A portion of Brian Head Switch is not processing calls.  
**Notification** :  
**Cause of Outage** :  
**Location of Outage** : BRIAN HEAD/UT  
**Exchange Name / Wire** : BNHDUTMAKAA  
**Center** :  
**Expected Duration** : 03-JUL-2017 19:00:00  
**Duration** : 0002:01:58  
**Number of Customers/**  
**Cable pair impacted** : 202  
**Services Affected** : LOCAL LOOP,FACILITY,ETHERNET  
**Agencies Notified** :  
**Significant Update** :  
**Resolution** :  
**Restore Date/Time** :

--Disclaimer--

--  
 Gary Widerburg  
 Commission Secretary

7/3/2017

State of Utah Mail - Fwd: PUC\_UT.070217.001\_I

Public Service Commission of Utah  
801-530-6713