

'acific Power Utah Power

rquiries to: arah Calloway 503) 813-6940



Invoice

Invoice Date: 12/24/03 Invoice Number: JU 342566

Terms: Net 30 days

	Customer # 10002916					
				# of months		
UC-CC#	PacifiCorp District	Charge	Quantity	attached	Amount	Remarks
77-11421	American Fork	\$26.65	1		\$ 26.65	Application Processing
		\$4.00	43		\$ 172.00	Per Pole Processing
		\$41.20	3		\$ 123.60	Level 2 Inspection
		\$30.40	21		\$ 638.40	Additional Level 2 Inspection
		\$41.20	2		\$ 82.40	Level 5 Inspection
		\$30.40	17		\$ 516.80	Additional Level 5 Inspection

**Total Due This Invoice:** 

\$ 1,559.85

Foreign App#
WR# 002241281
2nd WR#
3rd WR#
NJUNS#
Copco#
Other Foreign #

PREPARED BY:  TELEPHONE #  VENDOR #  CHECK DESC.	Rachelle Dilling 801-401-3028	oham_		DATEJAN 0.7  PAY ALONE 253-	2004 707
	ACCOUNT	DE	PT	AMOUNT	
ENTITY H76	18050	00	00	\$ 1,559.8	
APPROVAL	SIGNATURE	Ē		PRINTED NAME	DATE
LEVEL			Kae	i Majors	
Manager \$0-2K	-		Teresa Mahoney Craig Malang		
BM/Director \$2K -10K					
VP /GM\$10K+			5.4	3	

ayment

Invoice Date	Invoice Number	Payment Due Date	Amount Due
12/24/03	JU 342566	01/24/04	\$1,559.85

Amount Enclosed:

Customer#

10002916

Comcast Accounts Payable 1649 W 4200 S Salt Lake City, Ut 84123 Remit Payment to:

**PacifiCorp** 

Attn: Central Cashiers

PO Box 5504

Portland, OR 97228-5504

POLE ATTACHMENT INSPECTION APPLICATION 2241281 Flu Rev. 05/07/03 Request Number Page 1 of 43 11405002.0 Pole Inspector PPL MAP STRING Inspection Date PPL POLE NUMBER Requesting Licensee POLE ADDRESS PLEASANT CITY UTAH STATE (Circle Analysis Level Below) Is Attachment Approved as Requested by Level of Analysis? Pre Inspection Levels No Post Inspection Levels Yes Yes No 4 or 4a 1 or 1a 5 or 5a 6 or 6a ( If Attachment needs work to be approved, Post Inspections, or has an NESC Infraction, fill out lower section ) Pole Attributes No Yes Pole Height Can Serviceman Modify Service? Pole Class Need to go to Estimator Is Make Ready Work Required By Licensee? Pole Circumference Is Make Ready Work Required By Another Utility? Is There a 12" Separation Violation Between Utilities? Is There a Climbing Space Violation? Is There a Mid Span Violation? Does Pole have an NESC Infraction? Need to Route to Another Utility for corrections ( see notes ) **ATTACHMENT HEIGHTS** Licensee Proposed Attachment Ht. Grounded Mid Span Clr. To Pole No#. Violation 96308 Lowest(Secondary)or Neutral Streetlight Mast Streetlight Drip Loop CATV TELCO **FIBER** OTHER#1 Telco on JHOIR 22'9" OTHER #2 **Guys and Anchors** Service Drops **Violation Guy Size** Ht. Over Rd. Drop Ht. Primary Secondary Lowest Secondary CATV 22110" **TELCO TELCO FIBER FIBER** Other Other #1 No Yes Other #2 Does Licensee Need Breaker In Guy? Does Another Utility Need Breaker In Guy? 'mid span

tan mina

Request Number 2241	28/			Flu Rev. 05/07/03	
Page 2 of 43				1/	
PPL MAP STRING	5002.0		Pole Inspector	Ren	Bell 2003
PPL POLE NUMBER /96	308	· ·	Inspection Date	<u> フ-ヱ-</u>	2003
POLE ADDRESS 110	1300	لك	Requesting Licensee	AT&I	OVERLASH
CITY PLEASA	INT GROVE				
STATE UTAH					
		Analysis Level Bel			
/ Is Pre Inspection L	Attachment Approve	d as Requested by Yes No		ection Levels	; Yes No
1 or 1a	cveis		•	or 4a	
2 or (2a)			5	or 5a	
3 or 3a				or 6a	
( If Attachment needs wo	rk to be approved, Pos				)
Can Serviceman Modify Service?		Yes No	<u>Pole Attrib</u> Pole Height	utes	45'
Need to go to Estimator		一一一	Pole Class		3
Is Make Ready Work Required By Lice	nsee?	まま は は は は は は は は は は は は は は は は は は	Pole Circumferer	nce	
Is Make Ready Work Required By Anol					
Is There a 12" Separation Violation Bet					
Is There a Climbing Space Violation?					
Is There a Mid Span Violation?					
Does Pole have an NESC Infraction?					
Need to Route to Another Utility for con					
ATTACHMENT	HEIGHTS				
Licensee Proposed Attachment Ht.		rounded	Mid Span Clr.	To Pole No#.	Violation
Lowest Secondary or Neutral	24'	> New to	1. 24'	196207	
Streetlight Mast					
Streetlight Drip Loop					
CATV	251211		201211		
TELCO	53,81,0		20. 2		
FIBER OTHER #1		<b>=</b>			
OTHER #2		H			H
Service Drops	0161	<u> </u>	Guys a	ind Anchors	<u></u>
Drop Ht.	Ht. Over. Ref.	^७ । ⁄iolation	Leads	Guy Size	JA
Secondary	23'10"	Primary	****		
CATV		Lowest Se	condary		
TELCO	20'1"	TELCO	-		
FIBER		FIBER			
Other #1		Other			res No
Other #2		Does Licens	ee Need Breaker In Gu	-	
			er Utility Need Breaker II	<u>-</u>	
NOTES:		00007210411			
Telco 40"cl	Pavance	. 1/in	lation		
161C0 -10 C1	- will t				
		·			

Request Number 2241	28/			Flu Rev. 05/07/03	
Page 3 of 43					
PPL MAP STRING 1140	5002.0		Pole Inspector	<u>Ken</u>	Bell
	207		Inspection Date	7-2	- 2002
POLE ADDRESS 22	<u> </u>	20 W.	Requesting Licensee	ATET	OVERLASH
CITY PLEAS	~				0 0 317-117
	ANI OROS				
STATE UTAH	( Cir	rcle Analysis Level Be	low)		
l:		roved as Requested by	Level of Analysis?		:
Pre Inspection I	Levels	Yes No		ection Levels or 4a	Yes No
1 or 1a				or4a or5a	
2 or 2a) 3 or 3a	Į.			or 6a	
( If Attachment needs w	and to be approved	Poet legactions of ha			<u>,                                    </u>
( It Attachment needs w	ork to be approved,	Yes No	Pole Attrib		,
Can Serviceman Modify Service?			Pole Height		45
Need to go to Estimator			Pole Class		3
Is Make Ready Work Required By Lice	ensee?		Pole Circumfere	nce	
Is Make Ready Work Required By And	other Utility?				
Is There a 12" Separation Violation Be	tween Utilities?				
Is There a Climbing Space Violation?					
Is There a Mid Span Violation?					
Does Pole have an NESC Infraction?					
Need to Route to Another Utility for co	rrections ( see note:	s)			
ATTACHMENT	HEIGHTS				
Licensee Proposed Attachment Ht.		Grounded	Mid Span Ctr.	To Pole No#.	Violation
Lowest Secondary of Neutral	3212"	$\bowtie$	27'2"	196206	
Streellight Mast					
Streetlight Drip Loop					
CATV			****		
TELCO	27'4"	<u>                                     </u>			
FIBER		<u> </u>			
OTHER #1		<u> </u>			
OTHER #2	<u> </u>		Giner	and Anchors	L
Service Drops	Ht. Over Rd.	Violation	Leads	Guy Size	JA
Drop Ht.	HL OVEI Ku.	Primary	Leads	7/16/1	
Secondary		Lowest Se	condary		<b>  </b>
TELCO		TELCO			
FIBER	<del></del>	FIBER	Toppen to a description of the second	•	
Other #1		Other	*********************************		
Other #2				`	res No
		Does Licens	ee Need Breaker In Guy	?	
		Does Anothe	er Utility Need Breaker I	n Guy?	
NOTES:					

Request Number 224	128/			Flu Rev. 05/07/03	
Page 4 of 43					
PPL MAP STRING 1140	15002.0		Pole Inspector	Ken	Bell
	206	*	Inspection Date	ブー・	2 - 2007
POLE ADDRESS 321	13000	W	Requesting Licensee	ATAT	OVERLASH
CITY PLEAS	<u> </u>				- V = (\ - K - J   )
	AIVI OROVE	-			
STATE UTAH	( Circle	Analysis Level Be	elow)		
	Is Attachment Approv				;
Pre Inspection		Yes No	-	ection Levels or 4a	Yes No
1 or 1a 2 or(2a				or 5a	
3 or 3a	·			or 6a	
		st Inspections, or h	as an NESC Infraction, fil		 
( II Allachment needs in	ork to be approved, i e	Yes No	Pole Attrib		,
Can Serviceman Modify Service?			Pole Height		45
Need to go to Estimator			Pole Class		3
Is Make Ready Work Required By Lic	ensee?		Pole Circumferer	nce	
Is Make Ready Work Required By An					
Is There a 12" Separation Violation Be	etween Utilities?				
Is There a Climbing Space Violation?					
Is There a Mid Span Violation?					
Does Pole have an NESC Infraction?					
Need to Route to Another Utility for co	rrections (see notes)				
ATTACHMENT	THEIGHTS				
Licensee Proposed Attachment Ht.		Grounded	Mid Span Clr.	To Pole No#.	Violation
Lowest Secondary of Neutral	29'8'	X	25/611	196205	
Streetlight Mast		F			' <del>                                     </del>
Streetlight Drip Loop		Longitude Control			
CATV					
TELCO					
FIBER					
OTHER #1			***************************************		
OTHER #2			**************************************		
Service Drops				ind Anchors	
Drop Ht.	Ht. Over Rd.	Violation	Leads	Guy Size	JA
Secondary		Primary	-	1/16	
CATV			econdary		
TELCO		TELCO	T		The second secon
FIBER	<u> </u>	FIBER Other	-		
Other #1					L—⊸J ∕es No
Other #2		L_J	one Nord Breeken to Co.	-	res No
			isee Need Breaker In Guy ner Utility Need Breaker In	to the second	
NOTES:		Does Allou	ici dulity i veed breaker ii	L Cuy:	
<b>A</b>					
POLE NOT ON L	.157				

Request Number 2241	28/			Flu Rev. 05/07/03	
Page 5 of 43					_
PPL MAP STRING 1140	5002.0		Pole Inspector	Ker	Bell
	205		Inspection Date	フ・2	-2003
POLE ADDRESS 22/	1300	ow	Requesting Licensee	ATAT	OVERLASH
CITY PLEAS	-				
STATE UTAH	<u> </u>	<del>4</del>			
	•	Analysis Level I			
	• •		by Level of Analysis?		;
Pre Inspection I 1 or 1a	_evels	Yes No		ection Levels or 4a	Yes No
2 or 2a	)	WH.		or 5a	ĦĦ·
3 or 3a	•	戶門	6	or 6a	<del>居居</del>
( If Attachment needs we	ork to be approved, Po	est Inspections, or	has an NESC Infraction, fi	Il out lower section	) )
		Yes No	Pole Attrib	outes	1101
Can Serviceman Modify Service?			Pole Height		40
Need to go to Estimator	•		Pole Class		
Is Make Ready Work Required By Lice			Pole Circumferer	nce	-
Is Make Ready Work Required By And					
Is There a 12" Separation Violation Be Is There a Climbing Space Violation?	tween Ounues:				
Is There a Mid Span Violation?		一一一			
Does Pole have an NESC Infraction?		一一一			
Need to Route to Another Utility for con	rrections (see notes)				
ATTACHMENT	HEIGHTS				
Licensee Proposed Attachment Ht.		Grounded	Mid Span Clr.	To Pole No#.	Violation
	27'	N/	271111	10/010	
Lowest Secondary or Neutral	<u> </u>		- 41	196203	
Streetlight Mast Streetlight Drip Loop		<u></u>	·		
CATV					
TELCO		H	the grant of the design of the		
FIBER					
OTHER #1					
OTHER #2			-		
Service Drops				and Anchors	
Drop Ht.		Violation	Leads	Guy Size	JA
socondary Neutral	24'9"	Priman		_3/8	
CATV		TELCO	Secondary		
TELCO		FIBER	<del></del>		
FIBER Other #1		Other			
Other #2		H	-		(es No
	4	Does Lice	ensee Need Breaker In Gu	v?	
			ther Utility Need Breaker I	•	
NOTES:				_	
			***		

POLE ATTACHMENT INSPECTION APPLICATION 2241281 Request Number Flu Rev. 05/07/03 Pole Inspector PPL MAP STRING Inspection Date PPL POLE NUMBER Requesting Licensee **POLE ADDRESS** CITY STATE TAH (Circle Analysis Level Below) Is Attachment Approved as Requested by Level of Analysis? **Post Inspection Levels** Pre Inspection Levels Yes No No 4 or 4a 1 or 1a 2 or (2a 5 or 5a 6 or 6a ( If Attachment needs work to be approved, Post Inspections, or has an NESC Infraction, fill out lower section ) Pole Attributes Yes No Pole Height Can Serviceman Modify Service? Need to go to Estimator Pole Class Is Make Ready Work Required By Licensee? Pole Circumterence Is Make Ready Work Required By Another Utility? Is There a 12" Separation Violation Between Utilities? Is There a Climbing Space Violation? Is There a Mid Span Violation? Does Pole have an NESC Infraction? Need to Route to Another Utility for corrections ( see notes ) **ATTACHMENT HEIGHTS** Licensee Proposed Attachment Ht To Pole No# Grounded Mid Span Clr. Violation 9610Z Lowest Secondary or Neutral Streetlight Mast Streetlight Drip Loop CATV TELCO Service on J Hook 181 FIBER co OTHER #1 Splice Box CO OTHER #2 Service on THOO Service Drops **Guys and Anchors Violation** Drop Ht. **Guy Size** Ht. Over Rd. Leads Primary Secondary CATV Lowest Secondary **TELCO TELCO FIBER FIBER** Other Other #1 Other #2 Does Licensee Need Breaker In Guy? Does Another Utility Need Breaker In Guy?

NOTES:
Teles or Quest 40" Clearance violation.
and Pole To small.

POLE ATTACHMENT INSPECTION APPLICATION 2241281 Request Number Flu Rev. 05/07/03 Page 7 of 43 11405002.0 Pole Inspector PPL MAP STRING Inspection Date PPL POLE NUMBER Requesting Licensee POLE ADDRESS PLEASANT GROVE CITY WTAH STATE (Circle Analysis Level Below) Is Attachment Approved as Requested by Level of Analysis? **Post Inspection Levels** Yes No **Pre Inspection Levels** No 4 or 4a 1 or 1a 5 or 5a 6 or 6a ( If Attachment needs work to be approved, Post Inspections, or has an NESC Infraction, fill out lower section ) **Pole Attributes** No Yes Pole Height Can Serviceman Modify Service? Pole Class Need to go to Estimator Pole Circumference Is Make Ready Work Required By Licensee? Is Make Ready Work Required By Another Utility? Is There a 12" Separation Violation Between Utilities? Is There a Climbing Space Violation? Is There a Mid Span Violation? Does Pole have an NESC Infraction? Need to Route to Another Utility for corrections ( see notes ) **ATTACHMENT HEIGHTS** Mid Span Clr. To Pole No#. Licensee Proposed Attachment Ht. Grounded Violation Lowest Secondary or Neutral Streetlight Mast Streetlight Drip Loop CATV **TELCO FIBER** OTHER #1 OTHER #2 **Guys and Anchors** Service Drops Drop Ht. Ht. Over Rd. **Violation** Leads **Guy Size** Primary Secondary Lowest Secondary CATV **TELCO TELCO FIBER FIBER** Other Other #1 Yes No Other #2 Does Licensee Need Breaker In Guy? Does Another Utility Need Breaker In Guy? NOTES:

Request Number 2241	28/			Flu Rev. 05/07/03	
Page 8 of 43				1/	<i>Q</i> 11
PPL MAP STRING 1140	5002.0	***************************************	Pole Inspector	Ken	Bell
PPL POLE NUMBER /96	101	•	Inspection Date	7-2	- Z003
POLE ADDRESS	13000	$\overline{\mathcal{U}}$	Requesting Licensee	AT&I	OVERLASH
CITY PLEAS	ANT GROVE				
STATE UTAH					
		Analysis Level B			
	s Attachment Approve			ection Levels	You No
Pre Inspection I 1 or 1a	_eveis	Yes No		or 4a	Yes No
2 or (2a)			5	or 5a	
3 or 3a		H	6	or 6a	
( If Attachment needs we	ork to be approved, Pos	t Inspections, or h	as an NESC Infraction, fi	Il out lower section	)
·		Yes No	Pole Attrib		
Can Serviceman Modify Service?			Pole Height		351
Need to go to Estimator			Pole Class		****
Is Make Ready Work Required By Lice			Pole Circumferer	nce	
Is Make Ready Work Required By And		إحا إحبا			
Is There a 12" Separation Violation Be	tween Utilities?				
Is There a Climbing Space Violation?					
Is There a Mid Span Violation?					
Does Pole have an NESC Infraction?					
Need to Route to Another Utility for con					
ATTACHMENT	HEIGHTS				
Licensee Proposed Attachment Ht.	G	rounded	Mid Span Cfr.	To Pole No#.	Violation
Lowest Secondary or Neutral	23'4"	$\square$	201	196000	
Streetlight Mast					一
Streetlight Drip Loop					
CATV					
TELCO					
FIBER			*****		
OTHER #1	***************************************				
OTHER #2	-		**************************************		
Service Drops				and Anchors	
Drop Ht.	Ht. Over Rd. V	iolation	Leads	Guy Size	JA
Secondary		Primary			<u></u>
CATV		<b>==</b>	Secondary		·
TELCO		TELCO	Annual An		
FIBER		FIBER	-		
Other #1		Other	-		res No
Other #2			and Mand Databas Is Co.		es No
			isee Need Breaker In Guy ner Utility Need Breaker I	<b></b>	러눠
NOTES.		DOES ALION	ier outry reed breaker in	iredy: [	
NOTES:					
				·	
		and the state of t			

POLE ATTACHMENT INSPECTION APPLICATION 2241281 Flu Rev. 05/07/03 Request Number Page 9 of 43 Pole Inspector PPL MAP STRING Inspection Date PPL POLE NUMBER 1300 W Requesting Licensee POLE ADDRESS PLEASANT CITY STATE (Circle Analysis Level Below) Is Attachment Approved as Requested by Level of Analysis? Post Inspection Levels Pre Inspection Levels Yes No Yes No 4 or 4a 1 or 1a 5 or 5a 2 or (2a) 6 or 6a ( If Attachment needs work to be approved, Post Inspections, or has an NESC Infraction, fill out lower section ) Pole Attributes Yes No Can Serviceman Modify Service? Pole Height Pole Class Need to go to Estimator Pole Circumference Is Make Ready Work Required By Licensee? Is Make Ready Work Required By Another Utility? Is There a 12" Separation Violation Between Utilities? Is There a Climbing Space Violation? Is There a Mid Span Violation? Does Pole have an NESC Infraction? Need to Route to Another Utility for corrections ( see notes ) **ATTACHMENT HEIGHTS** Grounded Mid Span Clr. To Pole No#. Violation Licensee Proposed Attachment Ht. 600 Lowest Secondary or Neutral Streetlight Mast Streetlight Drip Loop CATV \* TELCO Service on JHICK eskother#1 Splice Box at OTHER #2 **Guys and Anchors** Service Drops Drop Ht. Ht. Over Rd. **Violation** Leads **Guy Size** Primary Secondary Lowest Secondary CATV **TELCO TELCO FIBER** FIBER Other Other #1 No Yes Other #2 Does Licensee Need Breaker In Guy? Does Another Utility Need Breaker In Guy? NOTES:

Request Number 2241	28/			Flu Rev. 05/07/03	
Page 10 of 43					
PPL MAP STRING 1140	5002.0		Pole Inspector	Ken	Bell
	6001	-,	Inspection Date	フーノ・	2003
POLE ADDRESS /5	5 13000	w w	Requesting Licensee	ATET	OVERLASH
CITY PLEAS	-27				OV CRCASH
	ANT GROVE				
STATE UTAH	( Circle .	 Analysis Level Be	low)		
ı	s Attachment Approve				;
Pre Inspection I	Levels	Yes No	•	ction Levels	Yes No
1 or 1a				r4a r5a	
2 of 2a 3 or 3a	ŀ			r6a	
	and to be approved. Pos	t Inspections or ha	s an NESC Infraction, fill		
( ii Attadiment needs w	ork to be approved, 1 os	Yes No	Pole Attribu		
Can Serviceman Modify Service?			Pole Height		40'
Need to go to Estimator			Pole Class		
Is Make Ready Work Required By Lic			Pole Circumference	æ	
Is Make Ready Work Required By And					
Is There a 12" Separation Violation Be	tween Utilities?				
Is There a Climbing Space Violation?		누			
Is There a Mid Span Violation?		늗			
Does Pole have an NESC Infraction? Need to Route to Another Utility for co	mactions ( see notes )				
ATTACHMENT	HEIGHTS			· · · · · · · · · · · · · · · · · · ·	
Licensee Proposed Attachment Ht.		irounded		o Pole No#.	Violation
Lowes Secondary or Neutral	20'8"	$\bowtie$	19111"	19602	
Streetlight Mast					
Streetlight Drip Loop					
CATV					
TELCO					Service Anni Olifonomeno
FIBER		<b>_</b>			
OTHER #1		<b>  </b>			
OTHER #2			Guys an	d Anchors	
<u>Service Drops</u> Drop Ht.	Ht. Over Rd. V	iolation	Leads	Guy Size	JA
Secondary	191711	Primary		- <b>- -</b> · · · · ·	rii -
CATV		Lowest Se	condary		H
TELCO		TELCO			
FIBER	***************************************	FIBER			
Other #1		Other			
Other #2				Y	es No
		Does Licens	see Need Breaker In Guy?	,	
		Does Anothe	er Utility Need Breaker In	Guy?	
NOTES:					
					<u></u>

Request Number 224128/			Flu Rev. 05/07/03	
Pageof43				
PPL MAP STRING 1140500	2.0	Pole Inspector	Ken	Bell
	2	Inspection Date	7-2	- 2003
POLE ADDRESS 905 1	300 W	Requesting Licensee	AT&T	OVERLASH
CITY PLEASANT	GROVE			
STATE UTAH				•
	(Circle Analysis Level B			
	ent Approved as Requested l Yes No		ection Levels	Yes No
Pre Inspection Levels 1 or 1a		-	or 4a	
2 or (2a)		5	or 5a	
3 or 3a	듬믐	6	or 6a	HH
( If Attachment needs work to be a	pproved, Post Inspections, or h	nas an NESC Infraction, fi	Il out lower section	
	Yes No	Pole Attrib		- •
Can Serviceman Modify Service?		Pole Height		35'
Need to go to Estimator		Pole Class		
Is Make Ready Work Required By Licensee?		Pole Circumfere	nce	***************************************
Is Make Ready Work Required By Another Utility				
Is There a 12" Separation Violation Between Util	ities?			
Is There a Climbing Space Violation?				
Is There a Mid Span Violation?				
Does Pole have an NESC Infraction?			,	
Need to Route to Another Utility for corrections (	see notes )			
ATTACHMENT HEIGHTS		· · · · · · · · · · · · · · · · · · ·		
Licensee Proposed Attachment Ht.	Grounded	Mid Span Clr.	To Pole No#.	Violation
Lowest Secondary or Neutral 22'	411	28'8"	306908	
Streetlight Mast				
Streetlight Drip Loop				
CATV				
TELCO				
FIBER				
OTHER #1				
OTHER #2				
Service Drops		Guys:	and Anchors	
Drop Ht. Ht. Ove	r Rd. Violation	Leads	Guy Size	JA
Secondary 16'	7'1 Primary			
CATV	Lowest	Secondary		
TELCO	TELCO	-		
FIBER	FIBER			
Other #1 Secondary 16'	611 Other			
Other #2			•	Yes No
	Does Lice	nsee Need Breaker In Gu	y? [	
	Does Anol	ther Utility Need Breaker	In Guy?	
NOTES:	4			٨
Telco old J-Hoa	K Needs	to be Re	movee	X
, , , , , , , , , , , , , , , , , , , ,	· · · · · · · · · · · · · · · · · · ·			

	Request Number	2241	28/				Flu Rev. 05/07/03	
	Page 12 of 43							
	PPL MAP STRING	1140	5002.0	<u> </u>		Pole Inspector	Ken	Bell
	PPL POLE NUMBER	306	908	**	ı	nspection Date	7-	2-2003
	POLE ADDRESS	923	5 130	ow.	Reque	esting Licensee	AT&T	OVERLASH
	CITY	PLEAS	ANT GR	OVE				
	STATE	UTAH						
	-				s Level Below)	of Analysis 2		
	D.e.	ا e Inspection I		pproved as Ke Yes	quested by Level No		ection Levels	Yes No
		1 or 1a	_eveis	1.23	רדוו	•	or 4a	
		2 0/23	<b>Y</b>	$\overline{\mathbb{Z}}$	iff	5	or 5a	
		3 or 3a			i 🗂	6	or 6a	
	( If Attach	ment needs w	ork to be approve	ed, Post Inspec	tions, or has an NE	SC Infraction, fi	Il out lower section	)
	·			Yes	No	Pole Attrib	outes	701
	Can Serviceman Modify	y Service?			! <del></del>	Pole Height		<u> 35'</u>
	Need to go to Estimator		_			Pole Class		
	Is Make Ready Work Re				<u>                                   </u>	Pole Circumfere	nce	
	Is Make Ready Work Re			ļ.	<b>  </b>			
	Is There a 12* Separation		tween Utilities?		H			
	Is There a Climbing Spa							
	Is There a Mid Span Vio Does Pole have an NES				H			
	Need to Route to Anothe		rections / see no	otes )	H			
				,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,				
		TTACHMENT	HEIGHTS					
	Licensee Proposed Atta	chiment Ht.		Grounde	d A	Mid Span Clr.	To Pole No#.	Violation
	Lowest Secondary or Ne	eutral	20'81	' ⊠	. <u> </u>	22181	306902	
	Streetlight Mast				-	·		
	Streetlight Drip Loop							
	CATV							
•	TELCO		181911					
	FIBER							
	OTHER #1							
	OTHER #2			L			and Anchors	
	Service Dro	<del></del>	Ht. Over Rd.	Violation		Leads	Guy Size	JA
	<b>.</b>	Drop Ht.	Ht. Over Ru.	Violation	Primary	Ecaus	ouy oize	
	Secondary CATV				Lowest Secondary	·		
	TELCO				TELCO			
	FIBER				FIBER	<del></del>		
	Other #1			H	Other	•	*	
	Other #2			一一			,	Yes No
	5 41 <b>5</b> 1 112		Annual Control of the		oes Licensee Nee	d Breaker In Gu	y? [	$\neg \sqcap$
					oes Another Utility		<u>-</u>	ゴ苣
1	NOTES:						_	
	al'ash'	C 100 a	o Wiol	ation	Tree	e ava	Walan C	abaumal
-	DILAKO, WA	3 /0 1	7 7 2 7	(2,1,47)		315	<del>3 10 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3</del>	
_	Base ot	Pol	<u>e                                     </u>					
-				2				
-								
-				<u> </u>	The state of the s	th Constitution and the second se	- our or house continue of a continue of the c	

Λ \_ . .

POLE ATTACHMENT INSPECTION APPLICATION 2241281 Request Number Flu Rev. 05/07/03 Page 13 of 43 11405002.0 Pole Inspector PPL MAP STRING Inspection Date PPL POLE NUMBER 1300 W Requesting Licensee POLE ADDRESS PLEASANT GROVE CITY UTAH STATE (Circle Analysis Level Below) Is Attachment Approved as Requested by Level of Analysis? Post Inspection Levels **Pre Inspection Levels** Yes No 4 or 4a 1 or 1a 5 or 5a 6 or 6a ( If Attachment needs work to be approved, Post Inspections, or has an NESC Infraction, fill out lower section ) Yes No **Pole Attributes** Can Serviceman Modify Service? Pole Height Pole Class Need to go to Estimator Pole Circumference Is Make Ready Work Required By Licensee? Is Make Ready Work Required By Another Utility? Is There a 12" Separation Violation Between Utilities? Is There a Climbing Space Violation? Is There a Mid Span Violation? Does Pole have an NESC Infraction? Need to Route to Another Utility for corrections ( see notes ) **ATTACHMENT HEIGHTS** Mid Span Clr. To Pole No#. Licensee Proposed Attachment Ht. Grounded **Violation** 0680 Lowest Secondary of Neutral Streetlight Mast 02 Streetlight Drip Loop CATV TELCO **FIBER** OTHER #1 OTHER #2 **Guys and Anchors** Service Drops Drop Ht. Ht. Over Rd. **Violation** Leads **Guy Size** Primary Secondary. Lowest Secondary CATY New IVA **TELCO** TELCO overdrive **FIBER FIBER** Other #1 Telco. Other Other #2 Telco Yes No Does Licensee Need Breaker In Guy? Telco Does Another Utility Need Breaker In Guy? NOTES:

Request Number 2241	28/			Flu Rev. 05/07/03	
Page 14 of 43					
PPL MAP STRING /140	5002.0		Pole Inspector	Ken	Bell
PPL POLE NUMBER 30680		4.	Inspection Date		2-2003
POLE ADDRESS PROCTS	r LANE & P.C	BLUD	Requesting Licensee	ATAT	OVERLASH
	ANT GROVE				
	ANT OROVE				4
STATE UTAH	( Circle	Analysis Level Be	elow)		
Į:	s Attachment Approve	ed as Requested b			:
Pre Inspection I	Levels	Yes No	-	ection Levels or 4a	Yes No
1 or 1a 2 or 2a	<b>\</b>	HH		or 5a	
3 or 3a	,			or 6a	
( If Attachment needs w	ork to be approved. Po:	st Inspections, or h			
( ii Attaoiineit fieodo ii	on to be approved to	Yes No	Pole Attrib		11,
Can Serviceman Modify Service?			Pole Height		45
Need to go to Estimator			Pole Class	,	_4
Is Make Ready Work Required By Lice			Pole Circumferen	ce	·
Is Make Ready Work Required By And					
Is There a 12" Separation Violation Be	tween Utilities?				
Is There a Climbing Space Violation?		누러누			
Is There a Mid Span Violation?  Does Pole have an NESC Infraction?					
Need to Route to Another Utility for co	rrections ( see notes )				
ATTACHMENT				1	
Licensee Proposed Attachment Ht.		Grounded		To Pole Noff.	Violation
Lowest Secondary or Neutral	26'2"		TOP OF POLE	306802	
Streetlight Mast			<u></u>		
Streetlight Drip Loop	283"				
CATV					
TELCO					
FIBER		+			H
OTHER #1 OTHER #2					
Service Drops		L)	Guys a	nd Anchors	
Drop Ht.	Ht. Over Rd.	<b>Violation</b>	Leads	Guy Size	JA
Secondary		Primary		•	
CATV		Lowest S	econdary		
TELCO		TELCO			
FIBER		FIBER			
Other #1	***************************************	Other			
Other #2					es No
			see Need Breaker In Guy		_
		Does Anoth	er Utility Need Breaker In	Guy?	
NOTES:					
			,		
	A CONTRACTOR OF THE PARTY OF TH				

Request Number 2241	28/			Flu Rev. 05/07/03	
Page 15 of 43					
	5002.0	ว์	Pole Inspector	Ken	Rell
PPL POLE NUMBER 306	802		Inspection Date		-2003
POLE ADDRESS 210	A	ctor-Ln	Requesting Licensee	AT&T	OVERLASH
CITY PLEAS	7				
	3741 010	<u> </u>			
STATE UTAH	(	Circle Analysis Level B	elow)		
	Attachment A	proved as Requested I	by Level of Analysis?		:
Pre Inspection L	.evels	Yes No	•	pection Levels	Yes No
1 or 1a		닑뉘		or 4a or 5a	
(2) or 2a				or 6a	
3 or 3a ( If Attachment needs wo	nd to be opposite	A Post Inspections or b	_		<u>,</u>
( if Attachment needs wo	ak to be approve	Yes No	Pole Attril		,
Can Serviceman Modify Service?			Pole Height		45
Need to go to Estimator		一一一	Pole Class		4
Is Make Ready Work Required By Lice	ensee?		Pole Circumfere	nce	
Is Make Ready Work Required By And					
Is There a 12" Separation Violation Be					
Is There a Climbing Space Violation?					
Is There a Mid Span Violation?					
Does Pole have an NESC Infraction?					
Need to Route to Another Utility for cor	rections ( see no	otes)		•	
ATTACHMENT	HEIGHTS				
Licensee Proposed Attachment Ht.		Grounded	Mid Span Clr.	To Pole No#.	Violation
Lowest Secondary of Neutral)	39'	12	24'6"	306700	
Streetlight Mast					
Streetlight Drip Loop		<b>L</b>	Commence of the commence of th		
CATV					
TELCO					
FIBER					
OTHER #1					
OTHER #2					
Service Drops			<u>Guys</u> :	and Anchors	
Drop Ht.	Ht. Over Rd.	Violation	Leads	Guy Size	JA
Secondary		Primary	<del></del>		
CATV	· .	<u> </u>	Secondary		
TELCO		TELCO			
FIBER		FIBER			
Other #1		Other			لــا
Other #2				<u></u>	Yes No
			isee Need Breaker In Gu	·	
		Does Anot	her Utility Need Breaker I	n Guy?	
NOTES:					
			<u> </u>		

Request Number 26	14128/			Flu Rev. 05/07/03	
Page 16 of 43					
<del>-</del>	405002.0		Pole Inspector	Kon	Boll
-	06700		Inspection Date	7- 2	-2002
,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	305 Proct		Requesting Licensee	AT&T	OVERLASH
		•	rioquoomig Erranoso		OU CRCASH
	ASANT GROVE				
STATE UT	AH (Circle	 e Analysis Level Be	low )		
	Is Attachment Approv				;
Pre Inspec	tion Levels	Yes No	Post Insp	ection Levels	Yes No
	r <u>1a</u>			or 4a	
<u>0</u> 2 q				or 5a	
3 or				or 6a	
( If Attachment nee	eds work to be approved, Po				)
Can Serviceman Modify Service	2	Yes No	<u>Pole Attril</u> Pole Height	<u>outes</u>	35'
Need to go to Estimator	<b>.</b>	⊨림⊨림	Pole Class		
Is Make Ready Work Required B	ly Licensee?	一十一	Pole Circumfere	nce	
Is Make Ready Work Required B		一片岩			
Is There a 12" Separation Violation		持付持			
Is There a Climbing Space Violat		HH			
Is There a Mid Span Violation?		H			
Does Pole have an NESC Infract	ion?	H			
Need to Route to Another Utility I				•	
	MENT HEIGHTS				
				L	
Licensee Proposed Attachment F		Grounded	Mid Span Clr.	To Pole No#.	Violation
Lowest Secondary or Neutral	2316"		19'4"	306602	
Streetlight Mast					
Streetlight Drip Loop					
CATV					
TELCO			· -		
FIBER					
OTHER #1		<u> </u>			<u> </u>
OTHER #2					
Service Drops				and Anchors	
Drop	Ht. Ht. Over Rd.	Violation	Leads	Guy Size	JA
Secondary		Primary			
CATV		Lowest Se	econdary		
TELCO		TELCO			누극
FIBER		FIBER			<u> </u>
Other #1		Other			Yes No
Other #2			and Mark Double of Co.		
			see Need Breaker In Gu		<b>=                                     </b>
		Does Anoun	er Utility Need Breaker I	in Guy?	
NOTES:					
					*

Request Number	2241	28/				Flu Rev. 05/07/03	
Page 17 of 43							
PPL MAP STRING	1140	5002.0			Pole Inspector	Ker	Bell
PPL POLE NUMBER		660Z			Inspection Date		-2003
POLE ADDRESS	440	Proct	ar In	13000	Requesting Licensee	ATET	OVERLASH
CITY	PLEAS	2				ediation discourant from the same	OV CICHSH
	WTAH	A741 9 700	<u> </u>				•
STATE			ircle Analysi				
	l:	s Attachment Ap	proved as Re	quested by	Level of Analysis?		:
P	re Inspection I	_evels	Yes	No	•	ection Levels or 4a	Yes No
	1 or 1a 2 or 2a	١	-			or 5a	<b>HH</b> .
	3 or 3a	,	<u> </u>			or 6a	
( If Attacl	-	ork to be approve	ـــــــا d. Post Inspec	tions, or has	an NESC Infraction, fi	Il out lower section	
( 11 1122		о,	Yes	No	Pole Attrib		
Can Serviceman Modit	fy Service?				Pole Height		40'
Need to go to Estimate					Pole Class		
Is Make Ready Work F					Pole Circumfere	nce	
Is Make Ready Work R			$\geq$				
Is There a 12" Separat		tween Utilities?	<u> </u>				
Is There a Climbing Sp							
Is There a Mid Span Vi				-			
Does Pole have an NE Need to Route to Anoth		ractions / sac pol	<del>[</del>				
			.cs/				
	ATTACHMENT	HEIGHTS		·			
Licensee Proposed Atta	achment Ht.		Grounde	d	Mid Span Cir.	To Pole No#.	Violation
Lowest Secondary or N	leutral	22'	$\bowtie$		23'	306601	
Streetlight Mast	•				***************************************		
Streetlight Drip Loop							
CATV		<del></del>					
TELCO		79,1,,	M		13'		
FIBER		181111		4.			
OTHER #1 Tel co		18,411					
OTHER#2 on J	•		<u> </u>		Gine	and Anchors	LJ
Service Dr	<u>ops</u> Drop Ht.	Ht. Over Rd.	Violation	•	Leads	Guy Size	JA
Secondary	Driveway	711/01	710141101	Primary		<i>54,540</i>	
CATV		<u> </u>		Lowest Sec	ondary		
TELCO OVER Drive	13'	18'	一	TELCO	-	3/811	一
FIBER Way			m	FIBER			
Other #1 Teleo S.	ervice.	16'8"	$\boxtimes$	Other			
Other #2						`	Yes No
				Ooes License	e Need Breaker In Gu	y? [	
			C	oes Another	Utility Need Breaker I	n Guy?	
NOTES:		. ,	V 7.		>		- 1
18' clea	ranc	e Vio	lati	on	great	Sal /	elco.
15'6"	earanc	e Vio	latio	na	lone Ro		
Teles F	10°C	leara	nce	VVO	lation	1	

Request Number	2241281	Flu Rev. 05/07/03
Page /8 of 43	annuar .	
PPL MAP STRING	11405002.0	Pole Inspector Kon Bell
PPL POLE NUMBER	306601	Inspection Date 7-2-2007
POLE ADDRESS	3425 13	ODW Froct Requesting Licensee AT&T OVERLASH
CITY	PLEASANT GROV	15
_		
STATE _	UTAH (Cir	rcle Analysis Level Below)
		roved as Requested by Level of Analysis?
Pre	e Inspection Levels	Yes No Post Inspection Levels Yes No
	1 or 1a	4 or 4a
	2 or 2a) 3 or 3a	6 or 6a
/ If Attach		Post Inspections, or has an NESC Infraction, fill out lower section )
( II Alladii	ment needs work to be approved,	Yes No Pole Attributes
Can Serviceman Modify	Service?	Pole Height Bell Bole 40
Need to go to Estimator		Pole Class 4
Is Make Ready Work Re	equired By Licensee?	Pole Circumference
Is Make Ready Work Re	equired By Another Utility?	
Is There a 12" Separation	on Violation Between Utilities?	
Is There a Climbing Spa	ce Violation?	
Is There a Mid Span Vio		
Does Pole have an NES		
Need to Route to Anothe	er Utility for corrections (see notes	5)
<u> </u>	TTACHMENT HEIGHTS	
Licensee Proposed Attac		Grounded Mid Span Clr. To Pole No#. Violation
Lowest Secondary or Ne	eutral 22'5"	Neutral 22'1" 306502
Streetlight Mast		
Streetlight Drip Loop		
CATV		
K TELCO	17'6"	13 3 3 11
FIBER		Telcoser 141911
KOTHER#1 Telco S		
OTHER#2 ON J.	****	Telco 141
Service Dro		Service Guys and Anchors
	Drop Ht. Ht. Over Rd.	Violation Leads Guy Size JA
Secondary		Primary
TELCO SETVILE	7615	TELCO
FIBER	163	FIBER
OOther#1 Servic	161911	Other
Other #2		Yes No
Outer #2		Does Licensee Need Breaker In Guy?
		Does Another Utility Need Breaker In Guy?
NOTES:		
Tales 4	o" clearar	ice Vialation
7-1-1	1	
1elca 13	5'6" Cleara	nce Violation along a ka wa

Request Number	2241281		Flu R	ev. 05/07/03
Page 19 of 43				
PPL MAP STRING	11405002.0		Pole Inspector	Ken Bell
PPL POLE NUMBER	306502		Inspection Date	7-2-2007
POLE ADDRESS	3525 /30	OW	Requesting Licensee A-	TET OVERLASH
CITY	PLEASANT GRO			13.10911
STATE	UTAH			
	(c	ircle Analysis Level B		
		proved as Requested		lauria V ar
Pre	Inspection Levels 1 or 1a	Yes No	Post Inspection 4 or 4a	Levels Yes No
	2 or 2a	一员	5 or 5a	
	3 or 3a	一直首	6 or 6a	
( If Attachm	ent needs work to be approved	, Post Inspections, or h	as an NESC Infraction, fill out lo	wer section )
O O in in a man Madifu (	C-min-2	Yes No	<u>Pole Attributes</u> Pole Height	401
Can Serviceman Modify S Need to go to Estimator	Service?		Pole Class	
Is Make Ready Work Red	guired By Licensee?	一一一	Pole Circumference	The state of the s
Is Make Ready Work Red				
	Violation Between Utilities?			
Is There a Climbing Space	e Violation?			
Is There a Mid Span Viola				
Does Pole have an NESC			•	
	Utility for corrections ( see note			
	TACHMENT HEIGHTS			
Licensee Proposed Attact	nment Ht.	Grounded	Mid Span Cir. To Pol	
Lowest Secondary or Neu	tral 2714"	$\bowtie$	24'6" 300	6501
Streetlight Mast			<u> </u>	
Streetlight Drip Loop		[ <del></del>		<u> </u>
CATV	19:1011		13'101(1)	
TELCO FIBER	11 10		13 10.	
OTHER#1 Telco sev	rvice 2/1/11			
OTHER #2 ON J-				
Service Drop			Guys and An	
. 1	Drop Ht. Ht. Over Rd.	Violation	Leads Gu	y Size JA
Secondary Neutra	11. 24.9"	Primary	Secondary	
CATV TELCO	17'4"	TELCO	econdary	<u> </u>
VFIBER		FIBER		
Other#1 Splice	5-111	Other	dis-	
Other #2 Bax				Yes No
·			see Need Breaker In Guy?	
		Does Anot	her Utility Need Breaker In Guy?	
NOTES:	1		0 1	
Teleo Qu	Nest Heig	ht along	Rd At 13'1	o" should be
15'6"	<i>J</i>			

	Request Number	2241	281				Flu Rev. 05/07/03		
	Page 20 of 43							;	
	PPL MAP STRING	1140	5002.	5	P	ole Inspector	GRAHAM	1 Couns	
	PPL POLE NUMBER		500	· '	Ins	spection Date	7-2-03	+ 900/11/15	
	POLE ADDRESS	680	5 PROCT	na Lu	Reques	ting Licensee		OVERLASH	
						. 3		OVCKCH3H	
	CITY _	PLEAS	ANT GR	0V E				4	
	STATE	UTAH		Circle Analysis Le	evel Relow )				
		Į:		pproved as Reque		Analysis?		:	
	Pre	Inspection I		Yes	No	Post Insp	ection Levels	Yes No	
		1 or 1a		<u> </u> _	4 or 4a				
		(2)or 2a			==		or 5a		
		3 or 3a		L			or 6a	<u></u>	
	( If Attachn	nent needs w	ork to be approve		s, or nas an NES <b>No</b>	Pole Attrib	l out lower section outes	,	
	Can Serviceman Modify	Service?				ke Height		40 - BEL	
	Need to go to Estimator				Po	le Class		4	
	Is Make Ready Work Re	quired By Lic	ensee?		Po	le Circumferer	nce		
	Is Make Ready Work Re								
	Is There a 12" Separation	n Violation Be	etween Utilities?						
	Is There a Climbing Space	ce Violation?							
	Is There a Mid Span Viol			느닐느					
	Does Pole have an NESC								
	Need to Route to Anothe	r Utility for co	rrections (see no	otes)					
	<u>A</u>	TTACHMENT	HEIGHTS				***************************************		
	Licensee Proposed Attac	hment HL		Grounded	Mi	d Span Clr.	To Pole No#.	Violation	
	Lowest Secondary of Nei	utrai	28'1"		2	25'9"	306504		
	Streetlight Mast								
	Streetlight Drip Loop						15'6 over	3 <u></u>	
	CATV		101 37			11			
	TELCO		184			3'8" F	7007		
	FIBER								
	OTHER #1			<del>     </del>					
	OTHER #2 Service Drop	ne		L		Guvs a	and Anchors	L	
	Service Dio	<u>PS</u> Drop Ht.	Ht. Over Rd.	Violation		Leads	Guy Size	JA	
	Secondary	Diopila	71 0 7 7 7 7 7		imary		•		
	CATV				west Secondary				
	TELCO	*		TE	LCO				
	FIBER			Ell Fil	BER				
	Other #1			Ot	her				
	Other #2						,	Yes No	
					s Licensee Need		· • • • • • • • • • • • • • • • • • • •		
				Doe	s Another Utility N	leed Breaker i	n Guy?		
	NOTES:								
_									
				•					
•									
•									
_									
_									
•									

POLE ATTACHMENT INSPECTION APPLICATION 2241281 Flu Rev. 05/07/03 Request Number Page 21 of 43 Pole Inspector PPL MAP STRING Inspection Date PPL POLE NUMBER Requesting Licensee POLE ADDRESS CITY STATE (Circle Analysis Level Below) Is Attachment Approved as Requested by Level of Analysis? **Post Inspection Levels Pre Inspection Levels** Yes No 4 or 4a 1 or 1a 5 or 5a 2 of 2a) 6 or 6a 3 or 3a ( If Attachment needs work to be approved, Post Inspections, or has an NESC Infraction, fill out lower section ) Pole Attributes Yes No Pole Height Can Serviceman Modify Service? Pole Class Need to go to Estimator Is Make Ready Work Required By Licensee? Pole Circumference Is Make Ready Work Required By Another Utility? Is There a 12" Separation Violation Between Utilities? Is There a Climbing Space Violation? Is There a Mid Span Violation?

Does Pole have an NESC Infraction?								
Need to Route to Another Utility for corrections ( see notes )								
ATTACHMENT HEIGHTS								
Licensee Proposed Attachment Ht.		Grounded	Mid Span Clr.	To Pole No#.	Violation			
Lowest Secondary or Neutral	27.5		-					
Streetlight Mast								
Streetlight Drip Loop								
CATV								
TELCO	20'		<del></del>					
FIBER								
OTHER #1								
OTHER #2			<del></del>					
Service Drops				and Anchors				
Drop Ht.	Ht. Over Rd.	Violation	Leads	Guy Size	JA			
Secondary		Primary	-					
CATV		Lowest Secon	ndary					
TELCO		TELCO						
FIBER		FIBER						
Other #1		Other						
Other #2					Yes No			
Does Licensee Need Breaker In Guy?								
		Does Another U	Itility Need Breaker	In Guy?				
NOTES:								
NEEDS FACE PT +	ASSIG	NED TO LT.						

Request Number 2241	28/			Flu Rev. 05/07/03	
Page 22 of 43				0	,
	5002.0		Pole Inspector	GRAHAM	Loumis
	504	4	Inspection Date	7-2-0.	3'
POLE ADDRESS 698	- PROLTUR (		Requesting Licensee	ATAT	OVERLASH
CITY PLEAS	.7				
	ANT OROYE	·· <del>·····</del>			a .
STATE UTAH		 Analysis Level E			
	s Attachment Approve				;
Pre Inspection I	_evels	Yes No	-	ection Levels or 4a	Yes No
1 or 1a			•	or 5a	
2 o(2a) 3 or 3a				or 6a	
	ndk to be approved. Pos	t Inspections, or l	nas an NESC Infraction, fi		
(	,	Yes No	Pole Attril		,
Can Serviceman Modify Service?			Pole Height		<u>40</u>
Need to go to Estimator			Pole Class		A
Is Make Ready Work Required By Lice	ensee?		Pole Circumfere	nce	
Is Make Ready Work Required By And					
Is There a 12" Separation Violation Be	tween Utilities?				
Is There a Climbing Space Violation?					
Is There a Mid Span Violation?					
Does Pole have an NESC Infraction?					
Need to Route to Another Utility for con	rections ( see notes )				
ATTACHMENT	HEIGHTS				
Licensee Proposed Attachment Ht.		Prounded	Mid Span Cir.	To Pole No#.	Violation
Lowest Secondary or Neutral	29'	X Spa	man 28.6"	306400	
Streetlight Mast			0 0		·
Streetlight Drip Loop					
CATV					
TELCO			-		
FIBER	-				
OTHER #1			***************************************		
OTHER #2			***************************************		
Service Drops				and Anchors	
Drop Ht.	Ht. Over Rd. V	/iolation	Leads	Guy Size	JA
Secondary		Primary	<del></del>		
CATV			Secondary		
TELCO		TELCO FIBER	***************************************		
FIBER		Other	*		片
Other #1	**************************************				Yes No
Other #2		L_J Dana lian	nsee Need Breaker In Gu		
			ther Utility Need Breaker I	·	<b>=                                    </b>
NOTES:		00007410	arci cany nood broaker i	ouy:	
NOTES:					