



---

**Questar Gas Company**  
Integrity Management– DNR530  
PO Box 45360  
Salt Lake City, UT 84145-0360  
Tel. (801) 324 - 3304  
Richard.Kiser@Questar.com

**Richard J. Kiser II**  
Sr. Engineer, Integrity Management Support

September 22, 2015

Mr. Al Zadeh  
Manager Pipeline Safety Section  
Utah Division of Public Utilities  
Heber Wells Building 4<sup>th</sup> Floor  
160 E 300 S  
Salt Lake City, UT 84111

RE: Supplemental 2014 Distribution Annual Report

Dear: Mr. Zadeh,

Please see the attached Supplemental 2014 Distribution Annual Report for Questar Gas Company.

It was discovered that the number of reported Excess Flow Valves (EFV) installations reported in the 2014 Annual Report was under reported by 454 or 3.8%. The cause was determined to be due to paper work and plating processing delays. A process change has been made to remediate the cause.

Respectfully,

Richard J. Kiser II

Attachments:

Supplemental 2014 Distribution Annual Report Utah

Info Copy:

Vaughn Shosted, Vice President Operations  
Jeff Hansen, Manager Operations Support  
Barrie McKay, Vice President, State Regulatory Affairs  
Mark Warner, Chief DOT Compliance Officer, Questar Corporation  
Justin I. Withers, Supervisor, System Integrity Operations Compliance  
Jimmy Betham, Pipeline Safety Engineer, Division of Public Utilities  
Chien Hwang, Pipeline Safety Engineer, Division of Public Utilities  
Connie Hendricks, Office Specialist, State of Utah, Department of Commerce