

Renaissance Services

6170 South 380 West  
 #200  
 Murray, UT 84107  
 8012441363

# Invoice

Date	Invoice #
7/22/2021	2021-267

<b>Bill To</b>
Landmark Installations 4516 South 700 East Murray Utah 84107

P.O. No.	Terms	Project
	Due on receipt	

Quantity	Description	Rate	Amount
	Job Site: 4200 South Redwood Road 6/15/2021 emergency call out for patch on Redwood Road 40x50 asphalt patch, 7 in asphalt, UDOT Superpave 15x15 hole, 7 feet deep, fill with sand and 36" road base \$25,000 check Paid 7/16/2021 Thermal Striping	42,600.00	42,600.00
		2,600.00	-25,000.00 2,600.00

<p><b>Thank you for your business.</b></p> <p>Terms: As above, 1 1/2% per month (18% per year) interest will be added to past due charges. Purchaser agrees to pay all costs including attorney fees. If account is referred to collections Purchaser has 10 days to dispute charges upon receipt of invoice. No credits will be issued after 10 days.</p>	<p><b>Total</b></p> <p>\$20,200.00</p>
--	--