

Photo 19
1/25/07

3133 S. Connor St.
Bob Behrens
1 Failed insulator pin




Photo 20 3141 S. Connors
Grandma Behrens -
2 Failed insulator pins




Photo 21 End of Aveline Ave
that runs off Connor st.
(West 3127 Aveline)
1 Failed insulator pins




Photo 22 2036 E.
Lambourn
1 Failed insulator
pin





Photo 23
1 failing insulator
2018 E. Lambourn Ave



Photo 24
2 squatter on top
of cross arm. - off
Lambourn Ave



Squatter
on this
end as
well